GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI – 110001

No.F6/DFS/MS/GH/NDZ/2021/ 3 /9

Dated: /....../2021

FIRE SAFETY CERTIFICATE

Certified that the Laxmi Naryan Place Guest House located at 4390-18, Rahaman Mohalla, Katra Raiji, Basant Road, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (Reception + 02 guest rooms), 1st floor to 3rd floor (03 guest rooms at each floor), terrace floor (02 temporary staff room), total 11 guest rooms owned/occupied by Laxmi Naryan Place Guest House was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/2018/NDZ/1886 dated 10/08/18. Now, premise was re-inspected by the officer concerned of this department on 10/08/21 in the presence of Sh. Madhusudan and found that the said guest house building having submitted an affidavit dated 10.12.2019 regarding not to use any floor above third floor has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (Reception + 02 guest rooms), 1st floor to 3rd floor (03 guest rooms at each floor) total - 11 guest rooms only with effect from 19/18/2-1-----for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued -1-9/8-1-2-1--- at New Delhi by.

(**Dr. S.K.Tomar**) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, New Delhi. : to ensure that not in use any floor above third floor.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. 2021063014438 dated 30/06/2021
- 3. The Manager, Laxmi Naryan Place Guest House at 4390-17, Rahaman Mohalla, Katra Raiji, Basant Road, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- 1. This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 29.06.2021 latest by 30.09.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT

Laxmi Naryan Place Guest House at 4390-1. Name & address of the building 18, Rahaman Mohalla, Katra Raiji, Basant

Road, Pahar Ganj, New Delhi

Residential, Sub Division-A-1 2. Type of occupancy:-

Gr. + 04 Upper floors (total 11 Guest rooms) Ground floor (Reception + 02 guest rooms), 1st floor to 3rd floor (03 guest rooms at each floor), terrace floor (02 temporary staff room) not in use as affidavit dated 10.12.19 submitted by applicant

3. Type of case:-Renewal

No. F6/DFS/MS/GH/2018/NDZ/1886 dated 4. Details of previous FSC:-

10/08/18. N/A

5. Fire safety directives No.-

6. Date of inspection:-

7. Name of the inspecting officer:-

8. Name & designation of officer From the building side:-

9. Year of construction:-

10. Applicant's letter No:-

10/08/21

Sh. Ravinder Singh (ADO/CC)

Sh. Madhusudan

2021063014438 dated 30/06/2021.

				Old Case	
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR	
1.	Access to Building			*	
	1) Road width	N/A	04 feet	N/A	
	2) Gate width	N/A	N/A	N/A	
	3)Width of internal road	N/A	N/A	N/A	
2.	Number, Width Type & Arr	angement of Ex	xits		
	A. Number of staircases				
	1. Upper floors	01 Nos.	01 Nos.	MR	
	2. Basements	N/A	N/A	N/A	
	B. Width of staircase				
	1. Upper floors	0.80 mtr.	0.81 to 0.90	MR	
			mtr.		
	2. Basements	N/A	N/A	N/A	
	C. Protection of exits				
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous staircase to terrace	01	01	MR	
	E. Width of corridor	N/A	N/A	N/A	
	F. Door size	01 mtr.	01 mtr.	MR	
3.	Compartmentation				
	1) Fire check door	N/A	N/A	N/A	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	N/A	N/A	N/A	
4.	Smoke Management System				
	1) Basements	30 ACPH	N/A	N/A	
	2) Upper floors	Required as per G.N dated 27.05.19	Not provided	Last dt. 30.09.21 of compliance	
		21.03.17		extended vide order dt. 29.06.2021	
				29.00.2021	



N/23

5.	Eino Evil			to .		
3.	Fire Extinguishers			5		
	1) Total numbers	10 Nos.	10 Nos.	MR		
	2) Types	ABC & CO2		MR		
6	3) ISI marking	Required	Provided	MR		
6.	First-Aid Hose Reel					
	1) Total number of eachfloor		01	MR		
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR		
7	3) Nozzle diameter	05 mm	05 mm	MR		
7.	Automatic Fire Detection & Alarming System					
SV.	1) Type of detectors CO type	Required as per G.N dated 27.05.19	Not provided	Last dt. 30.09.21 of compliance extended vide order dt. 29.06.2021		
	2) Location of main panel	N/A	N/A	N/A		
	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of power	N/A	N/A	N/A		
	5) Hooter's Location	N/A	N/A	N/A		
8.	MOEFA	N/A	N/A	N/A		
9.	Public Address System	N/A	Provided	N/A		
10.	Automatic Sprinkler System		110 VIGOU	IVA		
	1) Basement	N/A	N/A	N/A		
	2) Upper floors	N/A	N/A	N/A		
	3) Sprinkler above false	N/A	N/A	N/A N/A		
	ceiling		14/74	IN/A		
11.	Internal Hydrants					
	1) Size of riser/down-comer	N/A	N/A	N/A		
	2) Number of hydrants per	N/A	N/A			
	floor	1 1/1 1	IVA	N/A		
	3) Hose box	N/A	N/A	77/4		
12.	Yard Hydrants	14/11	IVA	N/A		
	1) Total number of hydrants	N/A	N/A	-> T/A		
	2) Hose box	N/A	N/A	N/A		
3.	Pumping Arrangement	IVA	IN/A	N/A		
	1) Ground level	N/A	37/4			
	a) Discharge of main		N/A	N/A		
	pump	N/A	N/A	N/A		
	b) Head of main pump	77/4				
	c) Number of main pump	N/A	N/A	N/A		
	d) Jockey pump out put	N/A	N/A	N/A		
	J T T P Stite Pate	N/A	N/A	N/A		
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump output	N/A	N/A	N/A		
	g) Stand by pump head	N/A	N/A	N/A		
	h) Auto starting/Manual	N/A	N/A	N/A		
	stopping		P	2 0		
	2) Terrace level			2, 1		
	a) Discharge of pump	180 LPM	180 LPM	MR		
	b) Head of pump	30 mtr.	30 mtr.	MR		
	a) D1	D . 1	D 11 1			
	c) Power supply d) Auto starting of pump	Required	Provided	MR		



14.	Continue Wester St.			
14.	Captive Water Storage for 1	Fire Fighting		
	Under ground tank capacity	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
,	d) Over head tank capacity	2500 ltr.	2500 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syste Risk, if any: One ABC type fire	m for Protect	tion of special	MR

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2018/NDZ/1886 dated 10/08/18 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended up to third floor only.

Signature of the Inspecting Officer

Name: - Ravinder Sing

Designation: - ADO (CC)

DO (CC)

As approve for putup for coer feru