GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2021/ 335

Dated: 25./. 8/2021

FIRE SAFETY CERTIFICATE

Certified that the J.B.N International Guest House located at 8145/8, Arakashan Road, Pahar Ganj, New Delhi comprised of Ground + 05 Upper floors, Ground floor (Reception + 01 guest rooms), 1st floor to 4th floor (02 guest rooms at each floor) and 5th floor found sealed), total 09 guest rooms owned/occupied by J.B.N International Guest House was earlier granted FSC by this department vide letter No. F6/DFS/MS/GH/NDZ/2018/1799 dated 01/08/2018. Now, The premise was re-inspected by the officer concerned of this department on 18/08/21 in the presence of (Manager) and found that the said guest house building having given affidavit dated 26.09.2019 regarding not to use any floor above third floor, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (Reception + 01 guest rooms), 1st floor to 3rd floor (02 guest rooms at each floor) total 07 guest rooms up to third floor only with effect rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued -25/21-at New Delhi by.

0x10mm

(Dr. S.K. Tomar) Dy. Chief Fire Officer Tel: 011-23412025

Copy to:-

- The Commissioner, North MCD, Civic Centre, New Delhi: to ensure not to use any floor above third floor.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. e mail.id <hotelamax@gmail.com> dated 07.08.21 &Online id no.2021062514223 dated 03.07.2021
- 3. The Manager,
- J.B.N International Guest House 8145/8, Arakashan Road, Pahar Ganj, New Delhi. Condition for the validity of fire safety certificate

- This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 29.06.2021 latest by 30.09.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction,
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT

1. Name & address of the building J.B.N International Guest House at

8145/8, Arakashan Road, Pahar Ganj,

New Delhi

2. Type of occupancy:- Residential, Sub Division-A-1

Gr. + 05 Upper floors (total 07 Guest rooms) Ground floor (Reception + 01 guest rooms) 1st floor to 3rd floor (02 guest rooms at each

floor) having given

affidavit dated 26.09.2019 regarding not to

use any floor above third floor,

3. Type of case:- Renewal

4. Details of previous FSC:- No. F6/DFS/MS/GH/NDZ/2018/1799

dated 01/08/2018.

(Manager)

5. Fire safety directives No.- N/A

6. Date of inspection:- 18/08/21

7. Name of the inspecting officer:- Sh. Ravinder Sin

8. Name & designation of officer From the building side:-

Sh. Ravinder Singh (ADO/CC)

9. Year of construction:-

10. Applicant's letter No:
e mail.id < hotelamax@gmail.com> dated 07.08.21

&Online id no.2021062514223 dated 03.07.2021

Old Case S.No. Minimum Standards on fire Requirement/ Provided at site Remarks Prevention and fire safety U/R Existing fire MR/NMR 33 safety arrangements 1. Access to Building 1) Road width N/A 2.0 mtr. N/A 2) Gate width N/A N/A N/A 3) Width of internal road N/A N/A N/A 2. Number, Width Type & Arrangement of Exits A. Number of staircases 1. Upper floors 01 Nos. 01 Nos. MR 2. Basements N/A N/A N/A B. Width of staircase 1. Upper floors 0.80 mtr. 1 mtr. MR 2. Basements N/A N/A N/A C. Protection of exits 1. Fire check door N/A N/A N/A 2. Pressurization N/A N/A N/A D. No. of continuous staircase N/A N/A N/A to terrace E. Width of corridor N/A N/A N/A F. Door size 01 mtr. 01 mtr. MR 3. Compartmentation 1) Fire check door N/A N/A N/A 2) Sealing of electrical shafts N/A N/A N/A 3) Fire rating of shaft door N/A N/A N/A 4) Water curtain N/A N/A N/A 5) Fire Dampers N/A N/A N/A 4. Smoke Management System 1) Basements 30 ACPH N/A N/A



M133

	2) Upper floors	Required as per G.N dated 27.05.19	Not provided	Last dt. 30.0.21 of compliance extended vide order dt. 29.06.2021		
5.	Fire Extinguishers					
	1) Total numbers	10 Nos.	10 Nos.	MR		
	2) Types	ABC & CO2	ABC & CO2	MR		
	3) ISI marking	Required	Provided	MR		
6.	First-Aid Hose Reel					
	1) Total number of eachfloor	01	01	MR		
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR		
	3) Nozzle diameter	05 mm	05 mm	MR		
7.	Automatic Fire Detection & A	larming System	i			
	1) Type of detectors CO Type	Required as per G.N dated 27.05.19	Not provided	Last dt. 30.09.21 of compliance extended vide order dt. 29.06.2021		
	2) Location of main panel	N/A	N/A	N/A		
	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of power	N/A	N/A	N/A		
	5) Hooter's Location	N/A	N/A	N/A		
8.	MOEFA	N/A	N/A	N/A		
9.	Public Address System	Required	Provided	MR		
10.	Automatic Sprinkler System	required	Tiovided	17110		
10.	1) Basement	N/A	N/A	N/A		
	2) Upper floors	N/A	N/A	N/A		
	3) Sprinkler above false	N/A	N/A	N/A		
11.	ceiling Internal Hydrants					
11.	1) Size of riser/down-comer	N/A	N/A	N/A		
		N/A N/A				
	2) Number of hydrants per floor	IN/A	N/A	N/A		
	3) Hose box	N/A	N/A	N/A		
12	Yard Hydrants	IN/A	IN/A	IN/A		
12.	1) Total number of hydrants	N/A	N/A	N/A		
	2) Hose box	N/A	N/A	N/A		
13.		IN/A	IN/A	IVA		
13.	Pumping Arrangement	DI/A	DI/A	NI/A		
	1) Ground level	N/A	N/A	N/A N/A		
	a) Discharge of main	N/A	N/A	IN/A		
	pump	DI/A	DI/A	N/A		
	b) Head of main pump	N/A	N/A N/A	N/A N/A		
	c) Number of main pump	N/A N/A	N/A N/A	N/A N/A		
	d) Jockey pump out put	N/A N/A	N/A N/A	N/A N/A		
	e) Jockey pump head		N/A N/A	N/A N/A		
	f) Stand by pump output	N/A		N/A N/A		
	g) Stand by pump head	N/A	N/A			
	h) Auto starting/Manual stopping	N/A	N/A	N/A		
	0) T			1		
	Terrace level Discharge of pump	225 LPM	225 LPM	MR		

M/24

	· ((.					
	b) Head of pump	18 mtr	18 mtr.	MR		
	c) Power supply	Required	Provided	MR		
	d) Auto starting of pump	Required	Provided	MR		
14.	Captive Water Storage for Fire Fighting					
	Under ground tank capacity	N/A	N/A	N/A		
	a) Draw-off connection	N/A	N/A	N/A		
	b) Fire service inlet	N/A	N/A	N/A		
	c) Access to tank	N/A	N/A	N/A		
	d) Over head tank capacity	2500 ltr.	2500 ltr.	MR		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.					
	a) Pressurization of lift shaft	N/A	N/A	N/A		
	b) Pressurization of lift lobby	N/A	N/A	N/A		
	c) Communication in lift car		N/A	N/A		
	d) Fireman's switch	N/A	N/A	N/A		
	e) Lift signage	N/A	N/A	N/A		
17.	Stand by Power Supply	Required	Provided	MR		
18.	Refuge Area	N/A	N/A	N/A		
	Total area location	N/A	N/A	N/A		
19.	Fire Control Room	N/A	N/A	N/A		
	a) Detector system panel	N/A	N/A	N/A		
	b) Flow switch panel	N/A	N/A	N/A		
	c) PA system panel	N/A	N/A	N/A		
	d) Battery backup	N/A	N/A	N/A		
	e) Building floor plan	N/A	N/A	N/A		
20.	Special Fire Protection System for Protection of special Risk, if any:					

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2018/1799 dated 01/08/2018. renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Name: Ravinder Singh

Designation: ADO (CC)

Doce

more for patup for