GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/GH/NDZ/2021/ 3 3 4

Dated: 25/8 /2021

FIRE SAFETY CERTIFICATE

Certified that the M/s Al - Sana Guest House situated 8-12 to 15 SF, TF Bazar Matiya Mahal, Jama Masjid, Delhi-06, comprised of Ground + 03 upper floors: Ground floor commercial use, 1st floor - reception, 2nd floor - 07 guest rooms + 01 store room, 3rd floor - 07 guest rooms + 01 staff room, total 14 guest rooms was granted FSC by this department vide letter no. F6/DFS/MS/GH/NDZ/2018/1489 dated 25.06.2018. The building/premises was reinspected by officers concerned of this department on 12.08.2021 in presence of Mr. Naseem Akhtar (Manager) and found that building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. The owner has submitted an affidavit on 23.10.2019 not use any floor above third floor for any purpose except mumty of staircase/lift room, water tank in accordance with Gazette Notification dated 27.05.2019 and its subsequent clarification dated 25.09.2019. Accordingly, the premises is fit for occupancy of "Group A-1 (Residential)" for total 14 guest rooms, (2nd floor - 07 guest rooms, 3rd floor – 07 guest rooms) upto 3rd floor only, with effect from .25.1.8.1.1........ for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on ________at New Delhi by

(Dr. S.K. Tomar)

Dy. Chief Fire Officer

Copy to:-

Tel: 011-23412025

- The Commissioner, North Delhi Municipal Corporation, Shama Prasad Mukherjee Civic 1. Centre, New Delhi: to ensure the occupancy in the building and deviation if any
- The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defense Colony, 2. New Delhi 2021071415209 dated 14.07.2021
- The Licensee, M/s Al Sana Guest House situated 8-12 to 15 SF, TF Bazar Matiya 3. Mahal, Jama Masjid, Delhi-06

Condition for the validity of fire safety certificate

- 1. This clearance/FSC shall stand cancelled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 and any violation of clarification issued on 25.09.2019 & 17.12.2020 latest by 30.09.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry". Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained there to before occupancy of the same.

9/3			Dazai Manya Mana	i, Jama Masjid, L	Pelhi-U6	
	2.	Type of occupancy with details of	Residential Group A	-1 (Ground + 03		
		floors:	Ground floor- comm	nercial use	11	
	10.00	A PERSONAL PROPERTY OF THE PRO	1st floor - reception,			
			2 nd floor- 07 guest ro	oms + 01 store roo	om,	
			3 rd floor- 07 guest roo	oms + 01 staff ro	om	
7.00	3.	Type of case:	Renewal case			
	4.	Details of previous FSC:	F6/DFS/MS/GH/ND2	Z/2018/1489 dated	25.06.2018	
	5.	Fire safety directives no.:	NA			
	6.	Date of inspection:	12.08.2021			
	7.	Name of the inspecting officer:	DO Rajinder Atwal,			
1000	8.	Name and designation of the officer	J			
		from the building side:	Mr. Naseem Akhtar ((Manager)		
	9.	Year of construction:	1947	8)		
1	10.	Reference letter no.:	Online application I.l	D. 2021071415209) dated	
1			14.07.2021		dutod	
0	70.0	r				
S		linimum standard of Fire	Requirements	Provide at site	Remarks	
N	P	revention and Fire Safety II/R 33	(Evicting Fine &	(DCC)	BATTO ATTENTO	

	10.	Reference letter no.:	Online application 14.07.2021	I.D. 202107141520	9 dated			
S, N		Iinimum standard of Fire revention and Fire Safety U/R 33	Requirements (Existing Fire & Safety Measures)	Provide at site (PSS)	Remarks MR/NMR			
1	A	ccess to Building			1			
	A		NA	12 m (approx)	MR			
	В		NA	NA	NA			
	C	Width of internal roads	NA	NA	NA			
2	N	umber, Width, Type & Arrangem	ent of Exits					
	A No. of Staircase:							
		a) Upper Floor	01 no.	01 no	MR			
		b) Basements	NA	NA	NA			
-	B	Width of the Staircase:						
		a) Upper floors	01 m	1.2 m	MR			
	-	b) Basements	NA	NA	NA			
	C	Protection of Exits						
11		a) Fire Check Door	NA	NA	NA			
		b) Pressurization	NA	NA	NA			
4-	D	No. Of continuous staircase to	01 No	01 No	MR			
		terrace:						
	F	Width of the corridor	NA	NA	NA			
	E	Door size	1 m	1.06 m	MR			
3	Co	ompartmentation:						
	A	Fire Check doors	NA	NA	NA			
	В	Sealing of Electrical Shafts	NA	NA	NA			
	C	Fire rating of shaft Doors	NA	NA	NA			
	D	Water curtain	NA	NA	NA			
	E	Fire dampers	NA	NA	NA			
	Sr	noke management System:						
4	1.							
	A	Upper floors	Required as per G.N dated 27.05.19	Not provided	Last dt. 30.09.21 of			
T					compliance			
					extended vide			
	1				order dt.			
	В	Basements	NA	NIA	29.06.2021			
5			INA	NA	NA			
3		re extinguishers						
	A	Total numbers	06 no.	06 no.	MR			
19	В	Types	CO2, ABC	CO2, ABC	MR			

6	A	rst Aid Hose reel Total no. at each floor	01 No (2 nd &	O1 No Cand o	MD		
	A	Total no. at each floor	3 rd floor)	01 No (2 nd & 3 rd floor)	MR		
	В	Length of Hose Reel	30 mtrs	30 mtrs	MD		
	C	Nozzle diameter	5 mm		MR		
7		tomatic Fire Detection and Alarm S		5 mm	MR		
/	Au	Type of Detectors -(CO) detector		Nist sussided	T4 14		
	A	Type of Detectors -(CO) detector	Required as per G.N dated	Not provided	Last dt. 30.09.21 of		
			27.05.19		compliance		
			27.03.17		extended		
	Tas:				vide order dt		
					29.06.2021		
	В	Location of main Panel	NA	NA	NA		
	C	Location of Repeater Panel	NA	NA	NA		
	D	Alternate power Source	NA	NA	NA		
	E	Hooter's location	NA	NA	NA		
8		DEFA	NA	NA	NA		
9		blic Address System	Required	Provided	MR		
10		tomatic Sprinkler System	-toquilou	21011404	11111		
	A	Basement	NA	NA	NA		
7.4		Upper Floor	NA	NA	NA		
	C	Sprinklers above false ceiling	NA	NA	NA		
11		ernal hydrants	1471	11/11	1421		
11	A	Size of the riser/down comer	NA	NA	NA		
		No. Of hydrants per floor	NA	NA	NA		
	C	Hose box	NA	NA	NA		
12		rd Hydrants	1471	147 k	1421		
12	A	Total no. of hydrants	NA	NA	NA		
	В	Hose box	NA	NA	NA		
13		mping arrangements	1471	1471	11121		
13	A	Ground Level					
2.0	A	a) Discharge of main pump	NA	NA	NA		
	×	b) Head of main pump	NA	NA	NA		
		c) Number of main pump	NA	NA	NA		
		d) Discharge of jockey pump	NA	NA	NA NA		
		d) Discharge of Jockey pump	INA	INA	INA		
		e) Head of jockey pump	NA	NA	NA		
		f) Discharge of Standby pump	NA	NA	NA		
		1) Discharge of Standoy pump	1471	142 %			
		g) Head of Standby pump	NA	NA	NA		
		h) Auto starting/ manual	NA	NA	NA		
		stopping					
	В	Terrace Level					
NI-		a) Discharge of terrace pump	225 LPM	225 LPM	MR		
	-	b) Head of terrace pump	25 mtrs	25 mtrs	MR		
	F. 7	c) Alternate power supply	Required	Required	MR		
		d) Auto starting of pump	Required	Required	MR		
14	Car	ptive Water Storage for Fire Fightin	-				
14		Underground tank capacity	NA	NA	NA		
	A	Draw off connection	NA	NA	NA		
	B	Fire Service Inlet	NA	NA	NA		
	C		NA	NA	NA		
	E	Access to tank	25,00 ltrs	25,00 ltrs	MR		
	D	Overhead tank capacity	Required	Provided	MR		
15	777	it Signage	Doggramad	Provided	IVIR		

16	Pro	ovision of lift			•
	A	Pressurization of lift shaft	NA	NA	NA
	В	Pressurization of lift lobby	NA	NA	NA
	С	Communication in lift car	NA	NA	NA
	D	Fireman switch	NA	NA	NA
	E	Lift signage	NA	NA	NA
17		andby Power Supply	Required	Provided	MR
18					
	A	location	NA	NA	NA
	В	Total area	NA	NA	NA
19					
	A	Fire Detection System panel	NA	NA	NA
	В	Flow switch panel	NA	NA	NA
	C	P A system panel	NA	NA	NA
No.	D	Battery backup	NA	NA	NA
	E	Building floor plan	NA	NA	NA
20					NA

The fire protection systems provided in the building were tested, checked at random and

found functional at the time of inspections.

In view of the deemed compliance of minimum standards of fire prevention and fire safety Rules, the FSC issued vide letter No. required under the F6/DFS/MS/GH/NDZ/2018/1489 dated 25.06.2018 is recommended to be renewed under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name Rajinder Atwal Designation DO (CD)

Dy.CFO (NDZ)

M.S.(C)