

576

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F6/DFS/MS/School/SZ/2021/ 630

Dated: 24/8/21

FIRE SAFETY CERTIFICATE

Certified that **Sri Guru Tegh Bahadur Khalsa Boys/Girls Sr. Secondary School** located at **Dev Nagar, Karol Bagh, New Delhi- 110005** is comprised of ground plus two upper floors, using ground and first floor as boys school and second floor as girls school was inspected by the officer concerned of this department on 05.08.2021 in presence of Smt. Parvider Kaur, Principal of the girls school and found that the said School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Directorate of Education circular No. F.6/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011 and that the school building is fit for occupancy class "Educational" with effect from the date of issue of this certificate for a period of three years, subject to compliance of the under mentioned conditions.

Issued on ~~24/8/21~~ at New Delhi by.


(Anil Garg)
Director

Delhi Fire Service

Copy to: -

1. The Principal, Sri Guru Tegh Bahadur Khalsa Boys/Girls Sr Secondary School, Ramjas Lane-1, Karol Bagh, New Delhi- 110005.
2. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi- 110054

Conditions for the Validity of Fire Safety Certificate

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
3. The trained firefighting staffs should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
6. Basement used only for storage purpose as per BBL.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.
9. All the means of escapes /exits shall not be locked/blocked at any time for safe evacuation of the occupants in case of emergency.

INSPECTION REPORT

1. Name & address of the building : Sri Guru Tegh Bahadur Khalsa Boys/Girls Sr. Sec. School,
Rajinder Nagar, New Delhi- 110060
2. Type of Occupancy : Educational
3. Type of Case : New Case
4. Details of previous NOC : Nil
5. Fire Safety directives letter No : Directorate of Education circular No. F.16/Estate/CC/Fire
Safety/2011/3298 to 3398 dated 01-03-2011.
6. Date of inspection : 05.08.2021
7. Name of the Inspecting Officers : P.V. Rathee, Asstt. Div. Officer (SRD)
8. Name and designation of officers
from the building side : Smt. Parvinder Kaur, Principal (Girls School)
9. Year of Construction : Before 2007
10. Applicant's letter No. : Online email id sgtbkgd1953@gmail.com dated 19.07.2021

The School building is comprised of ground plus two upper floors, using ground and first floor as boys school and second floor as girls school.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Directorate of Edu. circular dt. 01.03.2011	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	6 mts	Provided	MR
	• Gate width	4.5 mts	Directly accessible	MR
	• Width of internal road	N/A	N/A	N/A
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases	-----	-----	-----
	• Upper Floors	02	02	MR
	• Basements	N/A	N/A	N/A
	b. Width of staircases	-----	-----	-----
	• Upper Floors	1.5 mts or less & 0.75 mt	1.46 & 1.20 mts. (iron made FF to SF)	MR
	• Basements	N/A	N/A	N/A
	c. Protection of exits	-----	-----	-----
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	e. No. of continuous staircases to terrace	01	01	MR
	g. Width of Corridor	Required	2.60 mts	MR
	h. Door Size	Required	Provided (1.06 mts)	MR
3	Compartmentation.			
	• Fire check door	N/A	N/A	N/A
	• Sealing of electrical shafts	N/A	Sealed	----
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4	Smoke Management System.			
	• Basements			

	<ul style="list-style-type: none"> • Communication In lift Car • Fireman's Grounding Switch • Lift Signage 	N/A	N/A	N/A
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	➤ Total Area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector System Panel	N/A	N/A	N/A
	• Flow Switch Panel	N/A	N/A	N/A
	• PA System Panel	N/A	N/A	N/A
	• Batter backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were test checked and found functional at the time of inspection. As school management has applied vide letter no. KGD/07-08/64 dated 21.06.2007 applied for issue a Fire Safety Certificate and submitted recognition letter issued by Directorate of Education, Delhi letter No. F.32(2).(6)/Gen/79/3173 dated 08.11.1979 palace at C-33.

Note: - all the shortcomings pointed out by this department vide letters No. F.6/DFS/MS/School/SZ/2018/2654 dated 21.06.2018 have complied

In view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant fire safety certificate under the Directorate of Education circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011 is recommended.

DFA is put up for approval & signature please.

D-0 (SW)

09/08/2021

By cfo (SZ)

CFO

10/8

17/8

6/8/21

(P.V. Rathee)

Asstt. Div. Officer, (SRD)

