GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/EH/2021/SZ/ 196

Dated: 26/8/2021

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s McDonalds Family Restaurant (A Unit of Connaught Plaza Restaurants Pvt. Ltd.) T 310, Plot No Ambience Mall, Phase II, Nelson Mandela Marg, Vasant Kunj, New Delhi–110070 is located at 3rd floor in a building comprised of Block II- 3 Tires Basement, Ground + 03 Upper floors. The building have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 10/08/2021 in the presence of Mr. Kartvaya Ahuja (Manager) and that the premise is fit for occupancy class Group–D Assembly (Restaurant at 3rd floor only) with effect from the date of issue of this certificate for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010

Issued on 26/8 /2021 at New Delhi by

(ATULGARG) DIRECTOR

Copy to: -

1. The Joint Comm. of Police (Lic.), First floor, P.S. Defence Colony, New Delhi-110049

2. The Dy. Health Officer, SDMC, South Zone, Green Park, Delhi -110016 (Ref. letter no. MHA Portal ID 2021062214111 dated 23/06/2021

3. The Authorized Signature, M/s McDonalds Family Restaurant (Connaught Plaza Restaurants Pvt. Ltd.) T 310, Plot No 2, Ambience Mall, Phase II, Nelson Mandela Marg, Vasant Kunj, New Delhi–110070.

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting system.

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL 2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

		INSPEC	TION REPORT				
1	Nan	ne & Address of the Building		mily Restaurant (Conn	aught Dlags		
			McDonalds Family Restaurant (Connaught Plaza				
			Restaurants Pvt. Ltd.), T 310, Plot No 2, Ambience Mall, Phase II, Nelson Mandela Marg, Vasant Kunj,				
			New Delhi-110	n, Neison Mandela Marg,	Vasant Kunj.		
2	Type	e of Occupancy					
3		ding Comprised of	Group-D Assen	nbly Building. (Restaurant)			
	Dunding Comprised of		Block II- 3 Tiers	s Basement, Ground + 3 Up	per Floors		
4	Type of Case			e Tier Basement Ground &	1 st floor		
			New				
5		ils of Previous NOC	Nil				
6	Fire	Safety Directives Letter No	Ambience Mall- F.6/MS/DFS/BP/2005/1691 dated 12/08/2005 &				
7	Doto	CI	F.6/MS/DFS/BP/2017/1424 dated 31/05/2017				
8		of Inspection	10/08/2021				
		e of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)				
9	Nam	e & Designation of Officers		Mr. Kartvaya Ahuja (Manager)			
		the building side	(
10	Year	of construction	2008				
11	Appl	icant letter No.	Online No. 2021062214111 dated 23/06/2021				
S.		mum standards on Fire Prevention	NDC / DDI				
No.	and l	Fire Safety U/R 33	Requirements	Provided at Site	Remarks		
1	Acces			S/Mall/2020/SZ/56 Dt. 21/01	MR/NMR		
	•	Road width	Restt. within	Provided by Mall			
	•	Gate width	DLF	N/A	MR N/A		
	•	Width of internal road	Promenade Mall	N/A	N/A		
2	Num	ber, width, type & arrangement of exi	ts.] IV/A	N/A		
	a) N	umber of Staircase	Provided & Maintained by Ambience Mall				
	>	Upper floors.	Restt within Mall	As above			
	-	Basement floor.	N/A	N/A	MR		
	b) Width of Staircase		N/A N/A N/A Provided & Maintained by Ambience Mall				
	>	Upper floors	Restt within Mall	As above	MR		
	-	Basement floor	N/A	N/A	N/A		
	c) Protection of exits		Provided of	& Maintained by Ambience	Mall		
	1	Fire check door	Restt within Mall	As above	MR		
	<u>></u>	Pressurization	Restt within Mall	As above	MR		
	d) No	o. of continuous staircase to terrace	Restt within Mall	-NA	MR		
		idth of corridor	N/A	N/A	N/A		
3	-	oor size	02 required	1.50 mtr each	MR		
3		artmentation.	Provided & Maintained by Ambience Mall				
	•	Fire check door.	Restt within Mall	As above	MR		
	•	Sealing of electrical shafts.	Restt within Mall	As above .	MR		
	•	Fire rating of shaft door.	N/A	N/A	N/A		
	•	Water curtain	N/A	N/A	N/A		
4	Smal	Fire dampers.	N/A	N/A	N/A		
-8	Smoke	Management system. Basement	Provided &	& Maintained by Ambience	Mall		
		Upper floors	30 ACPH	N/A	N/A		
5		xtinguishers.	12 ACPH	Exhaust Fans Provided	MR		
	rne E	Total numbers	D				
		Types	Required	08 Nos	MR		
		ISI Marking	ABC/CO ₂	ABC & CO ₂	MR		
6		Aid Hose Reels.	Required	Provided	MR		
	•	Total numbers on each floor.	Provided &	Maintained by Ambience			
		Length of hose-reel hose.	One near Restt	As above	MR		
		Nozzle Diameter	30m	As above	MR		
7		natic fire detection & alarming system	5mm	As above	MR		
	0 1	faintained by Ambience Ma					
		Type of detectors Location of Main Panel	Required	As above	MR		
			Required	As above	MR		
J		LOCATION Of Panastan Dan al	Required	A 1	3.00		
	•	Location of Repeater Panel	Required	As above	MR		

	Alternate source of power	Required	As above	MR		
	Hooter's location	Roquito				
8	MOEFA	Required	Provided	MR		
9	Public Address System	N/A	As above	MR		
10	Automatic Sprinkler System	Provided & Maintained by Ambience Mall				
	Basement	N/A	N/A	N/A		
	 Ground floor. 	Required	As above	MR		
	 Sprinkler above false ceiling 	N/A	N/A	N/A		
11	Internal Hydrants.	Provided & N	Maintained by Ambienc	e Mall		
	Size of Riser/Down-comer	Required	As above	MR		
	 Number of Hydrant per floor 	One near Restt	As above	MR		
	Hose box.	One near Restt	As above	MR		
12	Yard Hydrants.	Provided & N	Maintained by Ambienc	e Mall		
	Total number of hydrants.	N/A	As above	N/A		
and the same of th	 Hose box. 	N/A	As above	N/A		
13	Pumping arrangements.	Provided & N	Maintained by Ambieno	ce Mall		
	Ground Level		Common pumping arrangements for entire bldg			
	Discharge of main pump.	4500 LPM	4500 LPM	MR		
	Head of main pump.	70m	70m	MR		
	Number of main pumps.	02 Nos.	02 Nos.	MR		
	Jockey Pump output.	180 LPM	180 LPM	MR		
	Jockey Pump head.	70m	70m	MR		
	Standby Pump output.	4500 LPM	2 X 4500 LPM	MR		
	Standby Pump head.	70m	70m	MR		
	Auto Starting/Manual Stopping.	Required	Provided	MR		
	Pump house access.	Required	Provided	MR		
	Terrace Level					
	> Discharge of pump.	N/A	N/A	N/A		
	Head of pump.	N/A	N/A	N/A		
	Power supply.	N/A	N/A	N/A		
	Auto starting of pump.	N/A	N/A	N/A		
14	Captive water storage for fire fighting.	Provided & Maintained by Ambience Mall				
1.4	Underground tank capacity.	Required	500,000 Ltrs	MR		
	> Draw-off connection.	Required	Provided	MR		
	Fire Service Inlet.	Required	Provided	MR		
	Access to tank.	Required	Provided	MR		
	Overhead tank capacity.	Required	30,000 Ltrs	MR		
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.		Maintained by Ambien			
10	Pressurization of lift shaft.	N/A	As above	N/A		
	Pressurization of lift lobby.	N/A	As above	N/A		
	Communication in lift car.	N/A	As above	N/A		
	Fireman's switch.	N/A	As above	N/A		
	Lift signage.	N/A	As above	N/A		
17		Required	Provided	MR		
	Standby Power Supply	Roquitou	TOTACA	1414		
18	Refuge Area • Total area	N/A	N/A	N/A		
		N/A	N/A	N/A		
4.0	• Location		Maintained by Ambier			
19	Fire Control Room.		As above	N/A		
	Detector system panel.	N/A	As above As above	N/A		
	• Flow switch panel.	N/A	NAME OF THE PROPERTY OF THE PR	N/A		
	PA system panel.	N/A	As above			
	Battery backup.	N/A	As above	N/A		
	Building floor plan.	N/A	As above	N/A		

20	Special Fire Protection System for the	N/A	As above	N/A
	Protection of special Risk, if any.			

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 44 dated 20/01/2021

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Designation: ADO (BCP)

DO (SD)

21-8721

24/8/y CF.8

240/20M

4119

And fat P As upproved, F.T. Your esquature 8

tettel er joutub for

1/19