(-1-1

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2021/SZ/ 6 58

Dated: 27/8/5/

FIRE SAFETY CERTIFICATE

Certified that the **Sarvodaya Kanya Vidyalaya**, Rajouri Garden (Extn.), New Delhi-110027 comprised of two blocks namely A-Block & B-Block. Each block is having ground plus one upper floor, owned/occupied by Sarvodaya Kanya Vidyalaya was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2018/SZ/1171 dated 22/05/2018. The school building was re-inspected by the officer concerned of this department on 10/08/2021 in the presence of Smt. Sunita (HOS) and found that the School Building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on 27/8/57 at New Delhi.

(SUNIL CHAWDHARY) DY.CHIEF FIRE OFFICER

9015

Copy to:-

- The Principal, Sarvodaya Kanya Vidyalaya, Rajouri Garden (Extn.), New Delhi-110027
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

The state of the s	INSPECTION REPORT					
Renewal Previous NOC Se : Renewal Previous NOC : F.6/DFS/MS/S directives letter No : Circular No. F.16 Prection : 10/08/2021 Specting Officer : A.D.O. R.K. Yar designation of officers milding side : Smt. Sunita (Houstruction : 2013 Letter No. : Nil dated 27/07 Testandards on fire prevention and TU/R 33 building	chool/2018/SZ/11 /Estate/CC/Fire Safe dav OS) //2021 Requirement	Jouri Garden (Extn. 71 dated 22/05/201 ety/2011/3298 to 339	8			
oad width	Accessible 06 m 4.5 m	Provided	MR			
ate width	4.5 m N/A	05 & 4.6 m N/A	M/R			
idth of internal road	IN/A	IN/A	N/A			
Width, Type & Arrangement of Exits						
pper Floors						
asements	06 no.'s in each block	06 no.'s provided in	MR			
aschiellis	N/A	each block N/A	N/A			
	IVIX	IV/A	N/A			
of staircases pper Floor	1.50 & .75 m	1.45 (06 no.'s) in A & 1.45 (04 no.'s), 1.: 1.40 m in B blk				
asements	N/A	N/A	N/A			
on of exits	N/A	N/A	N/A			
re check door	N/A	N/A	N/A			
ressurization		IVA	IN/A			
continuous staircases to	N/A	N/A	N/A			
surreuses to	1.50 m	1.75 m	MR			
of Corridor	1.0 m	1.0-1.05 m	MD			
ize	1.0 m	(Double door) few including door frame	MR			
nentation			10			
e check door	N/A	N/A	N/A			
aling of electrical shafts	N/A	N/A	N/A			
e Rating of shaft door						
nter Curtain	N/A	N/A	N/A			
e Dampers	N/A	N/A	N/A			
	N/A	N/A	N/A			
Smoke Management System						
sements	N/A	N/A	N/A			
per floors	Required	Natural Ventilation provided	MR			
guishers						
al numbers	30 No's	Provided	MR			
pes	ABC/CO ₂ type	Provided	MR			
narking	ISI marked	100 AUGUST D. GOLDON W. C.	MR			
Iose Reels		151 markeu	IVIK			
al numbers on each floor	N/A	N/A	N/A			
ngth of hose reel hose	N/A		N/A			
	N/A		N/A			
nes ma Ho	numbers on each floor th of hose reel hose	ABC/CO $_2$ type arking ISI marked see Reels numbers on each floor N/A th of hose reel hose N/A	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$			

/.	Automatic fire detection and alarming system				
	Type of detectors	N/A	N/A	N/A	
	 Location of Main Panel 	N/A	N/A	N/A	
	 Location of Repeater Panel 	N/A	N/A	The same of the sa	
	 Alternate source of power 	N/A		N/A	
	Hooters' Location	N/A	N/A	N/A	
8.	MOEFA	N/A	N/A	N/A	
		IN/A	N/A	N/A	
9.	Public Address System	N/A	Provided	N/A	
10.	Automatic Sprinkler System				
	• Basement	N/A	N/A	N/A	
	 Ground Floor 	N/A	N/A	N/A	
	 Sprinkler above false ceiling 	N/A	N/A	N/A	
11.	Internal Hydrants				
	Size of riser/down-comer	N/A	N/A	N/A	
	 Number of hydrants per floor 	N/A	N/A	N/A	
	 Hose Box 	N/A	N/A	N/A	
12.	Yard Hydrants				
	Total number of hydrants	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
13.	Pumping Arrangements		11/18	17/12	
	Ground Level				
	Discharge of main Pump	N/A	N/A	N/A	
	Head of Main pump				
	Number of main pumps	N/A	N/A	N/A	
	Jockey Pump out put	N/A	N/A	N/A	
	Jockey pump head	N/A	N/A	N/A	
	Standby Pump out put	N/A	N/A	N/A	
	Standby Pump Head	N/A	N/A	N/A	
	Auto Starting/Manual Stopping	N/A	N/A		
			4 (5)	N/A	
		N/A	N/A	N/A	
	Pump House Access	N/A	N/A	N/A	
	 Terrace level 				
	Discharge of pump	N/A	N/A	N/A	
	Head of the pump	N/A	N/A	N/A	
	Power Supply	N/A	N/A	N/A	
	Auto Starting of pump	N/A	N/A	N/A	
4.	Captive Water Storage for fire fighting				
	Underground tank capacity	N/A	N/A	N/A	
	Draw-off connection	N/A	N/A	N/A	
	Fire service inlet				
	> Access to tank	N/A	N/A	N/A	
	 Overhead Tank capacity 	N/A	N/A	N/A	
	, , ,	N/A	N/A	N/A	
5.	Exit Signage.	N/A	N/A	N/A	
6.	Provision of Lifts.	(No Lift)			
	 Pressurization of Lift Shaft 	N/A	N/A	N/A	
	 Pressurization of Lift lobby 	N/A	N/A	N/A	
	 Communication In lift Car 	N/A	N/A	N/A	
	 Fireman's Grounding Switch 	N/A	N/A	N/A	
	• Lift Signage				
7.	Standby power supply	N/A N/A	N/A N/A	N/A N/A	
				ANAX	
18.	Refuge Area.				
	> Total Area	N/A	N/A	N/A	

Fire Co	itrol Room				
•	Detector System Panel	N/A	N/A	N/A	
•	Flow Switch Panel	N/A	N/A	N/A	
 PA System Panel Battery backup Building Floor Plans 	N/A	N/A	N/A		
	N/A	N/A	N/A		
	N/A	N/A	N/A		
Special special l	Fire Protection System for Protection of Risks, if any:	N/A	N/A	N/A	
	Special	 Flow Switch Panel PA System Panel Battery backup 	 Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans Special Fire Protection System for Protection of N/A 	Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans Special Fire Protection System for Protection of N/A N/A N/A N/A N/A N/A N/A	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2018/SZ/1171 dated 22/05/2018 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Office

Name: - R.K. Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)