C-3M

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI

No. F6/DFS/MS/EH/WZ2021/ 205

Dated: 31 / 8 /2021

FIRE SAFETY CERTIFICATE

Certified that the M/s Toss Bar & Lounge (A unit of NG Hotel and resorts Pvt. Ltd.) situated at Property No. 13, 3rd Floor, Club Road North West Avenue, Punjabi Bagh, New Delhi-110026 is running at Third Floor in a building comprised of Basement, stilt, Upper Ground + 1st + 2nd + 3rd owned/occupied by M/s. Toss Bar & Lounge have compiled with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 02/08/2021 in the presence of Sh. Sujeet Mishra (Manager) and found that the said building is fit for occupancy class "Assembly" Group D (Third floor only) with effect from for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 31.8. New Delhi by.

Director

Delhi Fire Service

Copy to:

- 1. The Joint Commissioner of Police, Licensing Unit, 1st floor, Police Station, Defence Colony, New Delhi.
- 2. M/s Toss Bar & Lounge (A unit of NG Hotel and resorts Pvt. Ltd.) situated a Property No. 13,3rd Floor, Club Road North West Avenue, Punjabi Bagh, New Delhi-110026.
- 3. Dy. Health Officer, SDMC, West Zone, Vishal Enclave, Rajouri Garden New Delhi-110027.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times,
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used strictly as per building bye laws.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. This NOC is valid for Third floor only.
- 10. One office is sealed on terrace floor if it is used FSC is null & void.

Pvt. Ltd.) Situated at Property No. 13, 3rd Floor, Club Road,
North West Avenue, Punjabi Bagh, New Delhi -110048.

2. Type of Occupancy : Assembly (Restaurant).

3. Type of Case : New

4. Details of previous NOC : Nil

5. Fire Safety directives Letter No.: Nil

6. Date of inspection : 05/08/2021

7. Name of the Inspecting Officer: Sarabjeet Singh, ADO (MN)

8. Name and designation of Officer

from the building side : Sh. Sujeet Mishra (Manager)

9. Year of Construction : 2016(as per MHA portal)

10. Applicant's letter No. :Email dated 08/06/2021

Note:-The restaurant is running at 3rd floor in a building comprised of Basement+

Stilt+ Ground+3 upper floors.

S No	prevention and fire safety	BBL/As per Gazette notification dtd. 24/02/2021	e Provided at site	Remarks MR/NMR			
1.	Access of building						
		2m	Provided	MR			
	Gate width	1.5m	On Main Road	MR			
	Width of internal road	VA	NA	NA			
2.	Number, width, Type & Arrangements of exits						
	a. Number of staircases						
	Upper floors	2	Provided	MR			
	Basements	NA	Provided	NA			
	b. Width of staircases						
	Upper floors	1.5m x 2	Provided	MR			
	•	NA _	NA	NA			
	Basements						
	c. Protection of exits	Required	Provided	MR			
	 Fire check door 	NA	NA	NA			
	 Pressurization 	1	Provided	MR			
	d. No of continuous staircas	e					
	to terrace	NR	NR	NR			
	e. Width Of Corridor	1.5m x 2	Provided	MR			
	f. Door Size						
3.	Compartmentation						
	 Fire check door 	Required	Provided	MR			
	 Sealing of electrical shafts 	s NA	NA	NA			
	 Fire Rating of shaft door 	NA	NA	NA			
	 Water Curtain 	NA	NA	NA			
	• Fire Dampers	NA	NA	NA			
4.	Smoke managements System						
	Basements	NA	NA	NA			
	• Upper floors	12 a/c per hour	Provided	MR			
5.	Fire Extinguishers						
	Total numbers	6 nos.	Provided	MR			
	• Types	ABC &	Provided	MR			
	IS marking	CO2 ISI marked	Provided	MR			
6.	First – Aid Hose Reels						
	Total numbers on each flo	or 1	Provided	MR			

7. Automatic fire detection and alarming system							
Type of detectors	ided MR						
Location of Main Panel Required Providence	ided MR						
Location of Repeater Panel NA N	A NA						
Alternate source of power Required Providence	ided MR						
Hooters' Location Required Providence	ided MR						
8. MOEFA Required Prov	ided MR						
9. Public Address System NA Prov							
10. Automatic Sprinkler System							
• Basements NA NA	NA NA						
Upper Floor Required Providence							
Sprinkler above false NA NA NA							
ceiling							
11. Internal Hydrants							
Size of riser/down- comer 100 mm Providence	ded MR						
Number of hydrants per floor 1 Providence	led MR						
Hose Box Providence	led MR						
12. Yard Hydrants							
Total number of hydrants NA NA	. NA						
Hose Box NA NA	. NA						
13. Pumping Arrangements							
Ground Level							
Discharge of main pump 2280 lpm Prov	vided MR						
	vided MR						
	vided MR						
➤ Jockey pump out put 180 lpm Pro	vided MR						
Jockey pump head 70m Pro	vided MR						
Standby Pump out put 2280lpm Provided	Instead of D.G. Pump E. pump of same capacity is						
Standby Pump Head 70m Prov	vided MR						
	vided MR						
D 11	vided MR						
Terrace level	vided						
Discharge of pump 450 lpm Providence	ded MR						
Head of the pump 40 m Providence							
Power supply Required Providence Providence Required Providence Providence Required Prov							
Auto starting of pump Required Providence Providence Required Providence Providence Required Providence Requ							
14. Captive water Storage for fire fighting							
	ovided MR						
	NA NA						
	ovided MR						
	NA NA						
	ovided MR						
	ovided MR						
16. Provision of Lifts							
	NA NA						
	NA NA						
	vided MR						
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	vided MR						
Required 110	vided MR						
	vided MR						
18. Refuge Area	TA						
Total area NA N	NA NA						
	N A						
➤ Location NA N	JA NA						
Location NA NA 19. Fire control room							
▶ Location NA N 19. Fire control room ▶ Detector system panel NA N	IA NA NA NA						

20.	Special Fire Protection Systems for Protection of special Risks, if any;	NA	NA	NA					
•	One office at terrace is sealed by brick Instead of D.G. pump of 2280 lpm one	wall by owner/or	ccupier.						
• Instead of D.G. pump of 2280 lpm one E. Pump of same capacity is provided &connected with D.G. set be allowed if permitted.									
The fire protection systems provided in the building were test checked and found functional at the time of inspection. The shortcomings issued by this department vide letter no F6/DFS/MS/EH/MN/2021/240 Dated 24/05/2021 have been complied.									
Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.									
	(20 (mydr)	Signature o	f the Inspecting On	ory Sticor					
146/ADO/MND 10/08/2021		Name: Sara	bjeet Singh a: ADO (MN)	incer					
Receive on 15/8/	2021	2021							
1	Deto (WZ)	Mention	d area	& Restorant					
. 80	Mest		V 18/1	1007					
	do								
DATED 19 08 B		2021							
ADO (MN)									
	Sir, The Restourant	us runn	ing at 3rd	floor in a					
	building Comprised of 1st, 2nd & 3rd floors.	J Basimi	nt, Stilt, v	ppur ground.					
9 .									
	As per N.B.C part II			3 under					

N11.6