c-15

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2021/ 35

FIRE SAFETY CERTIFICATE

Certified that the Janta South Indian Lodge located at 4247, Tel Mandi, Pahar Ganj, New Delhi comprised of Ground + 03 Upper floors, Ground floor (Reception), 1st floor (04 guest rooms), 2nd floor (05 guest rooms), 3rd floor (05 guest rooms) and terrace temporary tin shed for staff, total 14 guest rooms owned/occupied by Janta South Indian Lodge was earlier granted **FSC** by this department No.F6/DFS/MS/GH/NDZ/2018/1788 dated 01/08/18. Now, The premise was re-inspected by the officer concerned of this department on 24/08/21 in the presence of Sh. Gulshan and found that the said guest house building having given affidavit dated 30.10.2019 regarding not to use any floor above third floor, deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (Reception), 1st floor (04 guest rooms), 2nd floor (05 guest rooms), 3rd floor (05 guest rooms) total 14 guest rooms only, with effect from for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 1-2-1---at New Delhi by.

(Dr. S.K.Tomar) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure that not to use any floor above third floor for any purpose.

2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi.

Online id no.2021072215625 dated 22.07.21

3. The Manager,

Janta South Indian Lodge 4247, Tel Mandi, Pahar Gani, New Delhi.

Condition for the validity of fire safety certificate

- 1. This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 29.06.2021 latest by 30.09.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

4. The trained fire fighting staff should be available round the clock.

- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT

Janta South Indian Lodge at 4247, Tel 1. Name & address of the building

Mandi, Pahar Ganj, New Delhi.

Residential, Sub Division-A-1 2. Type of occupancy:-

Gr. + 03 Upper floors (total 14 Guest rooms) Ground floor (Reception), 1st floor (04 guest rooms), 2nd floor (05 guest rooms), 3rd floor (05 guest rooms) and terrace temporary tin shed for staff & having given affidavit dated 30.10.2019 regarding not to use any floor above third floor,

3. Type of case:-Renewal

No. F6/DFS/MS/GH/NDZ/2018/1788 dated 4. Details of previous FSC:-

01/08/18.

N/A 5. Fire safety directives No.-24/08/21 6. Date of inspection:-

Sh. Ravinder Singh (ADO/CC) 7. Name of the inspecting officer:-

8. Name & designation of officer From the building side:-

10. Applicant's letter No:-

Sh. Gulam Rabban

9. Year of construction:-

N/A Online id no.2021072215625 dated 22.07.21

				Old Case	
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR	
1.	Access to Building				
	1) Road width	N/A	2 mtr.	N/A	
	2) Gate width	N/A	N/A	N/A	
	3)Width of internal road	N/A	N/A	N/A	
2.	Number, Width Type & Arr	angement of Ex	its		
	A. Number of staircases		-		
	1. Upper floors	01 Nos.	01 Nos.	MR	
	2. Basements	N/A	N/A	N/A	
	B. Width of staircase				
	1. Upper floors	0.80 mtr.	0.87 mtr.	MR	
	2. Basements	N/A	N/A	N/A	
	C. Protection of exits				
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous staircase to terrace	N/A	N/A	N/A	
	E. Width of corridor	N/A	N/A	N/A	
	F. Door size	01 mtr.	01 mtr.	MR	
3.	Compartmentation				
	1) Fire check door	N/A	N/A	N/A	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	N/A	N/A	N/A	
4.	Smoke Management System				
	1) Basements	30 ACPH	N/A	N/A	
	2) Upper floors	Required as	Not provided	Last dt. 30.09.21	
		per G.N		of compliance	
		dated		extended vide	
		27.05.19		order dt.	
				29.06.21	

5.	Fire Extinguishers					
	1) Total numbers	10 Nos.	10 Nos.	MR		
	2) Types	ABC & CO2	ABC & CO2	MR		
	3) ISI marking	Required	Provided	MR		
6.	First-Aid Hose Reel					
	1) Total number of eachfloor	01	01	MR		
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR		
	3) Nozzle diameter	05 mm	05 mm	MR		
7.	Automatic Fire Detection &	- A				
	1) Type of detectors Co Type	Required	Provided	MR		
	2) Location of main panel	First floor	Provided	MR		
	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of power	Required	Provided	MR		
	5) Hooter's Location	Each floor	Provided	MR		
8.	MOEFA	N/A	N/A	N/A		
9.	Public Address System	N/A	N/A	N/A		
10.	Automatic Sprinkler System	11/11	1471	IVA		
and the second	1) Basement	N/A	N/A	N/A		
	2) Upper floors	N/A	N/A	N/A		
	3) Sprinkler above false	N/A	N/A	N/A		
	ceiling	1 1/1 1	14/14	IVA		
11.	Internal Hydrants					
	1) Size of riser/down-comer	N/A	N/A	N/A		
	2) Number of hydrants per	N/A	N/A	N/A		
	floor	14/14	14/71	IVA		
	3) Hose box	N/A	N/A	N/A		
12.	Yard Hydrants	14/71	IN/A	IN/A		
12.	1) Total number of hydrants	N/A	N/A	N/A		
	2) Hose box	N/A	N/A	N/A		
13.	Pumping Arrangement	14/21	IVA	IN/A		
	1) Ground level	N/A	N/A	N/A		
	a) Discharge of main	N/A	N/A			
		IN/A	IN/A	N/A		
	b) Head of main pump	N/A	NI/A	NI/A		
	c) Number of main pump	N/A	N/A	N/A		
			N/A	N/A		
	d) Jockey pump out put	N/A	N/A	N/A		
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump output	N/A	N/A	N/A		
	g) Stand by pump head	N/A	N/A	N/A		
	h) Auto starting/Manual	N/A	N/A	N/A		
14	stopping					
	2) Terrace level	100 7 77				
	a) Discharge of pump	180 LPM	180 LPM	MR		
	b) Head of pump	30 mtr	30 mtr.	MR		
	c) Power supply	Required	Provided	-MR		
	d) Auto starting of pump	Required	Provided	MR		
14.	Captive Water Storage for Fire Fighting					
	1) Under ground tank	N/A	N/A	N/A		
	capacity					
	a) Draw-off connection	N/A	N/A	N/A		
	b) Fire service inlet	N/A	N/A	N/A		

	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	2500 ltr.	2500 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
03	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
10.	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
17.	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			N/A

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2018/1788 dated 01/08/18, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

Remer and Syrretene Please ,