(-67

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2021/SZ 7 0 8

Dated: 3/9/21

FIRE SAFETY CERTIFICATE

Certified that the building of Govt. Sarvodaya Co-ed Sen. Sec. School, Possangipur, B-1, Janakpuri, New Delhi - 110058, comprised of two block namely Nalanda and Primary block having ground plus three upper floors & MP Hall having ground floor only and three blocks namely Bismil, Ramanujan, and APJ Abdul Kalam having ground plus one upper floor each was issued Fire Safety Certificate by this department vide letter F.6/DFS/MS/2018/School/SZ/693 dated 13/04/2018 (for G+3 Upper floors) & F6/DFS/MS/School/2020/SZ/390 Dated 01/10/2020 (for G+1 floor). The School building was re- inspected by the officer concerned of this department on 09/08/2021 in the presence of Sh. Kamlesh Meena (HOS) and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on 3/9/21 at New Delhi.

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to:-

The Principal,
 Govt. Sarvodaya Co-ed Sen. Sec. School,
 Possangipur, B-1, Janakpuri, New Delhi – 110058.

Director of Education,
 Govt. of NCT of Delhi, Old Secretariat,
 New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

gare

School building comprises of Five blocks: Blocks namely Bismil, Ramanujan, Dr.A.P.J.Abdul Kalam having ground plus one upper floor and Nalanda & Primary block having Ground plus three upper floors and MP Hall having ground floor only (Govt. Sarvodaya Co-ed Senior Secondary School, Possangipur, B-1, Janakpuri, New Delhi - 110058)

INSPECTION REPORT

Name & address of the building : Govt. Sarvodaya Co-ed Sen. Sec. School, Possangipur, B-1, Janakpuri, ND - 110058 1.

Educational Type of Occupancy 2. Type of Case Renewal 3.

F.6/DFS/MS/2018/School/SZ/693 dated 13/04/2018 (for G+3 Upper floors) & Details of Previous NOC

F6/DFS/MS/School/2020/SZ/390 Dated 01/10/2020 (for G+1 floor)

5. Fire Safety directives letter No :

09/08/2021 6. Date of inspection

A.D.O. R.K. Yadav 7. Name of Inspecting Officer

8. Name and designation of officers

	From the building side : Sh. Kamlesh I								
	Year of Construction : Before 2011 &	dated 06/08/2021							
10. S. No.	Applicant's letter No. : Letter No. 727 Minimum Standards on fire prevention and fire safety U/R 33	Requirements	Provided at site	Remarks MR/NMR					
1.	Access to building								
	 Road width Gate width Width of internal road 	Accessible 4.5 m	09 m provided	M/R					
2.	Number, Width, Type & Arrangement of Exits								
4.	a. Number of staircases								
	Upper Floors	10 No's	10 N	o's	M/R				
	Basements	N/A	N/A	4	N/A				
	b. Width of staircases								
	Upper FloorBasements	1.50 m	1.75 m (3 No.'s in N (1 No. in Prmy bl) Bismil blk, 1.57 x 2 1.64 m in Rar	k),1.37&1.60 in in APJ blk,1.40 &	M/R				
	c. Protection of exits	N/A	1.04 m m Kai		N/A				
	Fire check door	1011							
	Pressurization	N/A	N/	A	N/A				
		N/A	N/		N/A				
	d. No. of continuous staircases to	IN/A	TWEE		1 1/1 1				
	terrace		Durate	dad	N/A				
	e. Width of Corridor	Required	Prov		M/R				
	C D C	1.5 m	1.75 m						
	f. Door Size	1.0 & 2.0 in MP Hall	.97 to 1.12 m (Double Door) & 2.08 (2 No.'s) & 1.35 (4 no.'s) in MP hall		M/R				
3.	Compartmentation								
	Fire check door	N/A	N/A		N/A				
	Sealing of electrical shafts	N/A	N/A		N/A				
	Fire Rating of shaft door	N/A	N/A		N/A				
	Water Curtain				N/A				
	Fire Dampers	N/A	N/A N/A		N/A				
4.	Smoke Management System								
	Desaments	N/A	N/A	N/A					
	Basements	N/A	Natural M/						
	Upper floors	N/A	Ventilation	The second secon					
5.	Fire Extinguishers								
	Total numbers	30 no's	Provided M						
	• Types	ABC/CO ₂ type	Provided	M/R					
	IS marking	ISI marked	ISI marked	ISI marked M/F					

School building comprises of Five blocks: Blocks namely Bismil, Ramanujan, Dr.A.P.J.Abdul Kalam having ground plus one upper floor and Nalanda & Primary block having Ground plus three upper floors and MP Hall having ground floor only (Govt. Sarvodaya Co-ed Senior Secondary School, Possangipur, B-1, Janakpuri, New Delhi - 110058)

6. First-Aid Hose Reels Nalanda & Primary block							Thoor only (Govt.
	Total numbers on each floor	a & 1 no of D	of Proceedings of Procedure Procedur			1	
	 Length of hose reel hose 	2 no. in Nalanda & 1 no. of Pry. Blk. 30 m 05mm		ly. Dik.	Provided Provided		112/12
	Nozzle diameter			1			A TATAL
					Pro	vide	d M/R
7.	Automatic fire detection and alarm	ning system					
	 Type of detectors 		N/A	N/	'A	T	N/A
	 Location of Main Panel 		N/A	N/			
	 Location of Repeater Panel 		N/A				N/A
	 Alternate source of power 		N/A	N/			N/A
			N/A	N/	- A	-	N/A
8.	Hooters' Location MOEFA			19/	A		N/A
9.			N/A	N/	A		N/A
10.	Public Address System Automatic Sprinkler System		N/A	N/	A		N/A
	ratematic Sprinkler System						
	Basement		N/A) NI/			
	Ground Floor		N/A	N/			N/A
	Sprinkler above false ceiling		N/A	N/A			N/A
11.	Internal Hydrants		IV/A	N/2	4		N/A
	Size of riser/down-comer		N/A	N/A	1	-	N/A
	 Number of hydrants per floor 		N/A	N/A			N/A
12.	Hose Box		N/A	N/A	1		N/A
4.	Yard Hydrants						
	Total number of hydrants		NY/ 4				
	Hose Box		N/A	N/A			N/A
3.	Pumping Arrangements	Nolonda	N/A	N/A	1		N/A
	a de la contraction de la cont	Najanda	& Primary b	lock			
	Ground Level					· 	
	Discharge of main Pump	N/A		N/A	A		, NI/A
	Head of Main pump	N/A				,	N/A
	Number of main pumps	N/A		N/A			N/A
	> Jockey Pump out put	N/A		N/A	£, - ',		N/A
	> Jockey pump head			N/A			N/A
	stariaby ramp out put	N/A		N/A			N/A
	Standby Pump HeadAuto Starting/Manual	N/A		N/A			N/A
	Stopping	N/A	**	N/A			N/A
	Stobbille	N/A		N/A			N/A
	> Pump House Access	N/A		>T/ 4			
	Terrace level	- 1/1 X		N/A			N/A
	Discharge of pump	450 lpm Noland	Pr Day 1 11	P			
		450 lpm Nalanda 40 m	& Pry blk.	Provide			M/R
		Required		Provide			M/R
	> Auto Starting of pump	Required		Provide		_	M/R
		x oquitou		Provide	ed		M/R
							· · · · · · · · · · · · · · · · · · ·
	Captive Water Storage for fire fighting Nalanda & Primary block						
	Underground tank capacity Draw-off connection	N/A		N/A	5 0100	44	N/A
	Monage and Connection	N/A		N/A		2	N/A
	Fire service inlet Access to tank	N/A		N/A			
	riceess to talk	N/A		N/A			N/A
	Overhead Tank capacity 1	0,000 ltrs Nalanda	& Pry bll		J	1	N/A
		Required	cerry bik.	Provide Provide			M/R
	Exit Signage.			Provide	u		M/R

1/31

School building comprises of Five blocks: Blocks namely Bismil, Ramanujan, Dr.A.P.J.Abdul Kalam having ground plus one upper floor and Nalanda & Primary block having Ground plus three upper floors and MP Hall having ground floor only (Govt. Sarvodaya Co-ed Senior Secondary School, Possangipur, B-1, Janakpuri, New Delhi - 110058)

16.	Provision of Lifts.			
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	 Fire man's Grounding Switch 	N/A	N/A	N/A
Lift Signage	Lift Signage	N/A	N/A	N/A
		N/A	N/A	N/A
17.	Standby power supply		*	
18.	Refuge Area.			,
	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19.	Fire Control Room			
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans			
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter numberF.6/DFS/MS/2018/School/SZ/693 dated 13/04/2018 (for G+3 Upper floors) & F6/DFS/MS/School/2020/SZ/390 Dated 01/10/2020 (for G+1 floor) renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Officer

Name: - R.K. Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

(sz) F.f

And GKP)