GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/2021/SZ/ 216

Dated: 08/09/2021

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s HIRA SWEETS (A Unit of Hira Sweets and Confectionary Pvt. Ltd., located at Ground floor, Shop No J 2 B, RP Lajpat Nagar- II, New Delhi- 110024 in the building comprised of Basement, ground plus three upper floor owner occupied by Sh. Chander Shekhar Mishra (M/s HIRA Sweets and Confectionary Pvt. Ltd) have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 18/08/2021 in the presence of Mr. Rakesh Tiwari and that the premises is fit for occupancy class "Group-D Assembly" (Restaurant running at Ground Floor only) with effect from the date of issue of this certificate for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 08 / 69 /2021 at New Delhi by

TULGARG)
DIRECTOR

Copy to: -

The same of the sa

- 1. The Dy. Health Officer, SDMC, Public Health Department, Green Park, Aurobindo Marg, New Delhi 110016. (Ref. MHA Portal ID 2021081017389 dated 10/08/2021)
- 2. The Joint Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049.
- 3. M/s HIRA SWEETS AND Confectionary Pvt. Ltd., Shop No J 2 B, Ground Floor, RP Lajpat Nagar- II, New Delhi- 110024

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

1	IN	ame & Address of the Building	M/s HIRA SWE	ETS and Confections	ary Pvt. Ltd,
			Delhi- 110024	Ground Floor, RP Laj	pat Nagar-II,
2	Ty	ype of Occupancy	Group-D Assembly Building.		
3	Bi	uilding Comprised of	Basement, Ground Plus three upper floor		
	T	200	(Restaurant running at ground floor only)		
4		ype of Case	New		
5		etails of Previous NOC	Nil		
6	-	re Safety Directives Letter No	UBBL-2016 / NE	BC Part-IV	Statistical distributed and consider state and consider
	-	ate of Inspection	18/08/2021		
8	-	ame of the Inspecting Officers	DO (SD) & ADO (BCP)		
9	i i	ame & Designation of Officers	Sh. Rakesh Tiwar	ri.	
10	-	om the building side ear of construction	2000		
11		oplicant letter No.	2008		
11	A	opticant letter No.	MHA Portal ID 2021081017389 dated 10/08/2021		
S. No.	M	inimum standards on Fire Prevention	UBBL/NBC	Provided at Site	Remarks
	an	d Fire Safety U/R 33	Requirement		MR/NMR
1	A	ccess to Building.		1	
		Road width	Required	9m	MR
		Gate width	N/A	Assessable from road	N/A
		Width of internal road	N/A	N/A	N/A
2	Ni	umber, width, type & arrangement of ex			11/21
	-	Number of Staircase			
	ŕ	Upper floors.	N/A	N/A	N/A
		Basement floor.	N/A	N/A	N/A
	b)		14/7	IN/A	IV/A
	-	> Upper floors	N/A	N/A	N/A
		Basement floor	N/A	N/A	
	c)	Protection of exits	14/24	IN/A	N/A
		Fire check door	N/A	N/A	DT/A
	arve dimension	> Pressurization	N/A	N/A	N/A
	d)	No. of continuous staircase to terrace	Required	One	N/A
	e)	Width of corridor	N/A		MR
	f	Door size	1.50 mtr x 2	N/A 1.50 mtr each	N/A
3	-	mpartmentation.	1,50 mm x 2	1.50 mtr each	MR
		Fire check door.	N/A	N/A	DT/A
		 Sealing of electrical shafts. 	N/A		. N/A
		Fire rating of shaft door.	N/A	N/A	IN/A
		Water curtain	N/A	N/A	N/A
				N/A	N/A
4	Sm	• Fire dampers. noke Management system.	N/A	N/A	N/A
7	SIL				
		• Basement	30 ACPH	N/A	N/A
		Upper floors	12 ACPH	N/A	N/A
5	Fi	re Extinguishers.			1
According to the second		Total numbers	06 Nos	06 Nos	MR
		• Types	ABC/CO ₂	ABC & CO ₂	MR
	Charles and the same of the sa	ISI Marking	ISI marked	Provided	MR
.6	Fi	rst Aid Hose Reels.			ATAL
		Total numbers on each floor.	One	Provided	MR
		• Length of hose-reel hose.	30m	Provided	MR
		Nozzle Diameter	5mm	Provided	MR
7	Au	tomatic fire detection & alarming system			

	 Location of Main Panel 	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
. 8	MOEFA	Required	Provided	MR
9	Public Address System	N/A	NA NA	N/A
10	Automatic Sprinkler System			
	Basement	N/A	N/A	N/A
	Ground floor.	N/A	Provided	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.			
	Size of Riser/Down-comer	100 mm	Provided	MR
	Number of Hydrant per floor	One	Provided	MR
	Hose box.	One	Provided	MR
12	Yard Hydrants.		J	
	Total number of hydrants.	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13	Pumping arrangements.		1	L
·	Ground Level		A	
	Discharge of main pump.	N/A	N/A	N/A
	➤ Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A
	Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A	N/A	N/A
	Standby Pump head.	N/A	N/A	N/A
	Auto Starting/Manual Stopping.Pump house access.	N/A	N/A	N/A
		IVA	IV/A	IN/A
	 Terrace Level Discharge of pump. 	450 I DM	Provided	MR
	Head of pump.	450 LPM		
	Power supply.	40 m	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14		Required	Provided	MR
14	Captive water storage for fire fighting.	3 T / A		27/1
	 Underground tank capacity. Draw-off connection. 	N/A	N/A	N/A
	Fire Service Inlet.	N/A	N/A	N/A
	Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	N/A	N/A	N/A
4.5		20,000 Ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			T
	Pressurization of lift shaft.	N/A	N/A	N/A
	Pressurization of lift lobby.	N/A	N/A	N/A
	Communication in lift car. Figure 2.2 a said the	N/A N/A	N/A	N/A
	• Fireman's switch.		N/A	N/A
17	Lift signage. Standby Power Supply	N/A	N/A	N/A
18	Standby Power Supply Pofuge Area	N/A	N/A	N/A
19	Refuge Area			
	Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room.			-
	Detector system panel.	N/A	N/A	N/A
	• Flow switch panel.	N/A	N/A	N/A

	PA system panel.	N/A	N/A	N/A
	 Battery backup. 	N/A	N/A	N/A
	Building floor plan.	N/A	N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: - Sh. S. K Dua

Designation: - DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Designation: ADO (BCP)

Dy. CFO (SZ)

Receive don 1/9

As approved, F.T. letter is pump for your synature Pl.