## Sovernment of national capital territory of delhi HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/2021/WZ/ 4 28

Dated: 02/09/2021

## FIRE SAFETY CERTIFICATE

Certified that the Dr. Lal Pathlabs Ltd. Block-E, Sector-18, Rohini, Delhi-110085, comprised of Basement, Ground + Four upper floors was granted NOC by this department vide letter No. F.6/MS/DFS/WZ/2017/1343 dated 08.09.2017. The premises was re-inspected by the officer concerned of this department on 13.08.2021 in the presence of Mr. Ashish Thakur (DGM) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy Group "Business Building (Lab)" with effect from 09/09/301 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi 

Ph: 011-23414000

010

CNL

Copy to :-

1. Dr. Lal Path Labs Ltd. Block-E, Sector-18, Rohini, Delhi-110085.

## Conditions for the validity of fire safety certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director on Form'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form "K"is available on.
- 8. The temporary structure placed for COVID screening shall be removed within 6 moths from the date of issuance of this certificate under intimation to this department, non compliance will be treated as null & void of this department.

http://www.delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/ http://www.delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Forms

1	NI		oth lobe I td. P	look E. Sooton 10 Dollini D. 1	h; 05		
1. 2.		Name & address of the building : Dr. Lal Path labs Ltd. Block-E, Sector-18, Rohini, Delhi-85 : Business					
3.	Type o						
4.			,	1343 dated 08.09.2017	,		
5.	Fire Sa	fety directives letter No : F.6/DFS/	MS/BP/Hospit	tal/2007/1236 dated 01.05.2007	7		
6.		inspection : 13.08.202					
7.			D.B. Mukher	jee & ADO Rohini A.K.Sharr	na		
8.		and designation of officers	-1. Tl1 (DC				
0			sh Thakur (DC	JM)			
9. 10.		f Construction : 2007 ant's letter No. : Online m	nail dated 18.00	6 2021			
S. No.		num Standards on fire prevention and	NBC	Provided at site	Remarks		
5.110.		fety U/R 33	Requireme	110vided de site	MR/NMR		
			nt / Rule 35				
			(6)				
1.	Acces	s to building					
	•	Road width	Accessible	12 M	MR		
	•	Gate width	Accessible	5 M	MR		
	•	Width of internal road	Required	Provided	MR		
2.	Numl	per, Width, Type & Arrangement of	Exits	2			
	d.	Number of staircases					
		Hanna Elana	4 Nos	04 Nos. Provided	MR		
	•	Upper Floors	4 Nos + 2	4 Nos. Stairs + 2 Ramp Provided			
	•	Basements	Ramps-		IVIIC		
			As per				
			approved by				
			FPW at N/16	· ·			
	e.	Width of staircases					
		Upper Floor	1. 5 mtr	2.0m & 3 X 1.47m	MR		
			1. 5 mtr	each provided 2 X 1.5m & 2 X 1.9m	(Old Case		
	•	Basements	1. 3 IIII	each provided	MR		
	f.	Protection of exits	-				
	Fire c	heck door	Required	Provided	MR		
	•	Pressurization	Required	Provided	MR		
			02	02	MR		
		o of continuous staircases to terrace	1.5 mtr	Provided	MR		
		idth of Corridor	1.0 mtr	Provided			
l te	f. De	oor Size	1.0 11111	Provided	MR		
3.	Comp	partmentation					
	•	Fire check door	Required	Provided	MR		
	•	Sealing of electrical shafts	Required	Provided	MR		
	•	Fire Rating of shaft door	Required	Provided	MR		
	•	Water Curtain	N/A	N/A	N/A		
	•	Fire Dampers	N/A	N/A	N/A		
4	Smok	e Management System	"		1,111		
4.		Basements	30 a/c per	Provided	MR		
4.	•		hours	Tioriaca	1411/		
4.	•						
4.	•	Upper floors	12 a/c per	Provided	MR		
7	•		12 a/c per hours	Provided	MR		
5.	•	Extinguishers	_	Provided	MR		
7	•	Extinguishers  Total numbers	hours 48 Nos.	Provided  82 Nos.	MR MR		
7	• Fire I	Extinguishers	hours				

INSPECTION REPORT

	That The Host Aces			(P)
	• Total numbers on each floor	02	Provided	MR
	• Length of hose reel hose	30 m	Provided	MR
	Nozzle diameter	5 mm	Provided	MR
7.	Automatic fire detection and alarmin	g system		IVIIC
	Type of detectors	Required	Provided	MR
	• Location of Main Panel	Ground floor	Provided	MR
	• Location of Repeater Panel	N/A	N/A	N/A
	<ul><li>Alternate source of power</li><li>Hooters' Location</li></ul>	Required	Provided	MR
	Thoters Location	Required	Provided	·
8.	MOEFA	Required	Provided	MR MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System		Tiorided	IVIK
	• Basement	Required	Provided	MD
	<ul> <li>Ground &amp; Upper Floors</li> </ul>	Required	Provided	MR
	Sprinkler above false ceiling	N/A	N/A	MR
11.	Internal Hydrants		IN/A	N/A
	Size of riser/down-comer	100 mm	Provided	100
	<ul> <li>Number of hydrants per floor</li> </ul>	2 Nos.	Provided	MR
	• Hose Box	2 Nos.	Provided	MR
12.	Yard Hydrants	2 1103.	Provided	MR
	Total number of hydrants	Required	D 1 1	
	Hose Box	Required	Provided	MR
13.	Pumping Arrangements	required	Provided	MR
	Ground Level			^
	Discharge of main Pump	2850lpm	D	
	Head of Main pump	70 m	Provided	MR
	Number of main pumps	Two	Provided	MR
	Jockey Pump out put	180lpm (2 Nos.	Provided	MR
	Jockey pump head	70 m	Trovided	MR
	Standby Pump out put	2850lpm	Provided	MR
	Standby Pump Head	70 m	Provided	MR
	Auto Starting/Manual Stopping		Provided	MR
	Pump House Access	Required	Provided	MR
	Terrace level	Required	Provided	MR
	Discharge of pump	<b>&gt;</b> T/ +		
	Head of the pump	N/A	N/A	N/A
	Power Supply	N/A	N/A	N/A
	Auto Starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for fire fighting	N/A	N/A	N/A
		-		
	<ul><li>Underground tank capacity</li><li>Draw-off connection</li></ul>	75,000 ltr	75,000 ltr	MR
	Fire service inlet	Required	Provided	MR
	Access to tank	Required	Provided	MR
	Overhead Tank capacity	Required	Provided	MR
15.	Exit Signage.	10,000 ltr	10,000 ltr	MR
16.	Provision of Lifts.	Required	Provided	MR
	• Pressurization of Lift Shaft	Required	Provided	MR
	Tressurization of Lift lobby	N/A	N/A	N/A
	<ul><li>Communication In lift Car</li><li>Fireman's Grounding Switch</li></ul>	Required	Provided	MR MR
	Switch	Required	Provided	MR
				IVIK

0	•	Lift Signage	Required	Provided	MR		
17.	Stand	by power supply	Required	Provided	MR		
18.	Refuge Area.						
	. >	Total Area	N/A	N/A	N/A		
	>	Location	N/A	N/A	N/A		
19.	Fire Control Room						
_ '	0	Detector System Panel	Required	Provided	MR		
	•	Flow Switch Panel	N/A	N/A	N/A		
	•	PA System Panel	Required	Provided	MR		
	0	Battery backup Building Floor Plans	Required	Provided	MR		
	•		Required	Provided	MR		
20.	Specia	al Fire Protection System for	Required	Provided	MR		
	Prote	ction of special Risks, if any:					

Accordingly, the fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part-4, and removal of shortcomings issued vide letter no. 155 dated 20.01.2021, the FSC issued vide letter no. F.6/MS/DFS/WZ/2017/1343 dated 08.09.2017; renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended with a condition that temporary structure provided for COVID screening will be removed within 6 months from the date of issuance of FSC & non compliance under intimation to this department shall be treated as null & void of the FSC.

my24/08/2021

Signature of the Inspecting Officer Name (D.B. Mukherjee)

Designation DO (NW)

Signature of the Inspecting Officer

Name Ajay Kumar Sharma Designation ADO(Rohini)

FT letter is put up for Kind perusal and Signalure please.