FORM 'H'

FORM FOR ISSUING FIRE SAFETY CERTIFICATE [Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI

No. F6/DFS/MS/2021/SZ/ 437

Dated: 08/09/2021

FIRE SAFETY CERTIFICATE

Certified that the Polyclinic for New Delhi Centre for Sight (Pvt) Ltd, Located at, Sector -9, Dwarka, New Delhi - 110076 comprised of three tier basement, Ground + 5 Upper Floor owned/occupied by M/s A unit of New Delhi Centre for sight Ltd was issued FSC vide Letter No. F6/DFS/MS/SZ/2018/592 Dated- 05/04/2018. The premises was re inspected by the officers concerned of this department on 19/08/2021 in the presence of Ms. Vandana and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class " Business" Group E with effect from 08/09/22/ for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ... 08/09/2021 at New Delhi by.

Copy to: -

- 1. The Manager, Polyclinic for New Delhi Centre for Sight (Pvt) Ltd, Located at Sector 9, Dwarka, New Delhi – 110076
- 2. The Dy. Director (L&I) Building, DDA, Vikas Sadan, INA, New Delhi.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expired.

INSPECTION REPORT

 Name & address of the building: Polyclinic for New Delhi Centre for Sight (Pvt) Ltd, Located at Sector – 9, Dwarka, New Delhi - 110076

2. Type of Occupancy: Business 03 tier basement, Ground + 5 Upper Floors

3. Type of Case : Renewal

4. Details of previous NOC: F6/DFS/MS/SZ/2018/592 Dated- 05/04/2018

5. Fire Safety directives L. No.: NBC Part IV/F6/DFS/MS/BP/2015/210,Dated 09/07/2015

6. Date of inspection : 19/08/2021

7. Name of the Inspecting Officer: Udai vir Singh ADO (DWK)

8. Name and designation of Officer:

from the building side : Ms. Vandana

9. Year of Construction :2017-18

10. Applicant's letter No. : Email dated - 12/07/2021

S	Minimum standards on fire	NBC/B	NBC/BBL		Provided at site		Remarks		
No	prevention and fire safety	Require	Requirements				MR	/NMR	
	U/R 33	As per	As per N/5						
1.	Access of building								
	 Road width 	12 m		Provided Provided		110	MR MR		
	 Gate width 	4.5 m							
	 Width of internal ro 	ad 6 m	5.9 to	6m	Old Case	MR(Bein	g Old Case	
2.	Number, width, Type & Ar	rangements	angements of exits					¥	
	 a. Number of staircase 	S		*1			3	э.	
	 Upper floors 	02	02		Provided		MR		
	 Basements 	02 + 02	02 + 02 Ramp		Provided		MR		
	b. Width of staircases						# E F		
	• Upper floors		1.5 mtr Stair-183cm, 192cm each Stair=183cm, 142cm 1.5 mtr each Stair=183cm, 142cm & Ramp Ramp=305cm,295cm		192cm	MR(Being Old Case			
	• Basements	1.5 mtr					ı, N	MR(Being Old Case	
	c. Protection of exits		-		,			Vi.	
	Fire check door	Require	Required Required Required 1.5 mtr Prov		Provided Provided		M	MR MR	
	Pressurization						M		
	d. No of continuous staircase to terrace	Requir			Provid	Provided			
	e. Width Of Corridor	1.5 mtr			vided MR(B		eing Old Case		
	f. Door Size	1.5 mtr		Prov	vided	MR(B	MR(Being Old Cas		
3.	Compartmentation								
	Fire check door	Require	Required Required		Provided Provided			MR	
	• Sealing of electrical shafts	Requir						MR	
	 Fire Rating of shaft door 	NA			NA		TW:	NA	
	Water Curtain	NA	NA		NA			NA	
	 Fire Dampers 	Requir	Required		Provided			MR	

			n			<u> </u>
4.	Smoke managements System					
	Basements	302/0	per hour	Provided		MR
	 Upper floors 		per hour	Provided (ope	n able	MR
	• Opper Hoors	12a/0	per nour	window)	II able	IVIIX
5.	Fire Extinguishers			willdow)		
٥.		30		Duaridad		MD
	Total numbers	(4) 30	e-co2	Provided		MR
	• Types		&CO2,	Provided		MR
	IS marking	ISI ma	arked	Provided		MR
6.	First – Aid Hose Reels			1101144		1711
	Total numbers on	02 No	S.	Provided		MR
	each floor			110,140		1111
	 Length of hose reel 	30 m		Provided		MR
	hose			110114		17111
	Nozzle diameter	5 mm		Provided		MR
7.	Automatic fire detection and a			1101144		17114
-	Type of detectors		e & Heat	Provided		MR
	Location of Main	-	d Floor	Provided		MR
	Panel	Groun	1 1001	Tiovided		IVIK
	 Location of Repeater 	Each	floor	Provided		MR
	Panel	Laci	1001	Trovided		IVII
	Alternate source of	Requi	red	Provided		MR
	power	requi	100	Trovided		IVIIX
	Hooters' Location	All ar	eas .	Near stairs at eac	h floor	MR
8.	MOEFA Location					1411
		Requi		Provided MR Provided MR		
9.	Public Address System	Requi	red			
10.	Automatic Sprinkler System					
	• Basements		equired	Provided	MR	
	Upper Floor		equired	Provided	MR	
	 Sprinkler above false 	Re	equired	Provided	MR	
55	ceiling					
11.	Internal Hydrants:					*
	Size of riser/down- cor	mer	150 mm	Provided MR		
	 Number of hydrants per 	er floor	02 No.	Provided	MR	
	Hose Box		02 No.	Provided	MR	
12.	Yard Hydrants					
10	Total number of hydra	nts	05 Nos.	Provided	MR	
	Hose Box		05 Nos.	Provided	MR	
		Hose Box				
					4)	
			8 2			
	47 %					
	×			= 1 e		
				*		
			8			
	Pumping Arrangements:			A CONTRACTOR OF THE PARTY OF TH		

3. F	Pumping Arrangements:		•		
	Ground Level	2200 1	Provided	MR	
	Discharge of main	2280 lpm	riovided	1712	
	pump	80 m	Provided	MR	
*:	Ticau of main pamp	01 Nos.	Provided (02 Nos) MR	
	I dillioci oi mani	01 1105.	11071404 (02 2.12	<i>'</i>	
	pumps > Jockey pump out put	180 lpm	Provided (02 Nos)	MR	
	1 1	80m	Provided	MR	
	Jockey pump headStandby Pump out put	2280 lpm	Provided	MR	
	Standby Pump Head	80m	Provided	MR	
	> Auto Staring/Manual	Required	Provided	MR	
-	stopping	Required	_		
	> Pump House Access	Required	Provided	MR	
	Terrace level	Ttoquii			
40	Discharge of pump	NA	900 lpm	NA	
	> Head of the pump	NA	50 mtr	NA	
	> Power supply	NA	NA	NA·	
	> Auto starting of pump	NA	Provided	NA	
14.	Captive water Storage for fire f		1 - 1 - 1		
14.	Under ground tank	1,00,000 litre	Provided	MR	
Y 2	capacity	,			
	> Draw off connection	Required	Provided	MR	
	Fire service inlet	Required	Provided	MR	
	> Access to tank	Required	Provided	MR	
	Overhead Tank	10,000ltr	Provided	MR	
	capacity				
15	Exit Signage	Required	Provided	MR	
16.	Provision of Lifts			, ,	
10.	> Pressurization of Lift	Required	Provided	MR	
	Shaft				
	Pressurization of lift	Required	Provided	MR	
	lobby				
	Communication in lift	Required	Provided	MR	
	Car	> —		100	
	> Fireman's Grounding	Required	Provided	MR	
	Switch			X (D)	
	Lift Signage	Required	Provided	MR	
17	Ctandhy navyan aunnly	Required P	rovided	MR	
17.		Toquilou 1			
18.		NIA	NA	NA	
1	> Total area	NA	NA NA	NA	
	> Location	NA	INA	1 12 %	
19.		1 Degrained	Provided	MR	
1	> Detector system pane	1 Required	Provided	MR	
	Flow Switch Panel	Required	Provided	MR	
	PA System Panel	Required	Provided	MR	
	Battery backup	Required	Provided	MR	
	Building Floor Plans	Required	Tiovided	11111	
	2			, <u> </u>	
		4			
				Link hid	
Name of the last					
1.6		2.			

20.	Special Fire Protection	Required	02 CO2 flooding	MR
	Systems for Protection of		system in HT &	
	special Risks, if any;		LT.Panels.	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter no. F6/DFS/MS/SZ/2018/592 Dated- 05/04/2018 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Note;- In earlier inspection 03 stairs were found provided in the basement. Now only 02 stairs & 02ramps were seen however it is still meet with the criteria of travel distance/ exit requirement.

Sign of Inspecting Officer
Name Volay Var Strayh
Designation

Abolawy