

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001**

No.F6/DFS/MS/FW/NDZ/2021/

436

Dated: - ...../...../2021

07/09

**FIRE SAFETY CERTIFICATE**

Certified that the **M/S Gupta and Company** located at at **10103 to 10105, Rani Jhansi Road in front of Filmistan, Model Basti, Village Sidhipura, Delhi** proposed for running the trade of sale and possession of manufactured fireworks and Chinese crackers/sparkles of same category in quantities and class as specified by the licensing authority, at ground floor of a building owned/occupied by **Gupta and Company**, was granted FSC by this department vide letter No. **F6/DFS/MS/NDZ/2018/4156** dated **04/10/2018**. The premises was re-inspected by the officer concerned of this department on **16/08/21** in the presence of Mr. **Sita Ram Gupta** and found that the said building has complied with guidelines issued by Joint. Commissioner of Police (Lic.) and that the premises is fit for occupancy of Group J (Hazardous Occupancy) "**Fireworks**" with effect from...**07/09/2021**...for period of **three years**, subject to conditions mentioned below.

Issued on...**07/09/2021**...at New Delhi by.

  
(Atul Garg)  
**DIRECTOR**  
Delhi Fire Service  


Copy to:-

1. The Joint. Commissioner of Police (Lic.),  
1<sup>st</sup> floor, P.S. Defence Colony, New Delhi.
2. M/S Gupta and Company  
located at 10103 to 10105 , Rani Jhansi Road in front of Filmistan, Model basti  
Village Sidhipura , Delhi

**Condition for the validity of fire safety certificate**

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
9. The guidelines issued by the hon'ble Supreme Court shall be ensured/ complied.

**INSPECTION REPORT**

1. Name & address of the building **M/S Gupta and Company at 10104, Rani Jhansi Road in front of Filmistan , Model basti Village Sidhipura , Delhi**
2. Type of occupancy:- **Hazardous occupancy , Fire Works Ground floor only)**
3. Type of case:- **Addition /alteration -Renewal**
4. Details of previous FSC:- **F6/DFS/MS/NDZ/2018/4156 dated 04/10/2018.**
5. Fire safety directives No.- **N/A**
6. Date of inspection:- **16/08/2021**
7. Name of the inspecting officer:- **Sh. Ravinder Singh (ADO/CC)**
8. Name & designation of officer  
From the building side:- **Mr. Sita ram**
9. Year of construction:- **2013**
10. Applicant's letter No:- **letter no. 339/Joint CP/Lic.(Expl.), dated 23.07.2021**

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement Existing fire safety arrangements	Provided at site	Remarks MR/NMR
<b>1.</b>	<b>Access to Building</b>			
	1) Road width	06 mtr.	09 mtr.	MR
	2) Gate width	N/A	N/A	N/A
	3) Width of internal road	N/A	N/A	N/A
<b>2.</b>	<b>Number, Width Type &amp; Arrangement of Exits</b>			
	<b>A. Number of staircases</b>			
	1. Upper floors	N/A	N/A	N/A
	2. Basements	N/A	N/A	N/A
	<b>B. Width of staircase</b>			
	1. Upper floors	N/A	N/A	N/A
	2. Basements	N/A	N/A	N/A
	<b>C. Protection of exits</b>			
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	<b>D. No. of continuous staircase to terrace</b>			
	1. Upper floors	N/A	N/A	N/A
	2. Basements	N/A	N/A	N/A
	<b>E. Width of corridor</b>			
	1. Upper floors	N/A	N/A	N/A
	2. Basements	N/A	N/A	N/A
	<b>F. Door size</b>			
	1. Upper floors	N/A	N/A	N/A
	2. Basements	N/A	N/A	N/A
	<b>G. No. of exits</b>			
	1. Upper floors	Independent entry and exit required	Provided	MR
<b>3.</b>	<b>Compartmentation</b>			
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	<b>3) Fire rating of shaft door</b>			
	1) Upper floors	N/A	N/A	N/A
	2) Basements	N/A	N/A	N/A
	<b>4) Water curtain</b>			
	1) Upper floors	N/A	N/A	N/A
	2) Basements	N/A	N/A	N/A
	<b>5) Fire Dampers</b>			
	1) Upper floors	N/A	N/A	N/A
	2) Basements	N/A	N/A	N/A
<b>4.</b>	<b>Smoke Management System</b>			
	1) Basements	30 ACPH	N/A	N/A
	2) Upper floors	12 ACPH	N/A	N/A
<b>5.</b>	<b>Fire Extinguishers</b>			
	1) Total numbers	05 Nos.	05 Nos.	MR

M/17

	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
<b>6.</b>	<b>First-Aid Hose Reel</b>			
	1) Total number of each floor	N/A	N/A	N/A
	2) Length of hose reel hose	N/A	N/A	N/A
	3) Nozzle diameter	N/A	N/A	N/A
<b>7.</b>	<b>Automatic Fire Detection &amp; Alarming System</b>			
	1) Type of detectors	N/A	N/A	N/A
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
<b>8.</b>	<b>MOEFA</b>			
<b>9.</b>	<b>Public Address System</b>			
<b>10.</b>	<b>Automatic Sprinkler System</b>			
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false ceiling	N/A	N/A	N/A
<b>11.</b>	<b>Internal Hydrants</b>			
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per floor	N/A	N/A	N/A
	3) Hose box	N/A	N/A	N/A
<b>12.</b>	<b>Yard Hydrants</b>			
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
<b>13.</b>	<b>Pumping Arrangement</b>			
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main pump	N/A	N/A	N/A
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual stopping	N/A	N/A	N/A
	2) Terrace level			
	a) Discharge of pump	N/A	N/A	N/A
	b) Head of pump	N/A	N/A	N/A
	c) Power supply	N/A	N/A	N/A
	d) Auto starting of pump	N/A	N/A	N/A
<b>14.</b>	<b>Captive Water Storage for Fire Fighting</b>			
	1) Under ground tank capacity	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank	N/A	N/A	N/A

N/A

MR
MR
N/A
N/A
N/A

15.	Exit Signage.	Required	Provided	MR
16.	<b>Provision of Lifts.</b>			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	<b>Stand by Power Supply</b>	N/A	N/A	N/A
18.	<b>Refuge Area</b>	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	<b>Fire Control Room</b>	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	<b>Special Fire Protection System for Protection of special Risk, if any:</b> 1. No smoking signages board, sand bucket., 3. All the electric wiring found in conduit. 4. MCB found provided. 5. No other shop of same type inflammable material is located in the vicinity of 15 meter.			MR

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

Further, the department has already issued a FSC for storage of fireworks at shop no. 10104 area of admeasuring 13.85SQM vide letter No F6/DFS/MS/NDZ/2018/4156 dated 04.10.2018(copy placed on file at C/51).

Now, the letter has been received from ACP /A & E regarding issuance FSC to additional land i.e 10103 & 10105 adjacent to existing shop. Accordingly, the site was inspected by ADO (CC) on dated 16.08.21 and observed that the building is comprised of ground floor having shops at ground floor ( 13.85 m2 (existing)+ **10.14 m2( proposed)** = 23.99 m2 for storage of fire crackers. and fire safety arrangements as mentioned above are placed on the site.

In view of the compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if agreed, the FSC issued vide letter no. F6/DFS/MS/NDZ/2018/4156 dated 04/10/2018, renewal under guidelines issued by Addl. Commissioner of Police (Lic.), is recommended for approval .

Signature of the Inspecting Officer

Name: - Ravinder Singh  
Designation: - ADO (CC)



D of (C)