GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2021/ 375

Dated:

9/9/21

FIRE SAFETY CERTIFICATE

Bagh, New Delhi- 110005 was granted FSC for building comprised of basement, ground plus three upper floors, using basement as hall/storage, ground floor as reception & 01 guest room, first, second & third floor each having 06 guest rooms respectively (total 19 guest rooms) and a pantry with staff room on terrace, by this department vide letter No. F6/DFS/MS/GH/SZ/2018/1627 dated 13.07.2018. The premises was re-inspected by the officer concerned of this department on 03.09.2021 in presence of Sh. Siddharth Kohli, owner of the guest house, and found that the guest house have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) for basement (incidental storage), ground floor (reception & 01 guest room), first, second and third floor each having 06 guest rooms respectively (total 19 guest rooms only) with effect from 9/9/2/2/1 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed back side.

Issued on $\frac{9/9}{2}$ at New Delhi by.

(Sunil Chaudhary)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service

Copy to:-

- 1. The Owner/Occupier, M/s. Hotel Crown Deluxe, A/87, WEA, Channa Market, Karol Bagh, New Delhi- 110005.
- 2. The Joint C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.

Following Fire Safety Directives must be adhered to: -

A surrent 1

- 1. The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/359-374 dated 29.06.2021 in respect of existing building (copy enclosed) shall be implemented by 30.09.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void
- 2. No occupancy above third floor & basement as storage purpose, shall be adhered by Owner/Occupier
- 3. All the means of escape shall be kept free of all type of obstruction all the time.
- 4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 6. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 7. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 8. All comments / directions of licensing department shall always be permitted and followed.
- 9. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 10. The owner / occupier shall apply for renewal of this **Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37)** along with copy of the certificate, six months prior to its expiry.
- 11. Basement shall be used as per BBL.
- 12. No temporary shed is allowed on terrace.
- 13. The Fire Safety Certificate is only for Guest Rooms.

1. Name & address of the building : M/s. Hotel Crown Deluxe, 8A/37, WEA, Channa

Market, Karol Bagh, New Delhi- 110005.

2. Type of Occupancy : Lodging House

3. Type of Case : Renewal

4. Details of previous NOC : F6/DFS/MS/GH/SZ/2018/1627 dated 13.07.2018

5. Fire Safety directives letter No : Nil

6. Date of inspection : 03.09.2021

7. Name of the Inspecting Officers : P.V. Rathee, Asst. Divisional Officer (SRD)

8. Name and designation of officers from the building side

e : Sh. Siddharth Kohli, owner

9. Year of Construction : Before 2001

10. Applicant's letter No. : Online Application no. 2021080316721 dated 09.08.2021

The said guest house is comprised of basement, ground plus three upper floors.

S. No.		Minimum Standards on fire evention and fire safety U/R 33	Fire safety requirements as per FSC dt. 13.07.2018	Provided at site		Remarks MR/NMR	
The state of the s	Acce	Access to building					
	0	Road width	06 mts	Provided		MR	
	9	Gate width	4.5 mts	Directly access	ible M	R being old case	
		Width of internal road	N/A	N/A		N/A	
2	Num	mber, Width, Type & Arrangement of Exits					
	a. Nu	mber of staircases	- Maria	. Ak	and the same of th		
		Upper Floors	Old Case	01	MR being old case MR being old case		
			Old Case	01			
	b. W	dth of staircases	_	and .		PAGE .	
	*	Upper Floors	Old case	1.12 mts	MR.b	eing old case	
		Basements	Old case	1.40 mts		eing old case	
	o Dr	otection of exits	nha	Tree .		-	
		Fire check door	Required	Not Provided	date of compliance has bee extended up to 30.09.202		
			N/A	N/A		N/A	
		of continuous staircases to terrace	01	01		MR	
		dth of Corridor	Old case	1.10 mts		MR	
		or Size	Old case	0.85 mts	MR being old case		
3		partmentation.					
	0	Fire check door	Required	Not Provided	date of compliance has been extended up to 30.09.2021 N/A N/A N/A		
	0	Sealing of electrical shafts	N/A	Sealed			
	0	Fire Rating of shaft door	N/A	N/A			
	0	Water Curtain	N/A	N/A			
	0	Fire Dampers	N/A	N/A			
1	Smol	ke Management System.	<u></u>		, ' · ·		
	0	Basements	30 a/c per hour	Exhaust fan prov	date of compliance has been extended up to 30.09.2021		
		Upper floors	12 a/c per hour	Not Provided			
5	Fire	Extinguishers			Oxtended up to 50.07.2021		
	9	Total numbers	15	Provide	ed MR		
		Types	CO ₂ , ABC, WCO ₂	Provide	ed	MR	
		10	ISI marked	Provide	ed	MR	

		 Total numbers on each floor 	01	Provided		MR		
		• Length of hose reel hose	30 m	Provided		MR		
		Nozzle diameter	5 mm	Provided		MR		
	7	Automatic fire detection and alarming system.						
	,		Carbon Monoxide	Not Provided extend		compliance has been ed up to 30.09.2021		
		 Location of Main Panel 	Required	Not Provided		compliance has been ed up to 30.09.2021		
		Location of Repeater Panel	N/A	N/A		N/A		
-		Alternate source of power	Required	D.G. set 11 KVA		MR		
		Hooters' Location	N/A	N/A		N/A		
-	8	MOEFA	Required	Provided		MR		
-	9	Public Address System.	Required	Provided		MR		
-	10	Automatic Sprinkler System.						
		Basement	N/A	Provided	Area les	s than 200 Sq. Mtr		
		• Upper Floor	N/A	N/A		N/A		
		Sprinkler above false ceiling	N/A	N/A		N/A		
	1 1	Internal Hydrants						
		Size of riser/down-comer	N/A	N/A		N/A		
		 Number of hydrants per floor 	N/A	N/A		N/A		
		 Hose Box 	N/A	N/A		N/A		
	12	Yard Hydrants.				27/4		
		Total number of hydrants	N/A	N/A		N/A N/A		
		Hose Box	N/A	N/A		IN/A		
	13	Pumping Arrangements.						
		 Ground Level 	ONE WAS NOW	100 100 MM		400 MM PO		
		Discharge of main Pump	N/A	N/A		N/A		
		Head of Main pump	N/A	N/A		N/A		
		Number of main pumps	N/A	N/A		N/A		
-		Jockey Pump out put	N/A	N/A		N/A		
		Jockey pump head	N/A	N/A	,	N/A		
AND DESCRIPTION OF THE PERSON OF		Standby Pump out put	N/A	N/A		N/A		
		> Standby Pump Head	N/A	N/A		N/A		
		Auto Starting/ Manual stopping	ng N/A	N/A	, 18	N/A		
		Pump House Access	N/A	N/A		N/A		
		Terrace level	SUCCESS AND SUB-SUB-SUB-SUB-SUB-SUB-SUB-SUB-SUB-SUB-	note that the was not the		any tipe you see him top the tip.		
		Discharge of pump	450 LPN			MR		
		> Head of the pump	30 mts	Provide	d	MR		
		Power Supply	Require	d Provide	ed	MR		
		> Auto Starting of pump	Require	d Provide	ed	MR		
	14	Captive Water Storage for fire fightin	g.					
		 Underground tank capacity 	N/A	N/A		N/A		
		> Draw-off connection	N/A	N/A		N/A		
		Fire service inlet	N/A	N/A	· ·	N/A		
		Access to tank	N/A	N/A		N/A		
		Overhead Tank capacity	Old case	3000 lts		MR, Old case		
	15	Exit Signage. Required Provided MR						
	16	Provision of Lifts. Pressurization of Lift Shaft N/A N/A N/A						
	1	 Pressurization of Lift Shaft 	N/A	IV/A	17740 117	LVIIX		

		M37			
	9	Communication In lift Car	N/A	N/A	N/A
	-	Fireman's Grounding Switch	N/A	N/A	N/A
		Lift Signage	N/A	N/A	N/A
17	Stan	dby power supply	Required	Provided	MR
18 Refuge Area.					Х
	>	Total Area	N/A	N/A	N/A
	7	Location	N/A	N/A	N/A
19 Fire Control Room					
		Detector System Panel	N/A	N/A	N/A
		Flow Switch Panel	N/A	N/A	N/A
		 PA System Panel 	N/A	N/A	N/A
		Battery backup	Required	Provided	MR
		Building Floor Plans	N/A	N/A	N/A
20	1	ial Fire Protection Systems for ection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were checked and found functional at the time of inspection.

The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter-7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/359-374 dated 29.06.2021 in respect of existing building (copy enclosed) shall be implemented by 30.09.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/DFS/MS/GH/SZ/2018/1627 dated 13.07.2018, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer P.V. Rathee

Asstt. Div. Officer (SRD)

Dy ero 1/23

ADD BANJ