GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2021/ 3 8 6

Dated:/.4/.9../2021

FIRE SAFETY CERTIFICATE

Certified that the Avtar Guest House located at 3425, D.B.G. Road, Pahar Ganj, New Delhi comprised of Ground + Mezzanine + 03 Upper floors, Ground floor (Reception + Office), Mezzanine floor (06 guest rooms + 01 office + store), 1st floor & 2nd floor (11 guest rooms at each floor), 3rd floor (10 guest rooms) and Terrace floor found sealed, total 38 guest rooms owned/occupied by Avtar Guest House was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/NDZ/2018/2081 dated 12/09/18. Now, the premise was re-inspected by the officer concerned of this department on 06/09/2021 in the presence of Sh. Vivek Juneja and found that the said guest house building having given affidavit dated 07.09.2021, regarding not to use third floor (as mezzanine floor count as first floor) has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (Reception + Office) (mezzanine) (06 guest rooms + 01 office + store), 1st floor (11 guest room) & second floor (10 guest rooms), total 27 guest only with effect from for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 1-9-1-at New Delhi by.

(Dr. S.K. Tomar) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Commissioner of North, MCD, Civic Centre, New Delhi: to ensure the occupancy in the building.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi Online id no.2021081517782 dated 15.08.2021
- 3. The Manager,

Avtar Guest House 3425, D.B.G. Road, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- 1. This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 29.06.2021 latest by 30.09.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

NK 7 **INSPECTION REPORT** 1. Name & address of the building Avtar Guest House at 3425, D.B.G. Road, Pahar Ganj, New Delhi Residential, Sub Division-A-1 2. Type of occupancy:-Gr. + Mezzanine + 03 Upper floors (total 27 Guest rooms) Ground floor (Reception + Office), Mezzanine floor (06 guest rooms + 01 office + store), 1st floor (11 guest room), 2nd floor (10 guest rooms at each floor), 3rd floor (not in use) having given affidavit dated 07.09.2021, regarding not to third floor 3. Type of case:-Renewal 4. Details of previous FSC:-No. F6/DFS/MS/GH/NDZ/2018/2081 dated 12/09/18. 5. Fire safety directives No.-N/A 6. Date of inspection:-06/09/21 7. Name of the inspecting officer:-Sh. Ravinder Singh(ADO/CC) 8. Name & designation of officer From the building side:-Sh. Vivek Juneja 9. Year of construction:-10. Applicant's letter No:-Online id no.2021081517782 dated 15.08.2021 Old Case Minimum Standards on fire S.No Requirement/ Provided at Remarks Prevention and fire safety U/R 33 Existing fire site MR/NMR safety arrangements 1. Access to Building

| | 1) Road width | N/A | More than 18 | MR |
|-----|---------------------------------|---------------|--------------|-------------------|
| | | | mtr. | |
| | 2) Gate width | N/A | N/A | N/A |
| | 3)Width of internal road | N/A | N/A | N/A |
| 2. | Number, Width Type & Arrange | | | |
| | A. Number of staircases | | | |
| | 1. Upper floors | 01 Nos. | 01 Nos. | MR |
| | 2. Basements | N/A | N/A | N/A |
| | B. Width of staircase | | | 9 |
| | 1. Upper floors | 0.80 mtr. | 1.20 mtr. | MR |
| | 2. Basements | N/A | N/A | N/A |
| | C. Protection of exits | | | |
| | 1. Fire check door | Required as | Not provided | Last dt. 30.09.21 |
| | | per G.N dated | | of compliance |
| | | 27.05.19 | | extended vide |
| | | | | order dt. |
| | | | | 29.06.21 |
| | 2. Pressurization | N/A | N/A | N/A |
| 1 . | D. No. of continuous | N/A | N/A | N/A |
| | staircase to terrace | | 1 | |
| 1 | E. Width of corridor | N/A | N/A | N/A |
| | F. Door size | 1.0 mtr. | 1.0 mtr. | MR |
| 3. | Compartmentation | | | |
| | 1) Fire check door | N/A | N/A | N/A |
| | 2) Sealing of electrical shafts | N/A | N/A | N/A |
| | 3) Fire rating of shaft door | N/A | N/A | N/A |
| | 4) Water curtain | N/A | N/A | N/A |
| | 5) Fire Dampers | N/A | N/A | N/A |
| 4. | Smoke Management System | | | |
| | 1) Basements | 30 ACPH | N/A | N/A |

| | 2) Upper floors | Required as per G.N dated 27.05.19 | Not provided | Last dt. 3—99.21 of compliance extended vide order dt. 29.06.21 |
|-----|----------------------------------|------------------------------------|--------------|--|
| 5. | Fire Extinguishers | | | |
| | 1) Total numbers | 10 Nos. | 10 Nos. | MR |
| | 2) Types | ABC & CO2 | ABC & CO2 | MR |
| | 3) ISI marking | Required | Provided | MR |
| 6. | First-Aid Hose Reel | | IVIK | |
| | 1) Total number of each floor | 01 | 01 | MR |
| | 2) Length of hose reel hose | 30 mtr. | 30 mtr. | MR |
| | 3) Nozzle diameter | 05 mm | 05 mm | MR |
| 7. | Automatic Fire Detection & Ala | 7 - 7 - 7 - | | |
| | 1) Type of detectors Co Type | Required as per G.N dated 27.05.19 | Not provided | Last dt. 30.09.21 of compliance extended vide order dt. 29.06.2021 |
| | 2) Location of main panel | N/A | N/A | N/A |
| | 3) Location of repeater panel | N/A | N/A | N/A |
| | 4) Alternate source of power | N/A | N/A | N/A |
| | 5) Hooter's Location | N/A | N/A | N/A |
| 8. | MOEFA | Required | Provided | MR |
| 9. | Public Address System | Required | Provided | MR |
| 10 | Automatic Sprinkler System | | | |
| • | 1) Basement | 127/4 | | |
| | 2) Upper floors | N/A | N/A | N/A |
| | 3) Sprinkler above false ceiling | N/A N/A | N/A | N/A |
| 11 | Internal Hydrants | IN/A | N/A | N/A |
| • | 1) Size of riser/down-comer | N/A | NI/A | |
| | 2) Number of hydrants per floor | N/A N/A | N/A | N/A |
| | 3) Hose box | N/A | N/A N/A | N/A |
| 12 | Yard Hydrants | IV/A | N/A | |
| | 1) Total number of hydrants | N/A | N/A | N/A |
| | 2) Hose box | N/A | N/A | N/A |
| 13. | Pumping Arrangement | | | IVA |
| | 1) Ground level | N/A | N/A | N/A |
| | a) Discharge of main pump | N/A | N/A | N/A |
| | b) Head of main pump | N/A | N/A | N/A N/A |
| | c) Number of main pump | N/A | N/A | N/A |
| | d) Jockey pump out put | N/A | N/A | N/A |
| | e) Jockey pump head | N/A | N/A | N/A |
| | f) Stand by pump output | N/A | N/A | N/A |
| | g) Stand by pump head | N/A | N/A | N/A |
| | in) Auto starting/Manual | N/A | N/A | N/A |
| | | | | |
| | Terrace level Discharge of pump | | | |

| | | 191 | | |
|-----|-------------------------------------|----------------|---------------------|-----|
| | b) Head of pump | 30 mtr. | 30 mtr. | MR |
| | c) Power supply | Required | Provided | MR |
| | d) Auto starting of pump | Required | Provided | MR |
| 14. | Captive Water Storage for Fi | re Fighting | | |
| | Under ground tank capacity | N/A | N/A | N/A |
| | a) Draw-off connection | N/A | N/A | N/A |
| | b) Fire service inlet | N/A | N/A | N/A |
| | c) Access to tank | N/A | N/A | N/A |
| | d) Over head tank capacity | 2,500 ltr. | 2,500 ltr. | MR |
| 15. | Exit Signage. | Required | Provided | MR |
| 16. | Provision of Lifts. | | | |
| | a) Pressurization of lift shaft | N/A | N/A | N/A |
| | b) Pressurization of lift lobby | N/A | N/A | N/A |
| | c) Communication in lift car | N/A | N/A | N/A |
| | d) Fireman's switch | N/A | N/A | N/A |
| | e) Lift signage | N/A | N/A | N/A |
| 17. | Stand by Power Supply | Required | Provided | MR |
| 18. | Refuge Area | N/A | N/A | N/A |
| | Total area location | N/A | N/A | N/A |
| 19. | Fire Control Room | N/A | N/A | N/A |
| | a) Detector system panel | N/A | N/A | N/A |
| | b) Flow switch panel | N/A | N/A | N/A |
| | c) PA system panel | N/A | N/A | N/A |
| | d) Battery backup | N/A | N/A | N/A |
| | e) Building floor plan | N/A | N/A | N/A |
| 20. | Special Fire Protection System any: | for Protection | of special Risk, if | N/A |
| | | | | |

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2018/2081 dated 12/09/18, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to second floor.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

1. F. G. pl. 2. pl. correct numbering a noting pact