GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/GH/2021/SZ/ 383

Dated: 1.4/...\$./2021

FIRE SAFETY CERTIFICATE

Certified that Hotel Meridian Plaza located at R-41, R Block, Greater Kailash-I, New Delhi 110048 comprised of Basement, ground plus three upper floors, but guest house is running at ground plus three upper floors (28 guest room) was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/GH/2018/SZ/2335 dated 16/10/2018. The premise was re-inspected by the officer concerned of this department on 26/08/2021 in the presence of Mr. Gajender Singh (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential, Group-A" (Guest House) as above with effect from \(\frac{\psi}{2} \) / \(\frac{9}{2} \) /2021 for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued on 14/9 /2021 at New Delhi by

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER (SZ) DELHI FIRE SERVICE

Copy to: -

1. The Manager, Meridian Plaza located at R-41, R-Block, Greater Kailash-I, New Delhi-110048

2. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi–110049 (Ref. MHA Portal No 202030503390 dated 31/03/2021)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting system.

- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."
- 7. The provision's under clause 7.31 of UBBL-2016 shall be done in the building on or **before** 30/09/2021 in compliance to the notification dated 27/05/2019 an as approved and now have been extended till 30/09/2021 vide Directorate of Local Bodies, UDD, GNCT of Delhi letter no. F5 (189)/AD/LB/2016/359-374 dated 29.06.2021.

	INSPECTION	ON REPORT				
1	Name & Address of the Building	M/s Meridian Plaza Situated at R-41, Greater				
		Kailash-1, New Delhi 110048				
2	Type of Occupancy	Residential, "Group-A" (Guest House)				
3	Building Comprised of	Basement (Vacant), Ground + 03 upper floors				
4	Type of Case	Renewal	X			
5	Details of Previous NOC	F6/DFS/MS/GH	/2018/SZ/2335 date	ed 16/10/2018		
6	Fire Safety Directives Letter No	NBC Part IV				
7	Date of Inspection	26/08/2021				
8	Name of the Inspecting Officers	Sh. Rajesh Kum	ar ADO (BCP)	,		
9	Name & Designation of Officers	Mr. Gajender Singh (Manager)				
****	from the building side					
10	Year of construction		28 Guest room			
11	Applicant letter No.	Online ID No 202030503390 dated 31/03/2021				
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC Provided at Site requirements		te Remarks MR/NMR		
1	Access to Building.					
	Road width	Required	09 mtr	MR		
	Gate width	-NA-	-NA-	-NA-		
	Width of internal road	-NA-	-NA-	-NA-		
2	Number, width, type & arrangement of exits.	Assessment of the second of th				
	a) Number of Staircase		31			
	Upper floors.	Required	02 Nos	MR		
	Basement floor.	Required	02 Nos	MR		
	b) Width of Staircase					
	▶ Upper floors	1.25 m & 0.90 MR		MR		
	Basement floor	1.25 mtr	m (low occupancy lo height increasing 15 as per UBBL)			
		1.25 mtr	1.25 m & 0.90 m	MR (old case)		
	c) Protection of exits					
	Fire check door	-NA-	-NA-	-NA-		
	> Pressurization	-NA-	-NA-	-NA-		
	d) No. of continuous staircase to terrace	Required	One	MR		
	e) Width of corridor	-NA-	-NA-	-NA-		
	f) Door size	1m				
3	Compartmentation.	1111	m 1 m (final exit) MR			
	Fire check door.	-NA-	-NA-	-NA-		
	Sealing of electrical shafts.	-NA-	-NA-	-NA-		
	Fire rating of shaft door.	-NA-	-NA-	-NA-		
	Water curtain	-NA-	-NA-	-NA-		
	Fire dampers.	-NA-	-NA-	-NA-		
4	Smoke Management system.	11.1	1471	-1471		
	Basement	30 ACPH	Exhaust fan Prov	vided MR		
	Upper floors	12 ACPH	Natural ventilat			
5		12 ACFII	ivaturai ventilat	tion MR		
3	Fire Extinguishers.	10 37	D 114	1		
	Total numbers	10 Nos	Provided	MR		
	• Types	ABC / CO2	ABC & CO2			
	ISI Marking First Aid Hose Pools	ISI marked	Provided	MR		
6	First Aid Hose Reels.		T			
	 Total numbers on each floor. 	0	D '1 1	MD		
	Length of hose-reel hose.	One	Provided	MR		

1 . 1

	Nozzle Diameter	5 mm	Provided	MR
7	Automatic fire detection & alarming system.		06/2021 amendment / mo	
	The second of th	(UBBL-2016 till 30		
	Type of detectors	-NA-	-NA-	-NA-
	 Location of Main Panel 	-NA-	-NA-	-NA-
	 Location of Repeater Panel 	-NA-	-NA-	-NA-
	 Alternate source of power 	-NA-	-NA-	-NA-
	Hooter's location	-NA-	-NA-	-NA-
8	MOEFA	Required	Provided	MR
9	Public Address System	Required	Provided	MR
10	Automatic Sprinkler System			
	Basement	Required	Provided	MR
	 Upper floors. 	-NA-	-NA-	-NA-
	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11	Internal Hydrants.			
	Size of Riser/Down-comer	Required	Provided	MR
	 Number of Hydrant per floor 	01	Provided	MR
	Hose box.	01	Provided	MR
12	Yard Hydrants.			
	Total number of hydrants.	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
13	Pumping arrangements.			1111
10	Ground Level			
-	Discharge of main pump.	-NA-	-NA-	-NA-
	Head of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	Jockey Pump output.	-NA-	-NA-	-NA-
	Jockey Pump head.	-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	-NA-
	Standby Pump head.	-NA-	-NA-	-NA-
	Auto Starting/Manual Stopping.	-NA-	-NA-	-NA-
	Pump house access.	-NA-	-NA-	-NA-
	Terrace Level		, 1,1	
	Discharge of pump.	450 & 180 LPM	Provided	MR
	Head of pump.	35 m	Provided	MR
	Power supply.	Provided	Provided	MR
	Auto starting of pump.	Provided	Provided	MR
14	Captive water storage for fire fighting.			
	Underground tank capacity.	-NA-	NA	-NA-
	Draw-off connection.	-NA-	-NA-	-NA-
The state of the s	Fire Service Inlet.	Provided	Provided	Provide
Annie despresso esta	Access to tank.	-NA-	-NA-	-NA-
	 Overhead tank capacity. 	5,000 ltrs	10,000 ltrs	MR
15	Exit Signage.	Required	Provided	MR
	Provision of Lifts.	Kedanea	TOVIUCU	1711
10	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	 Pressurization of lift lobby. 	-NA-	-NA-	-NA-
	Communication in lift car.	-NA-	-NA-	-NA-
	wat a tild	-NA-	-NA-	-NA-
A Allega		-NA-	-NA-	-NA-
177	Lift signage. Standby Parent Supply			
	Standby Power Supply	Required	Provided (DG Set)	MR
18	Refuge Area	NTA I	NTA	TA.T.A.
	Total area	-NA-	-NA-	-NA-

	Location	-NA-	-NA-	-NA-
19	Fire Control Room.			
	Detector system panel.	-NA-	-NA-	-NA-
	Flow switch panel.	-NA-	-NA-	-NA-
	PA system panel.	-NA-	-NA-	-NA-
	Battery backup.	-NA-	-NA-	-NA-
	Building floor plan.	-NA-	-NA-	-NA-
20	Special Fire Protection System for the Protection of special Risk, if any.			-NA-

The fire protection system provided in the premises were checked, tested at random and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 262 dated 27/11/2020

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F6/DFS/MS/GH/2018/SZ/2235 dated 16/10/2018, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer
Name: - Rajesh Kumar
Designation: - ADO/BCP

DO (8D)

21 P 9/109/21 X.7

HOUBLA

As approved F-

tetter en

protrip

101912021

Dechy 1

M.5, Ql.