

C-27

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6/DFS/MS/2021/EH/WZ/ 226

Dated 13/9/21

FIRE SAFETY CERTIFICATE

Certified that the M/s Chill House Restaurant (A unit of Champion Restro Pvt. Ltd.) Shop No.B-309, North Ex-Shopping Mall, Sector-9, Rohini, Delhi-110085 is running at 3rd floor in building comprised of Basement + Ground + 3 upper floors owned/ occupied by M/s Chill House Restaurant was granted NOC by this department vide letter no. F.6/MS/DFS/2008/EH/3261 dated 26.11.2008. The premises was re-inspected by the officers concerned of this department on 16.08.2021 in the presence of Mr. Rohit Chhabra (Manager) and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules,2010. Hence the NOC is renewed and premises is fit for occupancy Group D "Assembly"(Eating House) for Shop No. B-309, 3rd floor only with effect from - 13/9/21 for a period of 03 (Three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 13/9/21 at New Delhi by

(Dhrampal Bhardwaj)
Dy.Chief Fire Officer
Tel:-01123412050

Copy to:-

1. The Dy. Health Officer, North MCD, Sec-5, Rohini Zone, Delhi-110085.
 2. Mr. Rohit Chhabra (Manager), M/s Chill House Restaurant (A unit of Champion Restro Pvt. Ltd.) Shop No.B-309, North Ex-Shopping Mall, Sector-9, Rohini, Delhi-85.
- Conditions for the validity of Fire Safety Certificate:**
1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
 3. The trained fire fighting staff should be available round the clock.
 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/
http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

INSPECTION REPORT

1. Name & address of the building : M/s Chill House Restaurant (A unit of Champion Restro Pvt. Ltd.)
Shop No.B-309, North Ex-Shopping Mall, Sector-9, Rohini, Delhi-85. (Restaurant is running at Shop No. B-309) at 3rd floor)
2. Type of Occupancy : Group D Assembly Building (Eating House)
3. Type of Case : F.6/MS/DFS/2008/EH/3261 dated 26.11.2008
4. Details of Previous NOC : NA
5. Fire Safety directives letter No : NA
6. Date of inspection : 16.08.2021
7. Name of Inspecting Officer : A.K. Sharma ADO (Rohini)
8. Name and designation of officers
From the building side : Mr. Rohit Chhabra (Manager)
9. Year of Construction :
10. Applicant's letter No. : Online application no.20210714151832 dated 27.07.2021

| S. No. | Minimum Standards on fire prevention and fire safety U/R 33 | Rule 35(6) | Provided at site | Remarks MR/NMR |
|--------|---|--|--------------------|----------------|
| 1. | Access to building [North Ex Mall issued FSC vide letter No.F.6/DFS/MS/WZ/2020/296 dated 05.08.2020] | | | |
| | <ul style="list-style-type: none"> • Road width • Gate width • Width of internal road | Restaurant within Mall | As Above | MR |
| 2. | Number, Width, Type & Arrangement of Exits [Provided & Maintained by Mall management] | | | |
| | a. Number of staircases | | | |
| | <ul style="list-style-type: none"> • Upper Floors • Basements | Restaurant within Mall | As Above | NA |
| | | Restaurant within Mall | As Above | NA |
| | b. Width of staircases | | | |
| | <ul style="list-style-type: none"> • Upper Floor • Basement | Restaurant within Mall | As Above | NA |
| | | Restaurant within Mall | As Above | NA |
| | c. Protection of exits | | | |
| | <ul style="list-style-type: none"> • Fire check door • Pressurization | Restaurant within Mall | As Above | NA |
| | | Restaurant within Mall | As Above | NA |
| | d. No. of continuous staircases to terrace | Restaurant within Mall | As Above | NA |
| | e. Width of Corridor | Restaurant within Mall | As Above | NA |
| | f. Door Size | 2 exit | 1.9 & 1.10 mtr | MR(Old case) |
| 3. | Compartmentation | | | |
| | <ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Water Curtain • Fire Dampers | Restaurant within Mall | As Above | NA |
| | | Restaurant within Mall | As Above | NA |
| | | Restaurant within Mall | As Above | NA |
| | | Restaurant within Mall | As Above | NA |
| | | Restaurant within Mall | As Above | NA |
| 4. | Smoke Management System [Provided & Maintained by Mall management] | | | |
| | <ul style="list-style-type: none"> • Basements • Upper floors | 30 ACPH | NA | NA |
| | | 12 ACPH | Natural Ventilated | MR |
| 5. | Fire Extinguishers | | | |
| | <ul style="list-style-type: none"> • Total numbers • Types • IS marking | 6 No's | 6Nos | MR |
| | | ABC/CO ₂ /W.CO ₂ | 6No's | MR |
| | | ISI marked | Provided | MR |
| 6. | First-Aid Hose Reels [Provided & Maintained by Mall management] | | | |
| | <ul style="list-style-type: none"> • Total numbers on each floor • Length of hose reel hose • Nozzle diameter | One (Near to Restaurant) | As Above | MR |
| | | 30 m | As Above | MR |
| | | 5 mm | As Above | MR |
| 7. | Automatic fire detection and alarming system [Provided & Maintained by Mall management] | | | |

| | | | | |
|-----|---|--|----------|----|
| | <ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location | Required | Provided | MR |
| | | NA | As Above | NA |
| | | NA | As Above | NA |
| | | NA | As Above | NA |
| | | NA | As Above | NA |
| 8. | MOEFA | Required | Provided | MR |
| 9. | Public Address System | NA | As Above | NA |
| 10. | Automatic Sprinkler System[Provided & Maintained by Mall management] | | | |
| | <ul style="list-style-type: none"> Basement | NA | As Above | NA |
| | <ul style="list-style-type: none"> Ground Floor | NA | As Above | NA |
| | <ul style="list-style-type: none"> Sprinkler above false ceiling | NA | As Above | NA |
| 11. | Internal Hydrants[Provided & Maintained by Mall management] | | | |
| | <ul style="list-style-type: none"> Size of riser/down-comer | 100mm | As Above | MR |
| | <ul style="list-style-type: none"> Number of hydrants per floor | One (near to Restaurant) | As Above | MR |
| | <ul style="list-style-type: none"> Hose Box | One (near to Restaurant) | As Above | MR |
| 12. | Yard Hydrants[Provided & Maintained by Mall management] | | | |
| | <ul style="list-style-type: none"> Total number of hydrants | NA | NA | NA |
| | <ul style="list-style-type: none"> Hose Box | NA | NA | NA |
| 13. | Pumping Arrangements[Provided & Maintained by Mall management] | | | |
| | <ul style="list-style-type: none"> Ground Level | | | |
| | <ul style="list-style-type: none"> ➤ Discharge of main Pump | NA | NA | NA |
| | <ul style="list-style-type: none"> ➤ Head of Main pump | NA | NA | NA |
| | <ul style="list-style-type: none"> ➤ Number of main pumps | NA | NA | NA |
| | <ul style="list-style-type: none"> ➤ Jockey Pump out put | NA | NA | NA |
| | <ul style="list-style-type: none"> ➤ Jockey pump head | NA | NA | NA |
| | <ul style="list-style-type: none"> ➤ Standby Pump out put | NA | NA | NA |
| | <ul style="list-style-type: none"> ➤ Standby Pump Head | NA | NA | NA |
| | <ul style="list-style-type: none"> ➤ Auto Starting/Manual Stopping | NA | NA | NA |
| | <ul style="list-style-type: none"> ➤ Pump House Access | NA | NA | NA |
| | <ul style="list-style-type: none"> Terrace level | [Provided & Maintained by Mall management] | | |
| | <ul style="list-style-type: none"> ➤ Discharge of pump | NA | As Above | MR |
| | <ul style="list-style-type: none"> ➤ Head of the pump | NA | As Above | MR |
| | <ul style="list-style-type: none"> ➤ Power Supply | Required | As Above | MR |
| | <ul style="list-style-type: none"> ➤ Auto Starting of pump | Required | As Above | MR |
| 14. | Captive Water Storage for firefighting[Provided & Maintained by Mall management] | | | |
| | <ul style="list-style-type: none"> Underground tank capacity | NA | As Above | NA |
| | <ul style="list-style-type: none"> ➤ Draw-off connection | NA | As Above | NA |
| | <ul style="list-style-type: none"> ➤ Fire service inlet | NA | As Above | NA |
| | <ul style="list-style-type: none"> ➤ Access to tank | NA | As Above | NA |
| | <ul style="list-style-type: none"> Overhead Tank capacity | NA | As Above | MR |
| 15. | Exit Signage. | Required | Provided | MR |
| 16. | Provision of Lifts.[Provided & Maintained by Mall management] | | | |
| | <ul style="list-style-type: none"> Pressurization of Lift Shaft | NA | NA | NA |
| | <ul style="list-style-type: none"> Pressurization of Lift lobby | NA | NA | NA |
| | <ul style="list-style-type: none"> Communication In lift Car | NA | NA | NA |
| | <ul style="list-style-type: none"> Fireman's Grounding Switch | NA | NA | NA |
| | <ul style="list-style-type: none"> Lift Signage | NA | NA | NA |
| 17. | Standby power supply | Required | As Above | MR |
| 18. | Refuge Area.[Provided & Maintained by Mall management] | | | |
| | <ul style="list-style-type: none"> ➤ Total Area | NA | NA | NA |

| | | | | |
|-----|--|----|----|----|
| | ➤ Location | NA | NA | NA |
| 19. | Fire Control Room [Provided & Maintained by Mall management] | | | |
| | • Detector System Panel | NA | NA | NA |
| | • Flow Switch Panel | NA | NA | NA |
| | • PA System Panel | NA | NA | NA |
| | • Batter backup | NA | NA | NA |
| | • Building Floor Plans | NA | NA | NA |
| 20. | Special Fire Protection System for Protection of special Risks, if any: | NA | NA | NA |

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/MS/DFS/2008/EH/3261 dated 26.11.2008 is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010.

Ajy
28/8/21

Signature of the Inspecting Officer
Name Ajay Kumar Sharma
Designation ADO (Rohini)

~~DO (NW)~~

Ajy
06/09/2021

~~Dy CPO (W2)~~

[Signature]
7/9/2021

~~ADO Rohini~~

FT letter is put up for kind perusal and signature please.

Ajy
9/9/21

~~Dy CPO (W2)~~

[Signature]
10/9/2021

MS/ call