

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2021/ 378

Dated: 13/9/21

FIRE SAFETY CERTIFICATE

Certified that M/s. Guest House South Indian located at 10211-16, Padam Singh Road, Karol Bagh, New Delhi- 110005 was granted FSC for building comprised of basement, ground plus four upper floors, using basement as hall/storage, ground floor as reception, office, shops & hall, first, second & third floor each having 10 guest rooms respectively (total 30 guest rooms) and fourth floor having 05 rooms for staff use with pantry, by this department vide letter No. F6/DFS/MS/GH/SZ/2018/1851 dated 08.08.2018. The premises was re-inspected by the officer concerned of this department on 02.09.2021 in presence of Sh. S. Murli Mani, owner of the guest house, and found that the guest house have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) for basement (storage), ground floor (reception & office), first, second and third floor each having 10 guest rooms respectively (total 30 guest rooms only) with effect from 12/9/21 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed back side.

Issued on 13 9 2 at New Delhi by.

(Sunil Chaudhary)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service

Copy to:-

- 1. Sh. S. Murli Mani, (Owner), M/s. Guest House South Indian, 10211-16, Padam Singh Road, Karol Bagh, New Delhi- 110005.
- 2. The Joint. C.P. (Lic.), Police Station Defence Colony, 1st floor, New Delhi.

Following Fire Safety Directives must be adhered to: -

- 1. The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/359-374 dated 29.06.2021 in respect of existing building (copy enclosed) shall be implemented by 30.09.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void
- 2. No occupancy above third floor & basement as storage purpose, shall be adhered by Owner/Occupier
- 3. All the means of escape shall be kept free of all type of obstruction all the time.
- 4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 6. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 7. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 8. All comments / directions of licensing department shall always be permitted and followed.
- 9. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 10. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- 11. Basement shall be used as per BBL.
- 12. No temporary shed is allowed on terrace.
- 13. The Fire Safety Certificate is only for Guest Rooms.

Aposko

1. Name & address of the building : M/s. Guest House South Indian, 10211-16, Padam Singh Road, Karol Bagh, New Delhi- 05.

2. Type of Occupancy : Lodging House

3. Type of Case : Renewal

4. Details of previous NOC : F6/DFS/MS/GH/SZ/2018/1851 dated 08.08.2018

5. Fire Safety directives letter No : Nil

6. Date of inspection : 02.09.2021

7. Name of the Inspecting Officers : P.V. Rathee, Asst. Divisional Officer (SRD)

8. Name and designation of officers from the building side : Sh. S. Murli Mani (owner)

9. Year of Construction : Before 1986

10. Applicant's letter No. : Online Application no. 2021081117517 dated 13.08.2021

The said guest house is comprised of basement, ground plus four upper floors.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Fire safety requirements as per FSC dt. 08.08.2018	1	site Remarks MR/NMR			
	Access to building						
	 Road width 	06 mts	Provided	MR			
	Gate width	4.5 mts	Directly accessib	ole MR			
	 Width of internal road 	N/A	N/A	N/A			
2	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases	-	V. S J. F.	m 10 3			
	• Upper Floors	02	02	MR			
	Basements	02	02	MR			
	b. Width of staircases	-	-				
	• Upper Floors	Old case	1.25, 1.18 mts	MR being old case			
	Basements	Old case	1.16, 1.10 mts	MR being old case			
	c. Protection of exits	_	- :				
	Fire check door	Required	Not Provided	date of compliance has bee extended up to 30.09.202			
	Pressurization	N/A	N/A				
	e. No. of continuous staircases to terrace	01	01				
	g. Width of Corridor	Old case	2.60, 2.10 mts	MR			
	h. Door Size	Old case	0.86 mts	MR being old case			
3	Compartmentation.						
	Fire check door	Required	Not Provided	date of compliance has been extended up to 30.09.2021 N/A N/A N/A			
	Sealing of electrical shafts	N/A	Sealed				
	 Fire Rating of shaft door 	N/A	N/A				
	Water Curtain	N/A	N/A				
	• Fire Dampers	N/A	N/A				
1	Smoke Management System.						
	Basements	30 a/c per hour	Exhaust fan provid				
	 Upper floors 	12 a/c per hour	Exhaust fan provid				
5	Fire Extinguishers						
	 Total numbers 	16	Provided	MR			
	• Types	CO ₂ , ABC, WCO ₂ ISI marked	Provided	MR			
	IS marking	151 marked	Provided	MR			

	 Length of nose reel nose 	30 III	Provided		MR	
	 Nozzle diameter 	5 mm	Provided		MR	
7	Automatic fire detection and alarming system.					
	Type of detectors	Carbon Monoxide	Not Provided		ompliance has been d up to 30.09.2021	
	 Location of Main Panel 	Required	Not Provided	rovided date of compliance has extended up to 30.09.2		
	Location of Repeater Panel	N/A	N/A		N/A	
	Alternate source of power	Required	D.G. set 82.5 KVA		MR	
	 Hooters' Location 	N/A	N/A		N/A	
8	MOEFA	Required	Provided	*		
9	Public Address System.	Required	Provided		MR	
10	Automatic Sprinkler System.					
	• Basement	Required	Provide	d	MR	
	Upper Floor	N/A	N/A		N/A	
	Sprinkler above false ceiling	N/A	N/A		N/A	
11	Internal Hydrants					
	Size of riser/down-comer	N/A	N/A		N/A	
	Number of hydrants per floor	N/A	N/A		N/A	
	Hose Box	N/A	N/A		N/A	
12	Yard Hydrants.					
	Total number of hydrants	N/A	N/A		N/A	
10	Hose Box	N/A	N/A		N/A	
13	Pumping Arrangements.					
	Ground Level	not use use			STOCKER AND	
	Discharge of main Pump	N/A	N/A		N/A	
90.	Head of Main pump	N/A	N/A		N/A	
	Number of main pumps	_N/A	N/A		N/A	
	Jockey Pump out put	N/A	N/A		N/A	
	Jockey pump head	N/A	N/A		N/A	
- 1	Standby Pump out put	N/A	N/A		N/A	
	> Standby Pump Head	N/A	N/A		N/A	
	Auto Starting/ Manual stoppin	g N/A	N/A		N/A	
	Pump House Access	N/A	N/A		N/A	
	Terrace level	NOT FOR NOW AND AND NOW	NOT NOT ANY PLOT THE TOTAL TOTAL TOTAL		DOD VALUE THAN THAN AND LAKE LAKE	
	Discharge of pump	450 LPM	Provided		MR	
	Head of the pump	30 mts	Provided	d	MR	
	Power Supply	Required	Provided	1	MR	
	Auto Starting of pump	Required	Provided	Tongood .	MR	
14	Captive Water Storage for fire fighting	Captive Water Storage for fire fighting.				
	Underground tank capacity	N/A	N/A		N/A	
	Draw-off connection	N/A	N/A		N/A	
	Fire service inlet	N/A	N/A		N/A	
	Access to tank	N/A	N/A		N/A	
	Overhead Tank capacity	10,000 lts	10,000 lts		MR, Old case	
15	Exit Signage.	Required	Provided		MR	

			1	NIYb	
	(9)	Pressurization of Lift Shaft	N/A	N/A	N/A
	0	Pressurization of Lift lobby	N/A	N/A	N/A
Í	*	Communication In lift Car	Required	Provided	MR
	. 🚳	Fireman's Grounding Switch	N/A	N/A	Old lift
WE CHANGE THE COMMAND OF T		Lift Signage	Required	Provided	MR
17	Sta	ndby power supply	Required	Provided	MR
18 Refuge Area.					
		Total Area	N/A	N/A	N/A
		Location	N/A	N/A	N/A
19	Fir	e Control Room	<u> </u>		
		Detector System Panel	N/A	N/A	N/A
		 Flow Switch Panel 	N/A	N/A	N/A
		 PA System Panel 	N/A	N/A	N/A
		Battery backup	Required	Provided	MR
		 Building Floor Plans 	N/A	N/A	N/A
20		cial Fire Protection Systems for tection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were checked and found functional at the time of inspection.

The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter-7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/359-374 dated 29.06.2021 in respect of existing building (copy enclosed) shall be implemented by 30.09.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/DFS/MS/GH/SZ/2018/1851 dated 08.08.2018, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer P.V. Rathee

Asstt. Div. Officer (SRD)

9/09/202)

fo ys 2

t. M

ADOSAN)