

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2021/ 4 co

Dated :2.1./. 9../2021

FIRE SAFETY CERTIFICATE

Certified that the City Place Guest House located at 12, Arakashan Road, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floor, Ground (Reception), 1st to 3rd floor (05 guest rooms at each floor) and 4th floor (04 guest rooms + 01 room used for staff), total 19 guest rooms owned/occupied by City Place Guest House Guest House was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/NDZ/2018/1926 dated 21/08/18. Now, The premises was re-inspected by the officer concerned of this department on 14/09/21 in the presence of Mr. Ashfak (Manager) and found that the said guest house building having given affidavit dated 27.09.2019, regarding not to use any floor above third floor has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1, Ground (Reception), 1st to 3rd floor (05 guest rooms at each floor) total 15 rooms only up to third floor only, with effect from21.1.3...................... for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued -- 21-191-21-- at New Delhi by.

(Dr. S.K. Tomar) Dy. Chief Fire Officer Delhi Fire Service

0210mg

Copy to:-

3. The Manager,

- 1. The Commissioner of North, MCD, Civic Centre, New Delhi. to ensure the occupancy in the building as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id no. 2021082018458 dated.24.08.21

City Place Guest House 12, Arakashan Road, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 29.06.2021 latest by 30.09.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.

		×1 8	, 4		
1, 30,40	INSP	ECTION REPOR	<u>T</u>		
1.	Name & address of the building	City Place G	uest House at 12, A	Arakashan	
		Road, Pahar	Ganj, New Delhi.		
2.	Type of Occupancy	Residential 1			
		Gr. + 04 Upper	floors (total 19 Gues	t rooms)	
		Ground (Recep	otion), 1 st to 3 rd floor (0	5 guest rooms at	
		each floor) and 4 th floor (04 guest rooms + 01 room used for staff) having given an affidavit dated			
		27.09.2019, regarding not to use any floor above			
		third floor.			
	Type of case:-	Renewal			
4.	Details of previous FSC:-		S/MS/GH/NDZ/201	8/1926 dated	
		21/08/18.			
	Fire safety directives No	N/A			
	Date of inspection:-	14/09/21			
7.	Name of the inspecting officer:	- Sh. Ravinde	r Singh (ADO/CC)		
0	0.11				
8.	Name & designation of officer	26 4 1 6 1			
0	from the building side:-	Mr. Ashfak	(Manager)		
	Year of construction:-	2007	001000010450 4-4-	124.00.21	
10. Applicant's letter No:- Online id no. 2021082018458 dated.24.08.21 Old Case					
S.No.	Minimum Standards on fire	Daguiroment	Provided at site	Remarks	
5.110.		Requirement Existing fire	Provided at site	MR/NMR	
	Prevention and fire safety U/R 33	safety		IVINIVIN	
	U/K 33	arrangements			
1.	Access to Building	arrangements			
1.		27/4	00	27/4	
	1) Road width	N/A	03 mtr.	N/A	
	2) Gate width	N/A	N/A	N/A	
	3) Width of internal road	N/A	N/A	N/A	
2	NY I XXI IAI ID O A	4 - CTD - 9	4		

S.No.	Minimum Standards on fire	Requirement	Provided at site	Remarks
5.140.	Prevention and fire safety	Existing fire	110 vided at Site	MR/NMR
	U/R 33	safety		WINGTHIN
	O/R 33	arrangements		
1.	Access to Building	on the second se		
	1) Road width	N/A	03 mtr.	N/A
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arr	angement of Ex	its	
	A. Number of staircases			
	1. Upper floors	01 Nos.	01 Nos.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	0.80 mtr.	0.92 mtr.	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits	4		
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous	N/A	N/A	N/A
	staircase to terrace	4		
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	01 mtr.	01 mtr.	MR
3.	Compartmentation			
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
	1) Basements	30 ACPH	N/A	N/A



M/38

	2) Upper floors	Required as	Not provided	Last dt.
	4	per G.N		30.09.2 f
		dated		compliance
		27.05.19		extended
				vide order dt.
				29.06.2021
5.	Fire Extinguishers			
	1) Total numbers	12 Nos.	12 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel			
	1) Total number of each	01	01	MR
	floor			
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection &			
	1) Type of detectors Co Type	Required	Provided	MR
	2) Location of main panel	Ground floor	Provided	MR
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	Required	Provided	MR
	5) Hooter's Location	Each floor	Provided	MR
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling	1071		1 1/12
11.	Internal Hydrants			
11.	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor	11/11		
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants	1472	1771	11/12
14.	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement	1071		
13.	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
		IV/A	IVA	11//1
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main	N/A	N/A	N/A
		1 1/ / 1	14/11	1 1/11
	d) Jockey pump out put	N/A	N/A	N/A
		N/A	N/A	N/A
	e) Jockey pump head		N/A	N/A
	f) Stand by pump	N/A	IN/A	IN/A
	output	NI/A	NI/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	IN/A
	stopping			



	2) Terrace level				
	a) Discharge of pump	225 LPM	225 LPM	MR	
		30 mtr.	30 mtr.	MR	
		Required	Provided	MR	
	, , , , , , , , , , , , , , , , , , , ,	Required	Provided	MR	
14.	Captive Water Storage for Fire Fighting				
	Under ground tank capacity	N/A	N/A	N/A	
	a) Draw-off connection	N/A	N/A	N/A	
	b) Fire service inlet	N/A	N/A	N/A	
	c) Access to tank	N/A	N/A	N/A	
	d) Over head tank capacity	2500 ltr.	2500 ltr.	MR	
15.	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts.				
	a) Pressurization of lift shaf	t N/A	N/A	N/A	
	b) Pressurization of lift lobby	N/A	N/A	N/A	
	c) Communication in lift ca	r N/A	N/A	N/A	
	d) Fireman's switch	N/A	N/A	N/A	
	e) Lift signage	N/A	N/A	N/A	
17.	Stand by Power Supply	Required	Provided	MR	
18.	Refuge Area	N/A	N/A	N/A	
	Total area location	N/A	N/A	N/A	
19.	Fire Control Room	N/A	N/A	N/A	
	a) Detector system panel	N/A	N/A	N/A	
	b) Flow switch panel	N/A	N/A	N/A	
	c) PA system panel	N/A	N/A	N/A	
	d) Battery backup	N/A	N/A	N/A	
	e) Building floor plan	N/A	N/A	N/A	
20.	Special Fire Protection System any:	for Protection	n of special Risk, if	N/A	

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

Shortcomings communicated vide letter No.F6/DFS/MS/GH/NDZ/2018/2524 dated 14/06/2018, has been rectified.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2018/1926 dated 21/08/18, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor.

Signature of the Inspecting Officer

Name: - Rayinder Singh

Designation: ADO (CC)

Service Service DoccD)

Chief Fire Of 157 21

F.A. pl.