## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2021/ 4 03

Dated: 22/9/21

## **FIRE SAFETY CERTIFICATE**

Certified that M/s. Hotel Good Times located at 8/7, WEA, Karol Bagh, New Delhi110005 was granted FSC for building comprised of basement, ground plus four upper floors, using basement as hall/storage, ground floor as reception, lobby & 06 guest rooms, first, second & third floor each having 09 guest rooms respectively (total 33 guest rooms) and a pantry for staff with office on fourth floor, by this department vide letter No. F.6/DFS/MS/GH/SZ/2018/1187 dated 23.05.2018. The premises was re-inspected by the officer concerned of this department on 15.09.2021 in presence of Sh. Suneet Sachdeva (Owner), and found that the guest house have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) for basement (incidental storage), ground floor (reception & 06 guest rooms) first, second and third floor each having 09 guest rooms respectively (total 33 guest rooms only) with effect from 22/9/21

for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed back side.

Issued on 22/3/21 at New Delhi by.

(Sunil Chaudhary)
Dy. Chief Fire Officer (SZ)
Occ Delhi Fire Service

Copy to:-

- 1. The Owner/Occupier, M/s. Hotel Good Times, 8/7, WEA, Karol Bagh, New Belhi- 110005.
- 2. The Joint. C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.

## Following Fire Safety Directives must be adhered to: -

- 1. The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/359-374 dated 29.06.2021 in respect of existing building (copy enclosed) shall be implemented by 30.09.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void
- 2. No occupancy above third floor & basement as storage purpose, shall be adhered by Owner/Occupier
- 3. All the means of escape shall be kept free of all type of obstruction all the time.
- 4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 6. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 7. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 8. All comments / directions of licensing department shall always be permitted and followed.
- 9. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 10. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- 11. Basement shall be used as per BBL.
- 12. No temporary shed is allowed on terrace.
- 13. The Fire Safety Certificate is only for Guest Rooms.

BOUSED

INSPECTION REPORT 1. Name & address of the building: : M/s Hotel Good Times, 8/7, WEA, Karol Bagh, New Delhi.

2. Type of Occupancy

: Lodging House

3. Type of Case

: Renewal

4. Details of previous NOC

: F.6/DFS/MS/GH/SZ/2018/1187 dated 23.05.2018

5. Fire Safety directives letter No : N/A.

6. Date of inspection

: 15.09.2021

7. Name of the Inspecting Officers: P.V. Rathee, Asst. Divisional Officer (SRD)

8. Name and designation of officers

from the building side

: Sh. Suneet Sachdeva, Owner

9. Year of Construction

: Before 2003

10. Applicant's letter No.

: Online Application no. 2021080617081 dated 13.08.2021

The said guest house is comprised of basement, ground plus four upper floors. Minimum Standards on fire Requirement as per

No.		revention and fire safety U/R 33	FSC dt 23.05.20	Provided at	t site MR/NMR		
1	Ac	Access to building					
		Road width	06 mts	Provided	MR		
		Gate width	4.5 mts	Directly acces	sible MR		
		<ul> <li>Width of internal road</li> </ul>	N/A	N/A	N/A		
2	Nu	mber, Width, Type & Arrangeme	nt of Exits				
	a. N	Number of staircases	-		_		
		Upper Floors	01	Provided(01)	MR		
		Basements	02	Provided(02)	MR		
	b. V	Width of staircases	-	-	_		
		Upper Floors	1.25 mts	1.32 mts.	MR		
		• Basements	Old Case	1.26mts, 0.75 mt.	MR being old case		
	c. F	Protection of exits			-		
		Fire check door	Required	Not Provided	date of compliance has been extended up to 30.09.2021		
		<ul> <li>Pressurization</li> </ul>	N/A	N/A	N/A		
		No. of continuous staircases to terrace	01	01	MR		
		Vidth of Corridor	Old Case	1.15 mts	MR being old case		
		Door Size	1.0 mt.	Provided (0.89 mt.)	MR being old case		
3	Cor	mpartmentation.					
		• Fire check door	Required	Not Provided	date of compliance has been extended up to 30.09.2021 N/A		
		• Sealing of electrical shafts	N/A	N/A			
		• Fire Rating of shaft door	N/A	N/A	N/A		
		Water Curtain	N/A	N/A	N/A		
		• Fire Dampers	N/A	N/A	N/A		
4	Sm	oke Management System.					

-	T	T	1	Exhaust fall I Tovided	IVIIC
		• Upper floors	12 a/c per hour	Exhaust fan Provided	MR
		• Basements	30 a/c per hour	Exhaust fan Provided	MR

Fire Extinguishers

	• I otal numbers	12	Provided	MR
1	• Types	CO <sub>2</sub> , ABC type	Provided	MR
	<ul> <li>IS marking</li> </ul>	ISI marked	Provided	MR

0	First-Aid Hose Reels.					
	Total numbers on each floor	01	Provided		MR	
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provided		MR	
	Nozzle diameter	5 mm	Provided		MR	
7	Automatic fire detection and alarming	system.				
	Type of detectors	Carbon Monoxide	Not Provided		of compliance has been inded up to 30.09.2021	
	Location of Main Panel	Required	Not Provided	date of c	f compliance has been added up to 30.09.2021	
	Location of Repeater Panel	N/A	N/A		N/A	
	Alternate source of power	Required	Provided		MR	
	Hooters' Location	N/A	N/A		N/A	
8	MOEFA	Required	Provided		MR	
9	Public Address System.	Required	Provided		MR	
10						
3	Basement	Required	Provided	<u>d</u>	MR	
	Upper Floor	N/A	N/A	7 9	N/A	
	Sprinkler above false ceiling	N/A	N/A		N/A	
11	Internal Hydrants					
	Size of riser/down-comer	N/A	N/A		N/A	
	<ul> <li>Number of hydrants per floor</li> </ul>	N/A	N/A		N/A	
	Hose Box	N/A	N/A		N/A	
12	Yard Hydrants.					
	<ul> <li>Total number of hydrants</li> </ul>	N/A	N/A		N/A	
	Hose Box	N/A	N/A		.N/A	
13	Pumping Arrangements.					
	Ground Level			15;		
	Discharge of main Pump	N/A	N/A		N/A	
	> Head of Main pump	N/A	N/A		N/A	
	Number of main pumps	N/A	N/A		N/A	
	> Jockey Pump out put	N/A	N/A		N/A	
1	Jockey pump head	N/A	N/A		N/A	
	> Standby Pump out put	N/A	N/A		N/A	
	> Standby Pump Head	N/A	N/A	j.	N/A	
	Auto Starting/ Manual stopping	N/A	N/A		N/A	
	Pump House Access	N/A	N/A		N/A	
	Terrace level					
	Discharge of pump	450 LPM	Provide	ed	MR	
	► Head of the pump	30 mts	Provide		MR	
	Power Supply	Required	Provide	ed	MR	
	Auto Starting of pump	Required	Provide	ed	MR	
14	Captive Water Storage for fire fighting.					
	Underground tank capacity	N/A	N/A		N/A	
	Draw-off connection	N/A	N/A		N/A	
-	Fire service inlet	N/A	N/A		N/A	
	Access to tank	N/A	N/A		N/A	
1 -	Overhead Tank capacity	5000 lts	Provided		MR	
15	Exit Signage.	Required	Provided		MR	
16	Provision of Lifts.					

			N-34			
	•	Pressurization of Lift Shaft	N/A	N/A	N/A	
	•	Pressurization of Lift lobby	N/A	N/A	N/A	
	•	Communication In lift Car	Required	Provided	MR	
	•	Fireman's Grounding Switch	Required	Provided	MR	
	•	Lift Signage	Required	Provided	MR	
17	Star	dby power supply	Required	Provided	MR	
18	Refu	uge Area.				
		Total Area	N/A	N/A	N/A	
		Location	N/A	N/A	N/A	
19	Fire	Control Room				
		Detector System Panel	N/A	N/A	N/A	
		Flow Switch Panel	N/A	N/A	N/A	
		PA System Panel	N/A	N/A	N/A	
		Battery backup	Required	Provided	MR	
		Building Floor Plans	N/A	N/A	N/A	
20	Spec	ial Fire Protection Systems for	Required	Two ABC type fire M		
	Prot	ection of special Risks, if any:		extinguisher found		

The fire protection systems provided in the building were checked and found functional at the time of inspection.

The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter-7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/359-374 dated 29.06.2021 in respect of existing building (copy enclosed) shall be implemented by 30.09.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/GH/SZ/2018/1187 dated 23.05.2018, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer P.V. Rathee

Asstt. Div. Officer (SRD)

17/09/2021

Dy ero (22)

F.t.

ADD SRN