

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001**

No. F.6/DFS/MS/SZ/2021/ 460

Dated 22/09/2021

FIRE SAFETY CERTIFICATE

Certified that M/s Musical Fountain, (Block-2 Building) at One Golden Mile Complex Netaji Nagar, New Delhi 110023 Comprised of ground plus one upper floor owned/Occupied by Applause Hospitality Services Pvt. Ltd., have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 13/09/2021 on in the presence of Sh. P.J Thareja (Owner) and found that the premise is fit for occupancy Group "D" Assembly Building with effect from the date of issue of this certificate for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010

Issued on 22 / 09 /2021 at New Delhi by


(ATUL GARG)
DIRECTOR

Copy to: -

1. M/s Musical Fountain, (Applause Hospitality Services Pvt. Ltd) Block-2 Building, One Golden Mile Complex Netaji Nagar, New Delhi 110023.

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire fighting system.
4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

INSPECTION REPORT

1	Name & Address of the Building	Musical Fountain, (Block-2 Building) One Golden Mile Complex Netaji Nagar, New Delhi 110023.		
2	Type of Occupancy	Assembly building Group D		
3	Building comprised of	Ground plus One upper floor		
4	Type of Case	New		
5	Details of Previous NOC	Nil		
6	Fire Safety Directives Letter No	F6/DFS/MS/2014/170 dated 16/06/2014		
7	Date of Inspection	13/09/2021		
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)		
9	Name & Designation of Officers from the building side	Sh. P.J Thareja (Owner)		
10	Year of construction	2014		
11	Applicant letter No.	Gmail dated 09/09/2021		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	NBC/ UBBL 2016	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	<ul style="list-style-type: none"> Road width Gate width Width of internal road 	06 m	12 m	MR
		05 m	06 m	MR
		NA	N/A	N/A
2	Number, width, type & arrangement of exits			
	a. Number of Staircase			
	<ul style="list-style-type: none"> Upper floors Basement floor 	02 No	02 Nos	MR
		-NA-	N/A	N/A
	b. Width of Staircase			
	<ul style="list-style-type: none"> Upper floors Basement floor 	1.20 mtr each	1.25 mtr each	MR
		-NA-	N/A	N/A
	c. Protection of exits			
	<ul style="list-style-type: none"> Fire check door Pressurization 	-NA-	N/A	N/A
		-NA-	N/A	N/A
	d. No. of continuous staircase to terrace	01	01	MR
	e. Width of corridor	N/A	N/A	N/A
	f. Door size	02 Exits	1.50 mtr each	MR
3	Compartmentation.			
	<ul style="list-style-type: none"> Fire check door. Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. 	-NA-	N/A	N/A
		-NA-	N/A	N/A
		-NA-	N/A	N/A
		-NA-	N/A	N/A
		-NA-	N/A	N/A
4	Smoke Management system.			
	<ul style="list-style-type: none"> Basement Upper floors 	-NA-	N/A	N/A
		Required	Natural ventilation	MR
5	Fire Extinguishers.			
	<ul style="list-style-type: none"> Total numbers Types ISI Marking 	Required	09 Nos	MR
		ABC / CO2	ABC & Co2	MR
		ISI marked	Provided	MR
6	First Aid Hose Reels.			
	<ul style="list-style-type: none"> Total numbers on each floor. Length of hose-reel hose. Nozzle Diameter 	One	Provided	MR
		30m	Provided	MR
		5mm	Provided	MR
7	Automatic fire detection & alarming system.			
	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hoofer's location 	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-

8	MOEFA	Required	Provided	MR
9	Public Address System	-NA-	-NA-	-NA-
10	Automatic Sprinkler System			
	<ul style="list-style-type: none"> Basement 	-NA-	-NA-	-NA-
	<ul style="list-style-type: none"> Upper floors 	-NA-	Provided	-NA-
	<ul style="list-style-type: none"> Sprinkler above false ceiling 	-NA-	-NA-	-NA-
11	Internal Hydrants.			
	<ul style="list-style-type: none"> Size of Riser/Down-comer 	Required	Provided	MR
	<ul style="list-style-type: none"> Number of Hydrant per floor 	Required	Provided	MR
	<ul style="list-style-type: none"> Hose box. 	Required	Provided	MR
12	Yard Hydrants.			
	<ul style="list-style-type: none"> Total number of hydrants. 	-NA-	-NA-	-NA-
	<ul style="list-style-type: none"> Hose box. 	-NA-	-NA-	-NA-
13	Pumping arrangements.			
	<ul style="list-style-type: none"> Ground Level 			
	<ul style="list-style-type: none"> ➤ Discharge of main pump. 	-NA-	900 LPM	-NA-
	<ul style="list-style-type: none"> ➤ Head of main pump. 	-NA-	45 m	-NA-
	<ul style="list-style-type: none"> ➤ Number of main pumps. 	-NA-	01	-NA-
	<ul style="list-style-type: none"> ➤ Jockey Pump output. 	-NA-	-NA-	-NA-
	<ul style="list-style-type: none"> ➤ Jockey Pump head. 	-NA-	-NA-	-NA-
	<ul style="list-style-type: none"> ➤ Standby Pump output. 	-NA-	-NA-	-NA-
	<ul style="list-style-type: none"> ➤ Standby Pump head. 	-NA-	-NA-	-NA-
	<ul style="list-style-type: none"> ➤ Auto Starting / Manual Stopping. 	-NA-	-NA-	-NA-
	<ul style="list-style-type: none"> ➤ Pump House Access 	-NA-	-NA-	-NA-
	<ul style="list-style-type: none"> Terrace Level 			
	<ul style="list-style-type: none"> ➤ Discharge of pump. 	450 LPM	Provided	MR
	<ul style="list-style-type: none"> ➤ Head of pump. 	40 m	Provided	MR
	<ul style="list-style-type: none"> ➤ Power supply. 	Required	Provided	MR
	<ul style="list-style-type: none"> ➤ Auto starting of pump. 	Required	Provided	MR
14	Captive water storage for Fire Fighting.			
	<ul style="list-style-type: none"> Underground tank capacity. 	-NA-	25,000 ltrs	-NA-
	<ul style="list-style-type: none"> ➤ Draw-off connection. 	-NA-	Provided	-NA-
	<ul style="list-style-type: none"> ➤ Fire Service Inlet. 	-NA-	Provided	-NA-
	<ul style="list-style-type: none"> ➤ Access to tank. 	-NA-	Provided	-NA-
	<ul style="list-style-type: none"> Overhead tank capacity. 	10,000 Ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	<ul style="list-style-type: none"> Pressurization of lift shaft. 	-NA-	-NA-	-NA-
	<ul style="list-style-type: none"> Pressurization of lift lobby. 	-NA-	-NA-	-NA-
	<ul style="list-style-type: none"> Communication in lift car. 	-NA-	-NA-	-NA-
	<ul style="list-style-type: none"> Fireman's switch. 	-NA-	-NA-	-NA-
	<ul style="list-style-type: none"> Lift signage. 	-NA-	-NA-	-NA-
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
	<ul style="list-style-type: none"> Total area 	-NA-	-NA-	-NA-
	<ul style="list-style-type: none"> Location 	-NA-	-NA-	-NA-
19	Fire Control Room.			
	<ul style="list-style-type: none"> Detector System Panel. 	-NA-	-NA-	-NA-
	<ul style="list-style-type: none"> Flow Switch Panel. 	-NA-	-NA-	-NA-
	<ul style="list-style-type: none"> PA system Panel. 	-NA-	-NA-	-NA-
	<ul style="list-style-type: none"> Battery backup 	-NA-	-NA-	-NA-
	<ul style="list-style-type: none"> Building floor plan 	-NA-	-NA-	-NA-

~ 11/21

Accordingly, It is submitted vide completion certificate issued by NDMC letter no CA/BP/Musical Fountain & Children Park/D-1698-1702 dated 09/10/2014, the occupancy of the building has already been changed for Assembly building i.e. for the use of retail/eating lounge etc. (copy enclosed at C/56 for ready reference)

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly DFA is put up for approval and signature please.

14
15/9/2021

Signature of the Inspecting Officer
Name : Sh. Rajesh Kumar
Designation: ADO (BCP)

~~DO (SD)~~

RVP
15/09/2021

~~DCFO (S2)~~

dh
16/9

C.F.O. (on d. off)

Director
16/9/2021
F/A

~~ADO/BCP~~

As approved, f.t. letter is put up for your signature @

Director P/R BPK G

14
20/9/2021