GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI

No. F6/DFS/MS/EH/WZ/2021/ 239

Dated: 22/9 /2021

FIRE SAFETY CERTIFICATE

Certified that the M/s Pulse Restaurant (A Unit of Nanak Food) located at A5, First Floor, Vishal Enclave, Rajori Garden, New Delhi-110027 in a building comprised of Ground Plus + Two Upper Floors owned/Occupied by M/s. Pulse Restaurant Eating House was issued Fire Safety Certificate vide letter No. F6/DFS/MS/EH/WZ/2018/1177 dated 22.05.2018, have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire service Rules, 2010 and verified by the officer concerned of this department on 14-09-2021 in the presence of Sh. Deep Kumar Narang and found that the said building is fit for occupancy class "Assembly" Group D with effect from 22 fs/21 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010. Conditions Mentioned Below.

Issued on2.2.1. at New Delhi by.

(Dharampal Bhardwaj) Dy. Chief Fire Officer Delhi Fire Service

Copy to: -

1. Pulse Restaurant located at A5, First floor, Vishal Enclave, Rajori Garden, New Delhi-110027 (Reference: - ID No. 2021040612331 dated: - 07/04/202)

2. The Joint Commissioner of Police, Licensing Unit, 1st floor, Police Station, Defence Colony, New Delhi.

3. The Dy. Health Officer, SDMC, West Zone, Vishal Enclave, Rajouri Garden, New Delhi 110027.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. This NOC is valid for First floor only.

21/09/201

INSPECTION REPORT

1. Name & address of the building : Pulse Restaurant located at A5, First floor, Vishal Enclave, Rajori Garden, New Delhi-110027.

2. Type of Occupancy : Class D (Assembly)

3. Type of Case : Renewal

4. Details of previous NOC : F6/DFS/MS/EH/WZ/2018/1177 Dated-22/05/2018

5. Fire Safety directives letter No : F6/6/TMS/Inspection/2004/106 dated-04/04/2005

6. Date of inspection : 14/09/2021

7. Name of the Inspecting Officers: Sarabjeet Singh (ADO MN)

8. Name and designation of officers

from the building side : Deep Kumar Narang

9. Year of Construction :2004-2005 (As per previous inspection report)

10. Applicant's letter No. : Online application No. 2021040612331 Dated-07/04/2021

* The Said Restaurant is running at 1st Floor in a building comprised at Ground + Two upper Floor. Provided at site Remarks BBL /NBC/ Minimum Standards on fire S. MR/NMR Requirement/As prevention and fire safety U/R 33 No. per pre.Ins.Rep dt.-11/05/2018 1 Access to building MR Provided 12 mts Road width On Main Road MR Gate width NA Width of internal road NR NR NR Number, Width, Type & Arrangement of Exits 2 a. Number of staircases Upper Floors Provided MR 02 Basements NA NA NA b. Width of staircases Upper Floors MR (being 115 cms & 89 cms NR as per 2005 old case) circular Basements NA NA NA c. Protection of exits Fire check door NA NA NA Pressurization NA NA NA e. No. of continuous staircases to terrace Provided MR Required f. Width of Corridor MR Halls only Halls only g. Door Size MR (being 102 cms & 120 cms 2_m old case) Compartmentation. 3 NA NA NA Fire check door NA NA Sealing of electrical shafts NA NA NA Fire Rating of shaft door NA NA NA Water Curtain NA NA NA Fire Dampers NA Smoke Management System. 4 NA NA NA Basements MR Provided Required Upper floors

5	Fire Extinguishers					
	Total numbers	10	Provided	MR		
	• Types	CO ₂ , ABC type	Provided	MR		
	IS marking	ISI marked	Provided	MR		
6	First-Aid Hose Reels.					
	Total numbers on each floor	1	Provided	MR		
	Length of hose reel hose	30m	Provided	MR		
i.	Nozzle diameter	5mm	Provided	MR		

7	Automatic fire detection and alarming		NR	NR		
	• Type of detectors	NR				
	Location of Main Panel CP	NR	NR	NR		
	Location of Repeater Panel	NR	NR	NR		
	Alternate source of power	NR	NR	NR		
*	Hooters' Location	NR	NR NR	NR		
8	MOEFA	Required	Provided	MR		
9	Public Address System.	Required	Provided	MR		
10	Automatic Sprinkler System.					
	Basement	NA	NA	NA		
2	• Upper Floor	NR	Provided			
	 Sprinkler above false ceiling 	NR	Provided			
11	Internal Hydrants		*			
	Size of riser/down-comer	100mm	Provided	MR		
	 Number of hydrants per floor 	1	Provided	MR		
	Hose Box	1	Provided	MR		
12	Yard Hydrants.					
	Total number of hydrants	NR	NR	NR		
l s	Hose Box	NR	NR	NR		
13	Pumping Arrangements.					
13	Ground Level					
	Discharge of main Pump	NR	NR	NR		
	Head of Main pump	NR	NR	NR		
	Number of main pumps	NR	NR	NR		
	> Jockey Pump out put	NR	NR	NR		
	> Jockey pump head	NR	NR	NR		
	Standby Pump out put	NR	NR	NR		
	Standby Pump Head	NR	NR	NR		
	> Auto Starting/ Manual stopping	NR	NR	NR		
	Pump House Access	NR	NR	NR		
	Terrace level	. 11.1	/			
	> Discharge of pump	180 lpm, 450lpm	Provided	MR		
	> Head of the pump	30 m	Provided	MR		
	> Power Supply	Required	Provided	MR		
	> Auto Starting of pump	Required	Provided	MR		
1.4		* ^	11071404			
14	1 8		NID	NR		
	Underground tank capacity Draw off connection	NR NR	NR NR	NR NR		

		N-31	1	NID		
7	> Access to tank	NR	NR	NR		
	Overhead Tank capacity	5,000 ltrs	Provided	MR		
5 Ex	xit Signage.	Required	Provided	MR		
6 P1	Provision of Lifts.					
	Pressurization of Lift Shaft	NA	NA	NA		
	p of Lift lohby	NA	NA	NA		
	Gin In lift Car	NA	NA	NA		
	D: Crounding Switch	NA	NA	NA		
	• Lift Signage	NA	NA	NA		
15 0		Required	Provided	MR		
	tandby power supply		8			
18 R	Refuge Area.	NR	NR	NR		
	Total Area Location	NR	NR	NR		
19 H	• Detector System Panel	NR	NR	NR		
	Detector System Panel Flow Switch Panel	NR	NR	NR		
	 PA System Panel 	NR	NR	NR		
	Batter backup	NR	NR	NR		
	 Building Floor Plans 	NR	NR	NR		
20	Special Fire Protection Systems for	NR	NR	NR		
	Protection of special Risks, if any:		81 8			

The fire protection systems provided in the building were checked and found functional at the time of inspection. The Shortcomings issued by this department vide Letter no. F6/DFS/MS/Eh/WZ/2021/321 Dated-30/07/2021 have been compiled.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the rules, the NOC vide letter no F6/DFS/MS/EH/WZ/2018/1177 Dated- 22/05/2018 renewal under the rule 35 of the Delhi Fire Service rules 2010 is recommended.

212/ADO MN 14/09/2021

Signature of the Inspecting Officer (Sarabjeet Singh)

Asst. Divisional Officer (MN)

Six As per the derection, fresh inspection repeat is put up along with MHA Portal ID No 2021040612321

for your persual & Sij. pl. 1 Stylen