## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/2021/SZ/ 453

Dated: 17./09/2021

## FIRE SAFETY CERTIFICATE

Certified that the **Westend Club** located at **Central Park, Westend Colony, New Delhi,** Comprised of Basement & Ground Floor only owned / occupied by The Diplomatic Enclave Extension, Cooperative Housing Building Society Ltd., was earlier issued Fire Safety Certificate by this department vide letter no F6/DFS/MS/Club/2018/SZ/255 dated 15/12/2018. The premises was re-inspected by the officer concerned of this department on 07/07/2021 in the presence of Sh. Rakesh and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy **class "Assembly (Club)** with effect from the date of issue 17/09/2021 for a period of **Three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued on 17092021 at New Delhi by

(SUNIL CHAWDHARY)
DY. CHIEF FIRE OFFICER (SZ)

Copy to: -

- 1. The Manager, Westend Club located at Central Park, Westend Colony, New Delhi-110021
- 2. The DHO, SDMC. Health Department, South Zone, Green Park, New Delhi 110016.

## Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection.
- 3. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4. All the staff members must know the correct method of operation of fire fighting system.
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL–2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL–2016), if any.
- 6. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."
- 8. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

## **INSPECTION REPORT**

1. Name & address of the building: Westend Club, Central Park, Westend Colony, Rao Tula Ram Marg, New Delhi-110021.

Type of Occupancy : Assembly Building (Group – D)

Type of Case : Renewal (Basement & Ground Floor only)

4. Details of previous NOC : F6/DFS/MS/Club/2018/SZ/255 dated 15/12/2018

5. Fire Safety directives Letter No.: F6/DFS/MS/BP/2001/1031dated 01/06/2001

6. Date of inspection : 07/07/2021 7. Name of the Inspecting Officers: A.D.O. (S.J.)

8. Name and designation of Officer

	from the building side	: Sh. Rakesh					
9.	Year of Construction	: 2010   Covered	d Area at each F	loor – 161m²			
<b>10.</b> A	Applicant's letter received through er	nail <u>ID-mgrweclub@</u>	gmail.com dated 30/	06/2021			
S	Minimum standards on fire	Old FSC	Provided at	Remarks			
No	prevention and fire safety U/R 33	Requirements	site	MR/NMR			
1.	Access of building						
	Road width	Required	9m	MR			
	Gate width	NA	NA	NA			
	Width of internal road	NA	NA	NA			
2.	Number, width, Type & Arran	gements of exits					
	a. Number of staircases	×	. 6				
8	Upper floors	NA	NA	NA			
	Basements	Required	2	MR			
	b. Width of staircases						
	Upper floors	NA	NA	NA			
	Basements	1.25m (each)	1.15m (each)	MR (Old Case)			
	c. Protection of exits						
	Fire check door	NA	NA	NA			
	<ul> <li>Pressurization</li> </ul>	NA	NA	NA			
,	d. No of continuous staircase to terrace	Required	1	MR			
	e. Width Of Corridor	NA	NA	NA			
	f. Door Size	1.5m	Provided	d MR			
3.	Compartmentation						
	Fire check door	NA	NA	NA			
	<ul> <li>Sealing of electrical shafts</li> </ul>	Required	Provided	ded MR			
	Fire Rating of shaft door	NA	NA	NA			
	Water Curtain	NA	NA	NA			
	Fire Dampers	NA	NA	NA			
4.	Smoke managements System						
	Basements	Required	Exhaust fan	MR			
	<ul> <li>Upper floors</li> </ul>	NA	NA	NA			
5.	Fire Extinguishers						
	Total numbers	Required	6	MR			
	• Types	ABC/CO <sub>2</sub> /WCO2	Provided	MR			
	ISI marking	ISI	Provided	MR			
	12:	Ahe					

6. First - Aid Hose Reels Total numbers on 2 Provided MR each floor Length of hose reel 30 Mtr. 30 Mtr. MR Nozzle diameter 5 mm 5 mm MR Automatic fire detection and alarming system 7. Type of detector NA NA NA Location of Main NA NA NA Panel Location of Repeater NA NA NA Alternate source of NA NA NA power Hooters' Location NA NA NA 8. **MOEFA** Required Provided MR 9. Public Address System NA NA NA Automatic Sprinkler System 10. **Basements** NA Provided NA Upper Floor NA NA NA Sprinkler above false NA NA NA ceiling Internal Hydrants 11. Size of riser/down-Required 100 mm MR comer Number of hydrants Required 2 MR per floor Hose Box Required 2 MR 12. Yard Hydrants Total number of NA NA NA hydrants Hose Box NA NA NA Pumping Arrangements 13. Ground Level Discharge of main pump NA NA NA > Head of main pump NA · NA NA Number of main pumps NA NA NA > Jockey pump out put NA NA NA Jockey pump head NA NA NA > Standby Pump out put NA NA NA Standby Pump Head NA NA NA Auto Staring/Manual NA NA NA stopping Pump House Access NA NA NA Terrace level Discharge of pump 450 & 180 LPM Provided MR Head of the pump 40 m Provided MR Power supply Required Provided MR Auto starting of pump Required Provided MR

1 4	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \							
14.	Para water storage for fire lighting							
	Under Ground tank capacity	NA NA		NA				
	> Draw of connection NA		NA		NA			
	Fire service inlet	NA NA NA 10,000 ltr Provid		NA	NA			
	Access to tank			NA	NA			
1.5	Overhead Tank     capacity			Provided	MR			
15	Exit Signage	Required	Required Prov		MR			
16.	Provision of Lifts				IVIIX			
	<ul><li>Pressurization of Lift Shaft</li></ul>	NA	NA NA NA NA		NA			
T	<ul><li>Pressurization of lift lobby</li></ul>	NA			NA			
	Car Communication in lift	NA			NA			
	<ul><li>Fireman's Grounding Switch</li></ul>	NA			NA			
7.	Lift Signage	NA	NA	36	NA			
8.	Standby power supply	power supply Required		ided	MR			
0.	Refuge Area				-			
-	> Total area	N/A	N/A N/A		N/A			
9.	> Location	N/A	N/A		N/A			
9.	The control room							
-	Detector system panel	NA I		NA	NA			
_	> Flow Switch Panel	NA		VA	NA			
-	> PA System Panel	NA .		VA	NA			
-	Battery backup	NT A		VA	NA			
	➤ Building Floor Plans	NA		VA.	NA			
5	Special Fire Protection Systems for Protection of special Risks, if any;	NA		NA	NA			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and safety as required under the rules the NOC issued vide letter no. F6/DFS/MS/Club/2018/SZ/255 dated 15/12/2018 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer
Name: Ashok Kumar Jaiswal
Designation: A.D.O. (S.J.)

The seems the area jurisdiction falls
under purious of ADO (Ref).