

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2021/ 409

Dated: 12/.5./2021

FIRE SAFETY CERTIFICATE

Certified that the Gulshan Palace Dx. Guest House located at 4390/7, Katra Raiji, Basant Road, Pahar Ganj, New Delhi comprised of Ground + 03 Upper floors, Ground floor (02 guest rooms + reception), 1st floor to 3rd floor (03 guest rooms at each floor), total 11 guest rooms owned/occupied by Gulshan Palace Dx. Guest House was earlier granted FSC by this department vide letter No. F6/DFS/MS/GH/NDZ/2018/1900 dated 14/08/18. Now, The premises was re-inspected by the officer concerned of this department on 15/09/21 in the presence of Sh. Ishan Chawla and found that the said guest house have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (02 guest rooms + reception), 1st floor to 3rd floor (03 guest rooms at each floor), total 11 guest rooms up to third floor only, with effect from And the premise in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued -2-79-1-- at New Delhi by.

(Dr. S.K. Tomar) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, and New Delhi: to ensure the occupancy in the building as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi online id no.2021062914365 dated 29/06/2021& mail id 9136262670m@gmail.com dated 02.09.21
- 3. The Manager, Gulshan Palace Dx. Guest House 4390/7, Katra Raiji, Basant Road, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- 1. This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 29.06.2021 latest by 30.09.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry"

INSPECTION REPORT

Gulshan Palace Dx. Guest House at 4390/7, 1. Name & address of the building

Katra Raiji, Basant Road, Pahar Ganj, New Delhi.

2. Type of occupancy:-Residential, Sub Division-A-1

Gr. + 03 Upper floors (total 11 Guest rooms) Ground floor (02 guest rooms + reception), 1st floor

to 3rd floor (03 guest rooms at each floor)

3. Type of case:-Renewal

4. Details of previous FSC:-No. F6/DFS/MS/GH/NDZ/2018/1900 dated

14/08/18

5. Fire safety directives No.-

6. Date of inspection:-

7. Name of the inspecting officer:-

8. Name & designation of officer From the building side:-

9. Year of construction:-

10. Applicant's letter No

N/A

15/09/21

Sh. Ravinder Singh (ADO/CC)

Sh. Ishan Chawla

online id no.2021062914365 dated 29/06/2021& mail id < 9136262670m@gmail.com> dated 02.09.21

				Old Case	
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR	
1.	Access to Building				
	1) Road width	N/A	02 mtr.	N/A	
	2) Gate width	N/A	N/A	N/A	
	3)Width of internal road	N/A	N/A	N/A	
2.	Number, Width Type & Arr	angement of Ex	kits		
	A. Number of staircases				
	1. Upper floors	01 Nos.	01 Nos.	MR	
	2. Basements	N/A	N/A	N/A	
	B. Width of staircase		1		
	1. Upper floors	0.80 mtr.	1.20 mtr.	MR	
	2. Basements	N/A	N/A	N/A	
	C. Protection of exits		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous staircase to terrace	N/A	N/A	N/A	
	E. Width of corridor	N/A	N/A	N/A	
	F. Door size	01 mtr.	01 mtr.	MR	
3.	Compartmentation		Ų!		
	1) Fire check door	N/A	N/A	N/A	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	N/A	N/A	N/A	
4.	Smoke Management System				
	1) Basements	30 ACPH	N/A	N/A	
	2) Upper floors	Required as	Not provided	Last dt. 30.09.21	
	a	per G.N		of compliance	
		dated		extended vide	
		27.05.19		order dt.	
				29.06.21	



N/30

		1 -		
5.	Fire Extinguishers			9
	1) Total numbers	10 Nos.	10 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel			
	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection & A			
	1) Type of detectors CO	Required	Provided	MR
	Type	2		
	2) Location of main panel	Ground floor	Provided	MR
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	Required	Provided	MR
	5) Hooter's Location	Ground floor	Provided	MR
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System	required	110,1000	
10.	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling	14/11	14/11	11/12
11.	Internal Hydrants			
11.	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor	14/21	1777	1777
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants	14/11	11//21	14/11
12.	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.		14/71	14/21	14/21
13.	Pumping Arrangement	N/A	N/A	N/A
	1) Ground level			N/A
	a) Discharge of main	N/A	N/A	IN/A
	pump	N/A	N/A	N/A
	b) Head of main pump			N/A N/A
	c) Number of main pump		N/A	
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping			
	2) Terrace level	100	100 = ===	1.00
	a) Discharge of pump	180 LPM	180 LPM	MR
	b) Head of pump	30 mtr.	30 mtr.	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR



14.	Captive Water Storage for F	ire Fighting		
	Under ground tank capacity	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	2500 ltr.	2500 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syst Risk, if any:	em for Protec	ction of special	N/A

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

Further, Shortcomings issued vide letter no No.F6/DFS/MS/GH/NDZ/481 dated 29/07/2021 have been rectified.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2018/1900 dated 14/08/18 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

