GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

<u>NEW DELHI</u>

No. F6/DFS/MS/Mercantile/WZ/2021 465

Dated: 34 / 0 9/2021

FIRE SAFETY CERTIFICATE

Certified that the Aggarwal City Mall, Located at Plot No – 05, Road No-44, Pitampura, Delhi – 110034, comprised of Basement + Ground + 03 Upper Floors was issued Fire Safety Certificate vide Letter No. F6/DFS/MS/2018/WZ/140 dated 23.01.2018. The said premise was re-inspected by the officer concerned of this department on 09.09.2021 in the presence of Sh. Rajesh Pandey (Mall Manager) & Sh. Ajay Chauhan (GM Operation) and found that the premises / building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010, and that the premises/building is fit for occupancy class "Mercantile Building" Group - F with effect from \mathcal{Mog} for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010,

Copy to:

1

- 1. Sh. Sunil K Jain, Aggarwal City Mall, Plot No 05, Road No-44, Pitampura, Delhi 110034.
- 2. The Joint Commissioner of Police (Lic), 1st Floor, Licensing Unit, Police Station, Defence Colony, New Delhi
- 3. The Vice Chairman, DDA, Vikas Sadan INA, Delhi-23.

CONDITIONS

1. The FSC for restaurants will be applied separately.

- 2. All the means of escape shall be kept free of all type of obstruction all the time. It should not bolt /locked.
- 3. Access road for movement of fire tenders around building shall be kept free from any hindrance.
- 4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any loss of life any property due to the non-functional of any fire safety measures, management shall be held responsible.
- Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 8. All comments / directions of building Department shall always be permitted and followed.
- 9. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <u>www.dfs.delhigovt.nic.in</u>
- 10. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

INSPECTION REPORT

	1851	ECTION REPOR								
	 Name & address of the buildi The second second	Road No-44, I	Pitampura, Delhi – J	10034						
	2. Type of Occupancy	: Mercantile (B +	G + 03 Upper Floors	,)						
	3. Type of Case	: Renewal								
	4. Details of previous NOC	: F6/DFS/MS/201	8/WZ/140 dated 23.0	1.2018						
	5. Fire Safety directives Letter N	√o. : F6/DFS/MS/2 F6/DFS/MS/BI	005/1527 dated19-07 P/2017/1819 dated 19	-2005 & 0.07.2017						
	6. Date of inspection	: 09.09.2021								
	7. Name of the Inspecting Officer : S.P. Bhardwaj ADO (WP)									
	 Name and designation of Officer from the building side : Sh. Rakesh Pandey (Mall Manager) & Sh. Ajay Chauhan (GM Operation) 									
	9. Year of Construction	: 2005-2006, 20	17							
	10. Applicant's letter No.	: email dated 27.	07.2021							
S N	Minimum standards on fire prevention and fire safety U/R 33	BBL/NBC Requirements/let dated 23.01.201		Remarks MR/NMR						
1.	Access of building			MD						
	 Road width 	24 m	Provided	MR						
	• Gate width	6 m	Provided	MR						
	• Width of internal road	As per sanction plan	n Provided	MR						
2.	Number, width, Type & Arrange			1						
	a. Number of staircases									
	• Upper floors	02	Provided	MR						
	• Basements	02+01 Prov Ramp in kite	ided & 1 additional chen	MR						
	b. Width of staircases									
	• Upper floors		to 2^{nd} floor) & 1.6 m							
	Basements		om 1.35- 1.85 m & 1 -	- MR(Old						
			1.8 m (0.82- 0.93 m n basement)	Case)						
	c. Protection of exits									
	• Fire check door	Required	Provided	MR						
	Pressurization	NA	NA	NA						
	d. No of continuous staircase to terrace	02	Provided	MR						
	e. Width Of Corridor	1.5 m	Hall (Old case)	MR						
	f Door Size	1.m & 1.5 m	Provided	MR						
,	Compartmentation									
	 Fire check door 	Required	Provided	MR						
	 Sealing of electrical shafts 	Required	Provided	MR						
	• Fire Rating of shaft door	Required	Provided	MR						
	Water Curtain	NR	NR	NR						
	• Fire Dampers	Required	Provided	MR						
	Smoke managements System									
	Basements	30 a/c per hrs	Provided	MR						
	• Upper floors	12 a/c per hour	Provided	MR						
	Fire Extinguishers	10								
	• Total numbers	12 nos.	18 Nos.	MR						
	TypesIS marking	ABC, CO2 &WCO2	ABC extinguishers Provided	MR						
	1.5 1111116	ISI marked	Provided	~						

6.	First – Aid Ho	se Reels							
		umbers on each	2			D			MD
	floor	en euen	har			Pro	vided		MR
	• Length	of hose reel hose	30 r	11		Pro	vided		MR
	 Nozzle 	diameter	5 m	m			vided		MR
7.	Automatic fire	detection and alar	ming sy	sten	n	110	videu		IVIIX
	 Type o 	f detectors	Smok			Pro	vided		MR
	 Location 	on of Main Panel	Grour				vided		MR
	 Location 	on of Repeater	Requi			and the second se	vided		MR
	Panel	-				110	· /dea		
		ate source of	Requi	red		Dro	vided		MR
	power		riequi	rea		110	videu		MIX
	 Hooter 	s' Location	At Str	ateg	gie	Pro	vided		MR
0			Locati				- Tabla		
8.	MOEFA		Requi	red		Prov	ided		MR
9,	Public Addres		Requi	red		Prov	vided	1	MR
10.		rinkler System	-					T	
	Basem		Requ				ovided	M	
	Upper Sprint		Requi				ovided	M	
	• Sprink ceiling	tler above false	Requi	red		Pro	vided	MI	<
11.	Internal Hydr				r				
		f riser/down- come	r 1	50	mm	Prov	vided	MF	2
		er of hydrants per f		_			vided	MF	
	• Hose		2				vided	MF	
12.	Yard Hydrant	S							
	• Total	number of hydrants					vided	MR	
	• Hose		04				vided	MR	
13.	1 0		nmon wi	ith a	djoining l	ouildin	g at ground	l level	
		nd Level		- 22	001	22	0.0.1	MR	
	• Disch	arge of main pump of main pump			80 lpm m	60	80 lpm	MR	
		ber of main pumps		01		00	111	MR	
		y pump out put			0 lpm) lpm	MR	
	Jocke	y pump head		60	m	60	m	MR	
		by Pump out put			80 lpm		30 lpm	MR	
		by Pump Head	mina		m	60		MR	
		Staring/Manual stop House Access	ping		equired		ovided ovided	MR MR	
		ce level		ICC	quirea	110	Whiteu	IVIIX	
		arge of pump		NA	ł	NA		NA	
		of the pump		NA	1	NA	of store and an experimental free store store of the store store and	NA	
	> Power			NA		NA		NA	
		starting of pump	lation of	NA	1	NA		NA	
14	• Under	r Storage for fire fig ground tank	hting 2,00,00	00 li	tres	Provi	ded	MR	
	capac	of connection	Requir	ed		Provi	ded	MR	
		ervice inlet	Requir			Provi	ded	MR	
	- Acces	s to tank	Requir	ed		Provi		MR	
	and the second	nead Tank capacity	20,000		es	Provi Prov		MR MR	
15	00	Lifts (Lift Run	Require	ed und	to 3rd Flo		idea	IVIK	
10		urization of Lift Shal	ft	und	NA NA	01)	NA	NA	
		urization of lift lobby			NA		NA	NA	
	Comr	nunication in lift Ca	ľ		Required		Provided	MR	
		an's Grounding Swi	tch		Required		Provided Provided	MR MR	
	≻ Lift S	ignage			Required				
						D 1	1	MR	
	7. Standby pow	er supply	Require	ed		Provid	led	MIX	
1			Require NR	ed		Provid	led	NR	2

	Fire control room						
Required	Provided	MR					
Required	Provided	MR					
Required	Provided						
Required	Provided	MR					
NA	NA	NA					
s Manually operated , CO2 system	Provided	MR					
1	Required Required Required NA Manually operated	RequiredProvidedRequiredProvidedRequiredProvidedNANANANA					

The fire protection systems provided in the building were checked and found functional at the time of inspection. The Shortcomings vide letter no. F6/DFS/MS/WZ/2021/1344 dated 08.07.2021 found rectified. One Staircase is not continuous but dislocated at upper floors & the same is accepted in previous NOC.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety requirements under the rules, renewal of FSC issued vide letter no. F6/DFS/MS/2018/WZ/140 dated 23.01.2018 is recommended under the rules 37 of the Delhi Fire Service Rules 2010 under the DFS Act 2007.

71

XIPIS

for Silvy

Deto

Vio

W2

418/21 ADO (WP)