GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No. F.6/DFS/MS/2021/SZ/ 462

Dated: 24/09/2021

FIRE SAFETY CERTIFICATE

Certified that the Banquet Hall running at upper ground & first floor only in a building comprised of basement (sealed), stilt (office), upper ground & first floor (banquet hall) second & third floor not in use, located at RZ-7, Old Pankha Road, Opp. A1-Block, Janak Puri, New Delhi-110059, owned/ occupied by the Seven Pearls hotel (P) Ltd. was inspected by the officers concerned of this department on 21/09/2021 in the presence of Sh. Jitin Pal Singh (Director) and found that the banquet hall have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (upper ground & first floor only) is fit for occupancy class Group D "Assembly Building" w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 24/09/2021 at New Delhi.

(SUNIL CHAWDHARY)
DY.CHIEF FIRE OFFICER

Copy to:-

- The Dy. Health Officer, S.D.M.C, Public Health Department, West Zone, Vishal Enclave, Rajouri Garden, New Delhi-110027
- Sh. Jitin Pal Singh (Owner), Seven Pearls hotel (P) Ltd., RZ-7, Old Pankha Road, Opp. A1-Block, Janak Puri, New Delhi-110059.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT Seven Pearls hotel (P) Ltd., RZ-7, Old Pankha Road, Opp. A1-Block, 1. Name & address of the building:

Janak Puri, New Delhi-110059

Basement, stilt, ground plus three upper floors 2. Building is comprised of

Assembly D-3 3. Type of Occupancy Renewal 4. Type of Case

F.6/DFS/MS/2018/SZ/2558 dated 26/11/2018 5. Details of Previous NOC

6. Fire Safety directives letter No N.A 21/09/2021 7. Date of inspection

A.D.O. R.K. Yadav 8. Name of Inspecting Officer

9. Name and designation of officers

: Sh. Jitin Pal Singh (Director) From the building side

: Before 2010 10. Year of Construction : Nil dated 11. Applicant's letter No.

The banquet hall using basement (Sealed by brick wall), Stilt as office, Upper ground floor as Hall, First Floor

No.	Minimum fire safety	or & third floor not in use. Standards on fire prevention and U/R 33	O D D AM I	T TO LYCE CO.	narks R/NMR
	Access to				
			Accessible (09 m.)	Provided	MR
	· · Ro	oad width	4.5 m	05 m	MR
		ate width	N/A	N/A	N/A
	• W	idth of internal road			
•	Number,	Width, Type & Arrangement of Exi	ts		1 -1 -1
	a. Numbe	r of staircases			MR
		Jpper Floors	02 No's	03 No's	
		Basements	N/A	N/A	N/A
	10000	of staircases	1.50 m	1.50, 1.50 & 1.30 m	MR
		Jpper Floor	N/A	N/A	N/A
		Basements	1 1/1 X		
	Annual Control of the	tion of exits	N/A	N/A	N/A
		Fire check door		N/A	N/A
	•	Pressurization	N/A	IV/A	
	d No o	of continuous staircases to		Provided	MR
	terrac		Required		MR
		h of Corridor	1.50 m	Opening in hall	•
	f. Door		1.50 m	1.50 m (02 no.'s)	MR
2	Compar	tmentation			
3.	Compar			NI/A	N/A
	•	Fire check door	N/A	N/A	
		Sealing of electrical shafts	N/A	N/A	N/A
		Fire Rating of shaft door	N/A	N/A	N/A
	•	Water Curtain	N/A	N/A	N/A
	•	Fire Dampers	N/A	N/A	N/A
4.	Smoke	Management System			27/4
т.		Basements	N/A	N/A	N/A
			Required	Natural ventilation	n MR
	•	Upper floors	Trongs.	provided	
5.	Fire Ex	tinguishers			
		Total numbers on each floor	03 no.'s	Provided	MR
	•		ABC/CO ₂ /W CO ₂ typ		MR
	•	Types	ISI marked	ISI marked	MR

	,					
6.	First-Aid Hose Reels					
	Total numbers on each floor	01 no.	Provided	MR		
	Length of hose reel hose	30 m	Provided	MR		
	Nozzle diameter	05 mm	Provided	MR		
'.	Automatic fire detection and alarming system					
	Type of detectors	Smoke/Heat	Provided	MR		
	Location of Main Panel	At entrance	Provided	MR		
	Location of Repeater Panel	N/A	N/A	N/A		
	Alternate source of power	Required	Provided	MR		
	Hooters' Location	In hall	Provided	MR		
•	MOEFA		Provided			
•	Public Address System	Required N/A	N/A	MR N/A		
0.	Automatic Sprinkler System	IVA	IN/A	IN/A		
	Basement	N/A	N/A	N/A		
	Ground Floor	N/A	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
1.	Internal Hydrants					
	Size of riser/down-comer	100 mm	Provided	MR .		
	Number of hydrants per floor	One	Provided	MR		
	Hose Box	One	Provided	MR		
2.	Yard Hydrants					
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
3.	Pumping Arrangements		17/14	1 1/1 1		
	Ground Level					
	Discharge of main Pump	2280 LPM	Provided	MR		
	➤ Head of Main pump	60 m	Provided	MR		
	Number of main pumps		Provided			
	> Jockey Pump out put	One		MR		
	> Jockey pump head	180 LPM	Provided	MR		
	Standby Pump out put (with DG set	60 m	Provided	MR		
	supply)	2280 LPM	Provided	MR		
	> Standby Pump Head	60 m	Provided	MR		
	> Auto Starting/Manual Stopping	Required	Provided	MR		
	> Pump House Access	Required	Provided	MR		
	Terrace level					
	Discharge of pump	N/A	N/A	N/A		
	➤ Head of the pump	N/A	N/A	N/A		
	Power Supply	N/A	N/A	N/A		
	> Auto Starting of pump	N/A	N/A	N/A		
4.	Captive Water Storage for fire fighting					
	Underground tank capacity	50,000 ltrs	Provided	MR		
	> Draw-off connection	Required	Provided	MR		
	, D	A	Provided	MR		
	> Fire service inlet	Required	Provided	IVII		
	> Access to tank	Required Required				
		Required Required 10000 ltrs	Provided Provided Provided	MR MR		

16.	Provi	sion of Lifts.					
	•	Pressurization of Lift Shaft	N/A	N/A	N/A		
	•	Pressurization of Lift lobby	N/A	N/A	N/A		
		Communication In lift Car	N/A	N/A	N/A		
		Fireman's Grounding Switch Lift Signage	Required	Provided	MR		
		3-13-	· N/A	N/A	N/A		
17.	Stand	by power suppl ŷ	Required	Provided	MR		
18.	Refuge Area.						
	>	Total Area	N/A	N/A	N/A		
	>	Location	N/A	N/A	N/A		
19.	Fire Control Room						
		Detector System Panel	N/A	N/A	N/A		
	•	Flow Switch Panel	N/A	N/A	N/A		
	•	PA System Panel	N/A	N/A	N/A		
	Battery backup Building Floor Pl		N/A	N/A	N/A		
		building Floor Plans	N/A	N/A	N/A		
20.	Spécia of spec	I Fire Protection System for Protection ial Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. <u>F6/DFS/MS/2018/S2/2558</u> dated <u>26/11/2018</u> renewal under rule 37 of the Delhi Fire Service rules 2010 is recommended

Note: As per the undertaking given by the Director of the banquet hall the management has sealed the basement hall with brick wall & second & third floor not use for any work.

Signature of Inspecting Officer

Name: - R.K. Yadav

Designation: - Asstt. Divisional Officer

D.O. (South vest) on leave

Thetter is put up

for sign

24/9/2021

124cxp(22)

h m c 11/1