

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001

No. F6/DFS/MS/GH/NDZ/2021/

Dated: 23/9/21

FIRE SAFETY CERTIFICATE

Certified that the M/s Tamanna Guest House located at 2294, Gali Qasim Jan, Ballimaran, Delhi, comprised of Ground + 03 upper floors: Ground floor – reception + office + 01 dormitory for 11 beds, 1st floor - 06 guest rooms, 2nd floor- 05 guest rooms, 3rd floor -07 guest rooms, total 18 guest rooms and 01 dormitory for 11 beds was granted FSC by this department vide letter no. F6/DFS/MS/GH/NDZ/2018/2200 dated 27.09.2018. The building/premises was re-inspected by Assistant Divisional Officer (SPM) from this department on 20.09.2021 in presence of manager/ owner and found that now the building is comprised of Ground + 04 upper floors: Ground floor - reception + office + 01 dormitory for 11 beds, 1st floor - 06 guest rooms, 2nd floor - 05 guest rooms, 3rd floor - 07 guest rooms, 4th floor- not in use. The owner has submitted an affidavit on 02.12.2019 not to use fourth floor for any other purpose except mumty of staircase and water tank in accordance with clarification of Gazette Notification (published on 27.05.2019) dated 27.12.2019. The building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of "Group A-1 (Residential)" for total 18 guest rooms and 01 dormitory for 11 beds, (1st floor - 06 guest rooms, 2nd floor - 05 guest rooms, 3rd floor - 07 guest rooms) upto 3rd floor only, with effect from 22.1.9.1........ for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 subject to condition printed below.

Issued on 23/5/21 at New Delhi by

(Dr. S.K. Tomar) Dy. Chief Fire Officer

Tel: 011-23412025

- Copy to:
 1. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defense Colony, New Delhi.
- 2. The Licensee, M/s Tamanna Guest House located at 2294, Gali Qasim Jan, Ballimaran, Delhi.

Condition for the validity of fire safety certificate

- This clearance/FSC shall stand cancelled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 and any violation of clarification issued on 25.09.2019 & 17.12.2020 latest by 30.09.2021.
- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- The trained fire fighting staff should be available round the clock.
- Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry". Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained there to before occupancy of the same.

INSPECTION REPORT

1.	Name and address of the building:	M/s Tamanna Guest House at 2294, GaliQasim Jan,Ballimaran, Delhi.				
2.	Type of occupancy with details of floors:					
3.	Type of case:	Renewal				
4.	Details of previous FSC:	F6/DFS/MS/GH/NDZ/2018/2200 dated 27.09.2018.				
5.	Fire safety directives no.:	Nil				
6.	Date of inspection:	20.09.2021.				
7.	Name of the inspecting officer:	Rajesh Kumar Shukla ADO (SPM)				
8.	Name and designation of the officer from the building side:					
9.	Year of construction:	2001				
10.	Reference letter no.:	Online Application No. 2021081918319 dated 19.08.2021.				

S.No	1	inimum standard of Fire evention and Fire Safety U/R 33	Requirements (Existing Fire & Safety Measures)	Provide at site (PSS)	Remarks MR/NMR	
1	Access to Building					
	A	Road width	NA (Spl. Area)	7mtrs.	NA	
	B	Gate width	NA	NA	NA	
	C	Width of internal roads	NA	NA	NA	
2	Nu	mber, Width, Type & Arrangeme	ent of Exits	,	1.	
	A	No. of Staircase:				
		a) Upper floor	01 nos.	01 nos.	MR	
		b) Basements	NA	NA	NA	
	В	Width of the Staircase:				
		a) Upper floors	80 cms	105cms	MR	
		b) Basements	NA	NA	NA	
	C	Protection of Exits			13-18	
		a) Fire check door	Required (as per GN dated 27.05,2019)	Not Provided	Last date of compliance 30.09.2021.	
		b) Pressurization	NA	NA	NA	
	D	No. of continuous staircase to terrace:	01 nos.	01 nos.	MR	
	F	Width of the corridor	NA	NA	NA	
	E	Door size	1mtrs.	1 mtrs.	MR	
3	Compartmentation:					
	A	Fire check doors	NA	NA	NA	
	B	Sealing of electrical shafts	NA	NA	NA	
	C	Fire rating of shaft doors	NA	NA	NA	
	D	Water curtain	NA	NA	NA	
	E	Fire dampers	NA	NA	NA	
4	Smoke management System:					
	A	Upper floors	Natural/Mechanical	Natural	MR	
	B	Basements	NA	NA	NA	
5	Fire extinguishers					
	A	Total numbers	08 no.	08no.	MR	
	В	Types	CO2, ABC	CO2, ABC	MR	
	C	ISI marking	Required	Provided	MR	

4.23

6	Fi	rst Aid Hose reel					
	A	Total no. at each floor	1 nos.	1 nos.	MR		
	B	Length of hose reel	30 mm	30 mm	MR		
	C	Nozzle diameter	5 mm	5 mm	MR		
7	Au	tomatic Fire Detection and Alarm S	vstem (ADAS)				
	A	Type of detectors -(CO) detector	CO detectors	Not Provided	Last date of		
			(required as per		compliance		
	4		GN dated		extended till		
	373		27.05.2019)		30.09.2021		
	В	Location of main Panel	At reception	Not provided	Last date of		
			(ground floor)		compliance extended till		
				-	30.09.2021		
	C	Location of repeater panel	NA	NA	NA		
	D	Alternate power source	NA	NA	NA		
	E	Hooter's location	NA	NA	NA		
8		OEFA	NA	NA	NA		
9		blic Address System	Required	Provided	MR		
10		tomatic Sprinkler System	required	Tiovided	17114		
X U	A	Basement	NA	NA	NA		
	В	Upper floor	NA	NA	NA		
	C	Sprinklers above false ceiling	NA NA	NA NA	NA NA		
11	-	ernal Hydrants	11/1	INA	INA		
11	A	Size of the riser/down comer	NA	NA	NA		
	B	No. of hydrants per floor	NA NA	NA NA	NA NA		
	С	Hose box	NA NA				
12			I NA	NA	NA		
14		rd Hydrants	I NTA	Tara	I NI A		
	A B	Total no. of hydrants Hose box	NA	NA	NA ·		
10			NA	NA	NA		
13		mping arrangements		*			
	A	Ground Level	Lara	I SYA	Lava		
		a) Discharge of main pump	NA	NA	NA		
		b) Head of main pump	NA	NA	NA		
		c) Number of main pump	NA	NA	NA		
		d) Discharge of jockey pump	NA	NA	NA .		
		e) Head of jockey pump	NA	NA	NA		
		f) Discharge of standby pump	NA	NA	NA		
		g) Head of standby pump	NA	NA	NA		
		h) Auto starting/ manual stopping	NA	NA	NA		
	B Terrace Level						
		a) Discharge of terrace pump	225 LPM	225LPM	MR		
		b) Head of terrace pump	30 meters	30 meters Provided	MR		
		c) Alternate power supply	Required	Provided	MR		
1.4	-	d) Auto starting of pump	Required	Provided	MR		
14	Captive Water Storage for Fire Fighting						
	A	Underground tank capacity	NA	NA	NA		
	B	Draw off connection	NA	NA	NA		
	C	Fire service inlet	NA	NA	NA		
	E	Access to tank	NA 2500 III	NA	NA		
	D	Overhead tank capacity	2500 litres	4000 litres	MR		
15		it Signage	Required	Provided	MR		
16							
	A	Pressurization of lift shaft	NA	NA	NA		
	В	Pressurization of lift lobby	NA	NA	NA		
	C	Communication in lift car	NA	NA	NA		
	D	Fireman switch	NA	NA	NA		
1	E	Lift signage	NA	NA	NA		
17	04	andby Power Supply	Required	Provided	MR		

18	Refuge Area					
	A	location	NA	NA	NA	
	B	Total area	NA	NA	NA	
19						
	A	Fire detection system panel	NA	NA	NA	
	B	Flow switch panel	NA	NA	NA	
	C	P a system panel	NA	NA	NA	
	D	Battery backup	NA	NA	NA	
	E	Building floor plan	NA	NA	NA	
20	20 Special Fire Protection for special risk if any				NA	

Meeting requirement (MR), Not meeting requirement (NMR), Not applicable (NA), Provided but not functional (PNF).

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections. The owner has submitted an affidavit on 02.12.2019 not to use fourth floor for any other purpose except mumty of staircase and water tank in accordance with clarification of Gazette Notification (published on 27.05.2019) dated 27.12.2019.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2018/2200 dated 27.09.2018 is recommended to be renewed under Rule 35 of the Delhi Fire Service Rules 2010.

22.09.24

Signature of the Inspecting Officer
Name Rajesh Kumar Shukla
Designation ADO (SPM)

DO (CD)

22/9/21

Dycfo (MDZ)

F. G. PI

(X 10 14)

ADOCSPM

Fr ies pert up for signatures pla

22 9 21

Dy. cho/AND2

KT9m7

TYS
holocubed MHA ordere Postal
MUNI
24109121

616 24818 53(5)31