## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2021/ 47\_9

Dated: 27./.9./2021

## FIRE SAFETY CERTIFICATE

Certified that the M/s Shree Balaji Dx. Guest House located at 2204, Raj Guru Pahar Ganj, New Delhi comprised of Ground + 03 Upper floors, Ground floor (reception + staff rooms + shops), 1st floor to 2nd floor (07 guest rooms at each floor), 3rd floor (staff kitchen + DG set), total 14 guest rooms owned/occupied by M/S Shree Balaii Dx. Guest House was granted FSC by this department vide letter No.F6/DFS/MS/GH/2018/NDZ/1507 dated 28/06/18. Now, the premises was re-inspected by the officer concerned of this department on 21/09/21 in the presence of Sh. A.S. Tondon and found that the said guest house building comprises of ground and three upper and having, ground floor (reception + staff rooms + shops), 1st floor to 2nd floor (07 guest rooms at each floor) and 02 store rooms with out kitchen at third floor, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 1st floor to 2nd floor (07 guest rooms at each floor), Total - 14 guest rooms only up to second floor with effect from -27-/-2-/--for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 27/9/21 at New Delhi by.

(**Dr. S.K. Tomar**) Dy. Chief Fire Officer Delhi Fire Service

## Copy to:-

- 1. The Commissioner of North, MCD, Civic Centre, New Delhi. to ensure the occupancy in the building as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID No 2021090320041 dated 03.09.21
- 3. The Manager,

M/s Shree Balaji Dx. Guest House 2204, Raj Guru Road, Pahar Ganj, New Delhi.

## Condition for the validity of fire safety certificate

- 1. This clearance/ FSC shall stand cancelled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 29.06.2021 latest by 30.09.2021.
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

N 24

INSPECTION REPORT

1. Name & address of the building M/s Shree Balaji Dx. Guest House at 2204, Raj Guru Road, Pahar Ganj, New Delhi.

2. Type of occupancy:- Residential, Sub Division-A-1

Gr. + 03 Upper floors (total 14 Guest rooms) Ground floor (reception + staff rooms + shops), 1<sup>st</sup> floor to 2<sup>nd</sup> floor (07 guest rooms at each floor),

3<sup>rd</sup> floor (02 store rooms & DG set)

3. Type of case:- Renewal

4. Details of previous FSC:- No. F6/DFS/MS/GH/2018/NDZ/1507 dated

5. Fire safety directives No.6. Date of inspection:28/06/18.
N/A
21/09/21

7. Name of the inspecting officer:- Sh. Ravinder Singh (ADO/CC) Sh. Rajinder Atwal (DO/CD)

8. Name & designation of officer
From the building side:- Sh. A.S.Tondon

9. Year of construction:-

10. Applicant's letter No:- 2021090320041 dated 03.09.21

Old Case S.No. Minimum Standards on fire Requirement/ Provided at site Remarks Prevention and fire safety U/R 33 Existing fire MR/NMR safety arrangements 1. Access to Building 1) Road width N/A 06 mtr. N/A 2) Gate width N/A N/A N/A 3) Width of internal road N/A N/A N/A 2. Number, Width Type & Arrangement of Exits A. Number of staircases 1. Upper floors 01 Nos. 01 Nos. MR 2. Basements N/A N/A N/A B. Width of staircase 1. Upper floors 0.80 mtr. 1.20 Mtr. MR 2. Basements N/A N/A N/A C. Protection of exits 1. Fire check door N/A N/A N/A 2. Pressurization N/A N/A N/A D. No. of continuous N/A N/A N/A staircase to terrace E. Width of corridor N/A N/A N/A F. Door size 01 mtr. 01 mtr. MR 3. Compartmentation 1) Fire check door N/A N/A N/A 2) Sealing of electrical shafts N/A N/A N/A 3) Fire rating of shaft door N/A N/A N/A 4) Water curtain N/A N/A N/A 5) Fire Dampers N/A N/A N/A 4. **Smoke Management System** 1) Basements 30 ACPH Provided MR 2) Upper floors Required as Not provided Last dt. per G.N 30.09.21 of dated compliance 27.05.19 extended vide order dt. 29.06.21

	Fire Extinguishers			1			
		10		10	N	IR	
	1) Total numbers	10	000	ABC & CO		IR	
	2) Types	ABC &		Provided Provided		IR IR	
	3) ISI marking	Requir	ed	Provided	17		
6.	First-Aid Hose Reel						
	1) Total number of eachfloor N/A			01	I	J/A	
	1) Total number of eachfloor	N/A N/A				N/A	
	2) Length of hose reel hose			05 mm		V/A	
	2) Maggle diameter	lo diameter N/A					
7.	Automatic Fire Detection &	Alarmi	ng Syst	Not provide	d	Last dt.	
	1) Type of detectors CO	Required as		Not provide		30.09.21 of	
	Type	per G.N				compliance	
		dated			1 0	extended	
		27.05.19				vide order dt.	
						29.06.21	
				DI/A		N/A	
	2) Location of main panel	N/A		N/A	12	N/A	
	3) Location of repeater panel	N/A		N/A		N/A	
	4) Alternate source of power	N/A		N/A		N/A	
	5) Hooter's Location	N/A		N/A			
0	MOEFA	N/A		N/A		N/A	
8.	Public Address System	N/A		N/A		N/A	
9.	Automatic Sprinkler System						
10.	Automatic Sprinkier System	N/A		N/A		N/A	
	1) Basement	N/A		N/A		N/A	
	2) Upper floors	N/A		N/A		N/A	
	3) Sprinkler above false						
	ceiling				E.		
11.	Internal Hydrants	re of riser/down-comer N/A		N/A		N/A	
	1) Size of riser/down-comer	N/A		N/A		N/A	
	2) Number of hydrants per	14/11					
	floor	N/A		N/A		N/A	
	3) HOSC DOX				1. 1.31	2	
12.	Yard Hydrants	s N/A		N/A		N/A	
	1) Total number of hydrants	s N/A		N/A		N/A	
	2) Hose box	IN/P				5	
13.	Pumping Arrangement	N	/ ^	N/A		N/A	
	1) Ground level		A /A	N/A		N/A	
	a) Discharge of main	17	A	14/11			
	pump N//		/Δ	N/A		N/A	
	b) Head of main pump N/A		111			N/A	
	C) Nullioci of man part		1 1/2 1			N/A	
	d) Jockey pamp		14/12			N/A	
	e) Jockey pains near		1 1/2 2			N/A	
	f) Stand by pump output		N/A N/A		The second second	N/A	
	g) Stand by pump head		I/A	N/A			
	h) Auto starting/Manual		I/A	N/A		N/A	
	stopping						
	2) Terrace level			100 1 0	1	N/A	
	a) Discharge of pump		I/A	120 LP	VI	IN/A	

N 26

	b) Head of pump	N/A	30 mtr.	N/A				
	c) Power supply	N/A	Provided	N/A				
	d) Auto starting of pum	p N/A	Provided	N/A				
14.	Captive Water Storage for Fire Fighting							
	Under ground tank     capacity	N/A	N/A	N/A				
	a) Draw-off connection	N/A	N/A	N/A				
	b) Fire service inlet	N/A	N/A	N/A				
	c) Access to tank	N/A	N/A	N/A				
	d) Over head tank capacity	N/A	2500 ltr.	MR				
15.	Exit Signage.	Required	Provided	MR				
16.	Provision of Lifts.							
	a) Pressurization of lift shaft	N/A	N/A	N/A				
	b) Pressurization of lift lobby	N/A	N/A	N/A				
· · · · · · · · · · · · · · · · · · ·	c) Communication in lift car	N/A	N/A	N/A				
	d) Fireman's switch	N/A	N/A	N/A				
	e) Lift signage	N/A	N/A	N/A				
17.	Stand by Power Supply	Required	Provided	MR				
18.	Refuge Area	N/A	N/A	N/A				
	Total area location	N/A	N/A	N/A				
19.	Fire Control Room	N/A	N/A	N/A				
	a) Detector system panel	N/A	N/A	N/A				
	b) Flow switch panel	N/A	N/A	N/A				
	c) PA system panel	N/A	N/A	N/A				
	d) Battery backup	N/A	N/A	N/A				
	e) Building floor plan	N/A	N/A	N/A				
20.	Special Fire Protection Sys Risk, if any: ABC & CO <sub>2</sub>	MR						

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2018/NDZ/1507 dated 28/06/18 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval.

Signature of the inspecting officer

Name: - Rajinder Atwal Designation: - DO (CD)

Signature of the Inspecting Officer

Name: Ravinder Singh Designation: ADO (CC)

Dycho (moz)

X19mV 2319121

As appoised Pripatub for Icus femas and