GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI – 110001

F6/DFS/MS/GH/NDZ/2021 417

Dated: 24/9/2/

## **FIRE SAFETY CERTIFICATE**

Issued on .24,1.9,1.21.....at New Delhi by

(**Dr. S.K. Tomar**)
Dy. Chief Fire Officer

Tel: 011-23412025

## Copy to:-

- 1. The Joint Commissioner of Police (Licensing), 1<sup>st</sup> Floor, Police Station Defence Colony, New Delhi
- 2. The Licensee, Oasis Guest House at 3745, Kucha Parmanand, Darya Gang, Delhi.

## Condition for the validity of fire safety certificate

- 1. This clearance/FSC shall stand cancelled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 and any violation of clarification issued on 25.09.2019 & 17.12.2020 latest by 30.09.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry". Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained there to before occupancy of the same.

## NIM

		INSPECTION REPORT		
1.	Name and address of the building:	Oasis Guest House at 3745, Kucha Parmanand, Darya Gang, New Delhi.		
2.	Type of occupancy with details of floors:	Residential Group A-1 (Ground + 03 upper floors)  1st floor - 05 guest rooms  2nd floor- 05 guest rooms  3rd floor- 04 guest rooms + staff room		
3.	Type of case:	Renewal case		
4.	Details of previous FSC:	F6/DFS/MS/GH/NDZ/2018 dated 17.07.2018		
5.	Fire safety directives no.:	NA		
6.	Date of inspection:	20.09.2021 ADO Rajesh Kumar Shukla (SPM)		
7.	Name of the inspecting officer:	ADO Rajesii Rumai Silami (		
8.	Name and designation of the officer from the building side:	Mr. Mirza Saleem bag (Owner's)		
9.	Year of construction:	2002 Online application I.D. 2021081717993 dated 17.08.2021		
10	Reference letter no.:	Online application 1.D. 202100171799		

S,No	M	lini rev	mum standard of Fire ention and Fire Safety U/R 33	Requirements (Existing Fire & Safety Measures)	Provide at site (PSS)	Remarks MR/NMR	
1	Access to Building				15	MR	
	A		Road width	06 mtrs.	15 mtrs.	NA	
	B		Gate width	NA	NA	NA	
	C		Width of internal roads	NA	NA	INA	
2	Number, Width, Type & Arrangement of Exits						
	-	A No. of Staircase:					
	-	+	a) Upper floor	01 no.	01 no	MR	
		+	b) Basements	NA	NA	NA	
	-	В	Width of the Staircase:			MR	
1	A		a) Upper floors	0.80 mtrs.	1.05 mtrs.	NA	
		t	b) Basements	NA	NA	INA	
		C	Protection of Exits			NIA	
			a) Fire check door	NA	NA	NA	
			b) Pressurization	NA	NA	NA	
		D	No. Of continuous staircase to	01 no.	01 no.	MR	
			terrace:	NA	NA	NA	
1	_	F	Width of the corridor	1.0 mtrs.	1.0 mtrs.	MR	
		E	Door size	1.0 11.0			
*	3	-	mpartmentation:	NA	NA	NA	
		A	Fire check doors	NA	NA	NA	
		B	Sealing of electrical shafts	NA	NA	NA	
		C	Fire rating of shaft doors	NA NA	NA	NA	
*		D	Water curtain	NA NA	NA	NA	
4		E	Fire dampers	INA			
+	4	S	moke management System:	Natural/mechanica	Natural	MR	
		A	Upper floors	NA NA	NA	NA	
		B		IVA			
	5	F	ire extinguishers	00 00	08 no.	MR	
		A	Total numbers	08 no.	CO2, ABC	MR	
24		B	Types	CO2, ABC	Provided Provided	MR	
		C	ISI marking	Required	Provided	TATE	



	A	Total no. at each floor	01	01	MR		
	В	Length of hose reel	30 mtrs.	30 mtrs.	MR		
	C	Nozzle diameter	05mm	05mm	MR		
7	Automatic Fire Detection and Alarm System (ADAS)						
,	A	Type of detectors -(CO) detector	CO detectors	Not Provided	Last date of		
	18	Type of detectors (CO) detector	(required as per GN dated 27.05.2019)	11011101100	compliance extended till 30.09.2021.		
	В	Location of main Panel	(required as per GN dated 27.05.2019)	Not Provided	Last date of compliance extended till 30.09.2021.		
	C	Location of repeater panel	NA	NA	NA		
	D	Alternate power Source	NA	NA	NA		
	E	Hooter's location	NA	NA	NA		
8	MO	DEFA	NA	NA .	NA		
9	Pul	blic Address System	Required	Provided	MR		
10	Au	tomatic Sprinkler System		1			
	A	Basement	NA	NA	NA		
	В	Upper floor	NA	NA	NA		
	C	Sprinklers above false ceiling	NA	NA	NA		
11		ernal hydrants		Table	1		
	A	Size of the riser/down comer	NA	NA	NA		
	B	No. of hydrants per floor	NA	NA	NA		
1.0	C	Hose box	NA	NA	NA		
12		rd Hydrants	Lava	INT	LATA		
	A	Total no. of hydrants	NA	NA	NA		
12	В	Hose box	NA	NA	NA		
13		mping arrangements Ground Level					
	A		NA	NA	NA		
		a) Discharge of main pump     b) Head of main pump	NA	NA NA	NA		
		c) Number of main pump	NA	NA	NA		
			NA NA	NA NA	NA NA		
		d) Discharge of jockey pump					
		e) Head of jockey pump	NA	NA	NA		
		f) Discharge of standby pump	NA	NA	NA		
	-	g) Head of standby pump	NA	NA	NA		
		h) Auto starting/ manual stopping	NA	NA	NA		
	B	to the control of the					
		a) Discharge of terrace pump	225 LPM	225 LPM	MR		
		b) Head of terrace pump	30 mtrs.	30 mtrs.	MR		
		c) Alternate power supply	Required	Provided	MR		
			Required	Provided	MR		
14	-	ptive Water Storage for Fire Fightin			Г		
	A	Underground tank capacity	NA	NA	NA		
	В	Draw off connection	NA	NA	NA		
	C	Fire service inlet	NA	NA	NA		
	E	Access to tank	NA	NA .	NA		
	D	Overhead tank capacity	2500 ltr.	2500 ltr.	MR		
15							
16							
	A	Pressurization of lift shaft	NA	NA	NA		
	В	Pressurization of lift lobby	NA	NA	NA		
	C	Communication in lift car	NA	NA	NA		
	D	Fireman switch	NA	NA	NA		
17	E	Lift signage	NA	NA	NA		
	1 64	andby Power Supply	Required	Provided	MR		

01 h

18	Refuge Area				
	A	location	NA	NA	NA
	B	Total area	NA	NA	NA
19	Fire Control Room				
,	A	Fire detection system panel	NA	NA	NA
	B	Flow switch panel	NA	NA	NA
	C	P A system panel	NA	NA	NA
	D	Battery backup	NA	NA .	NA
	E	Building floor plan	NA	NA	NA
20	Special Fire Protection for special risk if any				NA NA

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter No. F6/DFS/MS/GH/NDZ/2018/1673 dated 17.07.2018 is recommended to be renewed under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name Rajesh Kumar Shukla

Designation ADO (SPM)

ADOGSPM) it ies per up for signatural

