GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2021/ 424

Dated: 24/9/21

FIRE SAFETY CERTIFICATE

Certified that M/s. Almondz guest house located at 4/3,2,1, East Patel Nagar, New Delhi- 110008 was granted FSC for building comprised of basement (hall), stilt (parking), ground floor (reception, pantry/kitchen & dining hall), first floor (05 guest room), second floor (05 guest rooms) and third floor (18 guest rooms) (total 28 guest rooms) by this department vide letter No. F6/DFS/MS/GH/SZ/2017/448 dated 01.08.2017. The premises was re-inspected by the officer concerned of this department on 20.09.2021 in presence of Sh. Pankaj Kumar, Manger of the guest house and found that the guest house deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) for basement (incidental storage), ground floor (reception & hall), stilt (parking), first and second floor each having 05 guest rooms respectively, third floor having 18 guest rooms (total 28 guest rooms only) with effect from 249/21 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed back side.

Issued 24/8/21 at New Delhi by.

(Sunil Chaudhary) Dy. Chief Fire Officer (SZ) Delhi Fire Service

Copy to:-

1. The Owner/Occupier, M/s. Almondz guest house, 4/3,2,1, East Patel Nagar, New Delhi-110008.

2. The Joint C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi

Following Fire Safety Directives must be adhered to: -

- 1. The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/359-374 dated 29.06.2021 in respect of existing building (copy enclosed) shall be implemented by 30.09.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void
- 2. No occupancy above third floor & basement as storage purpose, shall be adhered by Owner/Occupier
- 3. All the means of escape shall be kept free of all type of obstruction all the time.
- 4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 6. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 7. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 8. All comments / directions of licensing department shall always be permitted and followed.
- 9. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 10. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- 11. Basement shall be used as per BBL.
- 12. No temporary shed is allowed on terrace.
- 13. The Fire Safety Certificate is only for Guest Rooms.

INDIECTION RELIGION 1. Name & address of the building : M/s Almondz guest house, 4/3,2,1, East Patel Nagar, New Delhi- 110008. 2. Type of Occupancy : Lodging House 3. Type of Case : Renewal 4. Details of previous NOC : F.6/DFS/MS/GH/SZ/2017/448 dated 01.08.2017 5. Fire Safety directives letter No : Nil 6. Date of inspection : 20.09.2021 7. Name of the Inspecting Officers : P.V. Rathee, Asst. Divisional Officer (SRD) 8. Name and designation of officers from the building side : Sh. Pankaj Kumar, Manger 9. Year of Construction : Before 2010 10. Applicant's letter No. : Online Application no. 2021082418774 dated 25.08.2021 The said guest house building comprised of basement, stilt, ground plus three upper floors. S. Minimum Standards on fire Fire safety Provided at Remarks arrangements as per No. prevention and fire safety U/R 33 site MR/NMR FSC dt. 01.08.2017 1 Access to building Road width 06 mts Provided MR Directly accessible Gate width MR Width of internal road N/A N/A N/A 2 Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors 02 02 MR Basements 02 02 MR b. Width of staircases 1.25 mts, 0.84mt, & 0.76 MR being old case Upper Floors old case mt. (from GF to TF only) MR; being old case 1.20 mts, 0.84 mt. Basements old case c. Protection of exits date of compliance has been Fire check door Required Not Provided extended up to 30.09.2021 Pressurization N/A N/A N/A e. No. of continuous staircases to 01 01 MR terrace g. Width of Corridor Old case 1.38 mts MR being old case h. Door Size Old case 0.78 mts MR being old case 3 Compartmentation. date of compliance has been Fire check door Required Not Provided extended up to 30.09.2021 Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A 4 Smoke Management System. Basements 30 a/c per hour Exhaust fan provided MR 12 a/c per hour date of compliance has been Upper floors Not Provided extended up to 30.09.2021 5 Fire Extinguishers Total numbers 20 Provided MR CO2, ABC, WCO2 Provided Types MR ISI marked

	Total numbers on each floor	01	Provided		MR		
	 Length of hose reel hose 	30 m	Provided		ME		
	Nozzle diameter	5 mm	Provided		MR		
7	Automatic fire detection and alarming system.						
	Type of detectors	Carbon Monoxide	Not Provided		compliance has been ed up to 30.09.2021		
	Location of Main Panel	Required	Not Provided		compliance has been ed up to 30.09.2021		
	 Location of Repeater Panel 	N/A	N/A		N/A		
	 Alternate source of power 	Required	Provided	1	MR		
	Hooters' Location	N/A	N/A	- v	N/A		
8	MOEFA	Required	Provided		MR		
9	Public Address System.	Required	Provided		MR		
10	Automatic Sprinkler System.						
	Basement	Required	Provided		MR		
	• Upper Floor	N/A	N/A		N/A		
11	Sprinkler above false ceiling Internal Hydroneter	N/A	N/A		N/A		
11	Internal Hydrants						
	Size of riser/down-comer Number of bydroots are flower.	N/A N/A	100 mm				
	Number of hydrants per floorHose Box	N/A N/A	01		W 40 50 10		
12	Yard Hydrants.	IN/A	U1				
12	Total number of hydrants	N/A	N/A		N/A		
	Hose Box	N/A	N/A		N/A N/A		
13	Pumping Arrangements.	11/11	14/11		IN/A		
	Ground Level						
	Discharge of main Pump	N/A	N/A		N/A		
1.	Head of Main pump	N/A	N/A		N/A		
	Number of main pumps	- N/A	N/A		N/A		
	Jockey Pump out put	N/A	N/A		N/A		
	Jockey pump head	N/A	N/A		N/A		
	Standby Pump out put	N/A	N/A		N/A		
	> Standby Pump Head	N/A	N/A		N/A		
	Auto Starting/ Manual stoppin	g N/A	N/A		N/A		
	Pump House Access	N/A	N/A		N/A		
	Terrace level		AND SIGN WAS SAND SAND SAND SAND				
	Discharge of pump	900 LPM	900 LPM		MR		
*	Head of the pump	40 mts	40 mts		MR		
	Power Supply	Required	Provided		MR		
	Auto Starting of pump	Required	Provided		MR		
14	Captive Water Storage for fire fighting	•			111111111111111111111111111111111111111		
	Underground tank capacity	N/A	N/A		N/A		
	> Draw-off connection	N/A	N/A		N/A		
	Fire service inlet	N/A	N/A		N/A		
	Access to tank	N/A	N/A		N/A		
15	Overhead Tank capacity Evit Signage	10,000 lts 10,000			MR		
15	Exit Signage.	Required	Provided		MR		

	•	Pressurization of Lift Shaft	N/A	N/A	N/A		
	•	Pressurization of Lift lobby	N/A	N/A	N/A		
	•	Communication In lift Car	Required	Provided	MR		
	•	Fireman's Grounding Switch	Required	Provided	MR		
	•	Lift Signage	Required	Provided	MR		
17	Stand	by power supply	Required	Provided	MR		
18	Refug	Refuge Area.					
	>	Total Area	N/A	N/A	N/A		
	>	Location	N/A	N/A	N/A		
19	Fire (Fire Control Room					
		Detector System Panel	N/A	N/A	N/A		
		Flow Switch Panel	N/A	N/A	N/A		
		PA System Panel	Required	Provided	MR		
o .		Batter backup	Required	Provided	MR		
		Building Floor Plans	N/A	N/A	N/A		
20	_	al Fire Protection Systems for etion of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were checked and found functional at the time of inspection.

Note:- During the course of inspection it was observed that wooden/ply is use at few places in corridor, certificate of fire retardant paint given by owner attached at C-53

The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter-7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/359-374 dated 29.06.2021 in respect of existing building (copy enclosed) shall be implemented by 30.09.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/GH/SZ/2017/448 dated 01.08.2017, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer P.V. Rathee

Dall 3/19/21

Asstt. Div. Officer (SRD)

DO (SW) - Medical Rest. A DY, CFO (\$Z) / Fit

ADOSPN