GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI No.F6/DFS/MS/GH/NDZ/2021/ 43 O Dated 27../9../2021

FIRE SAFETY CERTIFICATE

Certified that the New Amantran Guest House located at 5129, Main Bazar, Pahar Ganj, New Delhi comprised of Ground + 03 Upper floors, Ground floor (shops others), 1st floor (03 guest rooms + reception), 2nd floor (04 guest rooms), 3rd floor (02 guest rooms + staff room), total 09 guest rooms owned/occupied by New Amantran Guest House was granted FSC by this department vide letter No.F6/DFS/MS/GH/2018/NDZ/1004 dated 10/05/18. premise was re-inspected by the officers concerned of this department on 21/09/21 in the presence of Sh. Rahul (Manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 1st floor (03 guest rooms + reception), 2nd floor (04 guest rooms), 3rd floor (02 room), Total - 09 guest rooms only with effect from guest rooms + staff rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued ---27/9/-24-at New Delhi by.

(Dr. S. K. Tomar) Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID NO. 2021082919472 dated 29.08.21
- 2. The Manager,

New Amantran Guest House at 5129, Main Bazar, Pahar Gani, New Delhi.

Condition for the validity of fire safety certificate

- This clearance/ FSC shall stand cancelled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 29.06.2021 latest by 30.09.2021.
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT

New Amantran Guest House at 5129, Main 1. Name & address of the building Bazar, Pahar Ganj, New Delhi.

2. Type of occupancy:-Residential, Sub Division-A-1

Gr. + 03 Upper floors (total 09 Guest rooms) Ground floor (shops others), 1st floor (03 guest rooms + reception), 2nd floor (04 guest rooms), 3rd floor

(02 guest rooms + staff room)

3. Type of case:-Renewal

4. Details of previous FSC:-No. F6/DFS/MS/GH/2018/NDZ/1004 dated

N/A

10/05/18.

5. Fire safety directives No.-

6. Date of inspection:-

21/09/21 7. Name of the inspecting officer:-Sh. Ravinder Singh (ADO/CC)

Sh. Rajinder Atwal (DO/CD)

8. Name & designation of officer From the building side:-

9. Year of construction:-

10. Applicant's letter No:-

Sh. Rahul (Manager)

Old

2021082919472 dated 29.08.21.

10.	Applicant's letter No:-	202108291	19472 dated 29.08.2	Old Case	
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR	
1.	Access to Building				
	1) Road width	N/A	02 mtr.	MR	
	2) Gate width	N/A	N/A	N/A	
	3)Width of internal road	N/A	N/A	N/A	
2.	Number, Width Type & Art	rangement of E	Exits		
	A. Number of staircases				
	1. Upper floors	01 Nos.	01 Nos.	MR	
	2. Basements	N/A	N/A	N/A	
	B. Width of staircase				
	1. Upper floors	0.80 mtr.	0.80 to 1.01 mtr.	MR	
	2. Basements	N/A	N/A	N/A	
	C. Protection of exits				
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous staircase to terrace	N/A	N/A	N/A	
	E. Width of corridor	N/A	N/A	N/A	
	F. Door size	1 mtr.	1 mtr.	MR	
3.	Compartmentation				
	1) Fire check door	N/A	N/A	N/A	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	N/A	N/A	N/A	
4.	Smoke Management System				
	1) Basements	30 ACPH	N/A	N/A	
	2) Upper floors	Required as per G.N dated 27.05.19	Not provided	Last dt. 30.09.21 of compliance extended vide order dt. 29.06.21	

<u> </u>	Fire Extinguishers			E
5.	1) Total numbers	08 Nos.	08 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
		Required	7 70 71404	
6.	First-Aid Hose Reel	N/A	N/A	N/A
	1) Total number of eachfloor	N/A	N/A	N/A
	2) Length of hose reel hose		N/A	N/A
	3) Nozzle diameter	N/A		1
7.	Automatic Fire Detection & A	Required as	Not provided	Last dt.
	1) Type of detectors CO	per G.N	Not provided	30.09.21 of
	Type	dated		compliance
		27.05.19		extended
		27.03.17		vide order dt.
				29.06.21
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
	,	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	IN/A	IVA	11112
10.	Automatic Sprinkler System	N/A	N/A	N/A
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	IV/A	14/71	
4.4	ceiling			
11.	Internal Hydrants 1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor	IN/A	1777	14/71
	3) Hose box	N/A	N/A	N/A
10	Yard Hydrants	14/74	14/11	14/71
12.	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
12		14/11	14/14	IVA
13.	Pumping Arrangement 1) Ground level	N/A	N/A	NT/A
	,	N/A		N/A
	a) Discharge of main	IN/A	N/A	N/A
	pump	NI/A	NI/A	
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump		N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output		N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping			
	2) Terrace level			
	a) Discharge of pump	N/A	N/A	N/A
	b) Head of pump	N/A	N/A	N/A
	c) Power supply	N/A	N/A	N/A N/A
	d) Auto starting of pump	N/A	N/A	
			11/11	N/A

4.	Captive Water Storage for F		27/4	N/A
	1) Under ground tank	N/A	N/A	1472
	capacity	21/4	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank	N/A	IN/A	
b-	capacity	D. Jane	Provided	MR
5.	Exit Signage.	Required	Tiovided	
6.	Provision of Lifts.		27/4	N/A
	a) Pressurization of lift shaft	N/A	N/A	
	b) Pressurization of lift	N/A	N/A	N/A
	c) Communication in	N/A	N/A	N/A
	lift car d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
		Required	Provided	MR
17.	Stand by Power Supply	N/A	N/A	N/A
18.	Refuge Area Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
19.	a) Detector system	N/A	N/A	N/A
	panel b) Flow switch panel	N/A	N/A	N/A
		N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Systems Risk, if any:	tem for Protec	ction of special	N/A

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2018/NDZ/1004 dated 10/05/18 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor only.

Signatura of the Inspecting Officer

Signature of the Inspecting Officer

Name:- Rajinder Atwal Designation:- Do /CD

Name :- Ravinder Singh Designation: ADO (CC)

Sepora hum Pl