(-17



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2021/SZ/ 795

Dated: 29/9/2/

FIRE SAFETY CERTIFICATE

Certified that the S.D.M.C Primary School, New Jail Tillar, New Delhi-110064 comprised of two blocks namely Block-A & Block-B. Each block having ground floor only owned/occupied by S.D.M.C. was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2018/\$Z/2148 dated 19/09/2018. The school building was re- inspected by the officer concerned of this department on 20/09/2021 in the presence of Smt. Poonam Bhatla (Principal) and found that the School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on at New Delhi.

(SUNIL CHAWDHARY) DY.CHIEF FIRE OFFICER

Of S

Copy to:-

- The Principal,
   S.D.M.C Primary School,
   New Jail Tihar, New Delhi-110064
- Director of Education,
   S.D.M.C, Civic Centre,
   Minto Road, New Delhi-110001.

Following fire safety directives must be adhered to:-.

- .1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT 1. Name & address of the building: S.D.M.C Primary School, New Jail Tihar, New Delhi-110064. Building is comprised of Two blocks (Blk A & Blk B) Each block having Ground floor only. Type of Occupancy 3. Educational 4. Type of Case Renewal 5. Details of Previous NOC F.6/DFS/MS/School/2018/SZ/2148 dated 19/09/2018 6. Fire Safety directives letter No : Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 7. Date of inspection 20/09/2021 8. Name of Inspecting Officer A.D.O. R.K. Yadav 9. Name and designation of officers From the building side Smt. Poonam Bhatla (Principal) 10. Year of Construction 1965 11. Applicant's letter No. Nil dated 07/09/2021 S. No. Minimum Standards on fire prevention and Provided at Remarks Requirement fire safety U/R 33 MR/NMR site 1. Access to building Accessible (06 m) Road width MR 06 m 4.5 m Directly accessible MR Gate width N/A from road N/A Width of internal road N/A 2. Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors N/A N/A Ground floor only Basements N/A N/A N/A b. Width of staircases Upper Floor N/A N/A Ground floor only **Basements** N/A N/A N/A c. Protection of exits Fire check door Pressurization N/A N/A N/A N/A N/A N/A d. No. of continuous staircases to N/A N/A N/A terrace Width of Corridor N/A N/A N/A1.0 m 1.10 & 1.05 m M/RClass Room Door Size Compartmentation 3. N/A Fire check door N/A N/A Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A 4. Smoke Management System N/A N/A Basements N/A Upper floors N/A N/A N/A 5. Fire Extinguishers Total numbers 04 no's Provided M/R ABC/CO2 type Types Provided M/RIS marking ISI marked M/RISI marked 6. First-Aid Hose Reels Total numbers on each floor N/A  $N/\Lambda$  $N/\Lambda$ Length of hose reel hose N/A N/AN/ANozzle diameter N/A  $N/\Lambda$ N/A

N	/	15
	1 1	

	1 1 min oratom	and the second s		
Α	Automatic fire detection and alarming system	N/A	N/A	N/A
	<ul><li>Type of detectors</li><li>Location of Main Panel</li></ul>	N/A	N/A	N/A
	C D actor Danel	N/A	N/A	N/A
	<ul> <li>Location of Repeater Fanct</li> <li>Alternate source of power</li> </ul>	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A N/A
	According to the second	N/A	N/A	N/A N/A
	MOEFA	N/A	N/A	79/75
	Public Address System			
	Automatic Sprinkler System	1	N/A	N/A
	Basement	N/A	N/A	N/A
	<ul> <li>Ground Floor</li> </ul>	N/A	N/A	N/A
	<ul> <li>Sprinkler above false ceiling</li> </ul>	N/A	14/73	
	Internal Hydrants	N/A	N/A	N/A
	<ul> <li>Size of riser/down-comer</li> </ul>	N/A	N/A	N/A
	<ul> <li>Number of hydrants per floor</li> </ul>	N/A	N/A	N/A
	Hose Box	14//3		
	Yard Hydrants	N/A	N/A	N/A
	<ul> <li>Total number of hydrants</li> </ul>		N/A	N/A
	Hose Box	N/A	1	
3.	Pumping Arrangements			
	Ground Level	N/A	N/A	N/A
	<ul><li>Discharge of main Pump</li></ul>		N/A	N/A
	> Head of Main pump	N/A		N/A
	<ul><li>Number of main pumps</li><li>Jockey Pump out put</li></ul>	N/A	N/A	N/A
	> Jockey pump head	N/A	N/A	
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	Pump House Access			
	Terrace level	N/A	N/A	N/A
	Discharge of pump	N/A	N/A	N/A
	> Head of the pump	N/A	N/A	N/A
	<ul><li>Power Supply</li><li>Auto Starting of pump</li></ul>	N/A	N/A	N/A
	> Auto Starting of pump			
	Captive Water Storage for fire fighting			
14.	Underground tank capacity	N/A	N/A	N/A
	<ul> <li>Underground talk capacity</li> <li>Draw-off connection</li> </ul>	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
		N/A	N/A	N/A
15.	Exit Signage.	1772		
	Provision of Lifts.			(No Lift)
16.		2114	N/A	N/A
	<ul> <li>Pressurization of Lift Shaft</li> </ul>	N/A		N/A
	<ul> <li>Pressurization of Lift lobby</li> </ul>	N/A	N/A	N/A N/A
	<ul> <li>Communication In lift Car</li> </ul>	N/A	N/A	
	Fireman's Grounding Switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
		N/A	N/A	N/A
		IN/A		
17.	Standby power supply			
	- a Aa		N/A	N/A
18.	Refuge Area.  Total Area	N/A		
10.	> Total Area	21/4	N/A	N/A
101	> Location	N/A		

N		16
---	--	----

	<ul> <li>PA System Panel</li> <li>Battery backup</li> <li>Building Floor Plans</li> </ul>	N/A N/A N/A	N/A N/A N/A	N/A N/A N/A	
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2018/SZ/2148 dated 19/09/2018 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name:- R.K.Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West) on leave F. J.

Pycro (\$2)

A MANN P

F. T. helter us put up for sophature plan

Pycro(\$2)

M.S. M.