

C-50



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**


No. F6/DFS/MS/GH/SZ/2021/ 423

Dated: 24/9/21

FIRE SAFETY CERTIFICATE

Certified that M/s. Silver Stone guest house located at 13A/22, B.C. Marg, Karol Bagh, New Delhi- 110005, was granted FSC for building comprised of basement, ground plus three upper floors, using basement as hall/storage, ground floor as reception, lobby, office & shops, first, second & third floor each having 05 guest rooms respectively (total 15 guest rooms) and a pantry for staff in temporary shed on terrace by this department vide letter No. F6/DFS/MS/GH/SZ/2018/1727 dated 24.07.2018. The premises was re-inspected by the officer concerned of this department on 22.09.2021 in presence of Sh. Bhupesh Pathak, manager and found that the guest house have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) for **ground floor (reception & office), first, second & third floor each having 05 guest rooms respectively (total 15 guest rooms only)** with effect from 24/9/21 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed back side.

Issued on 24/9/21 at New Delhi by.


(Sunil Chaudhary)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service
01/9/21

Copy to:-

1. The Owner/Occupier, M/s. Silver Stone guest house, 13A/22, B.C. Marg, Karol Bagh, New Delhi- 110005.
2. The Joint C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.

Following Fire Safety Directives must be adhered to: -

1. **The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/359-374 dated 29.06.2021 in respect of existing building (copy enclosed) shall be implemented by 30.09.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void**
2. No occupancy above third floor & fourth floor sealed by owner and basements of building has other ownership and have separate entry and exit from guest house building, shall be adhered by Owner/Occupier
3. All the means of escape shall be kept free of all type of obstruction all the time.
4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
6. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
7. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
8. All comments / directions of licensing department shall always be permitted and followed.
9. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
10. The owner / occupier shall apply for renewal of this **Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37)** along with copy of the certificate, six months prior to its expiry.
11. Basement shall be used as per BBL.
12. No temporary shed is allowed on terrace.
13. The Fire Safety Certificate is only for Guest Rooms.

INSPECTION REPORT

1. Name & address of the building : M/s. Silver Stone guest house, 13A/22, B.C. Marg, Karol Bagh, New Delhi- 110005.
2. Type of Occupaney : Lodging House
3. Type of Case : Renewal
4. Details of previous NOC : F6/DFS/MS/GH/SZ/2018/1727 dated 24.07.2018
5. Fire Safety directives letter No : Nil
6. Date of inspection : 22.09.2021
7. Name of the Inspecting Officers : P.V. Rathee, Asst. Divisional Officer (SRD)
8. Name and designation of officers from the building side : Sh. Bhupesh Pathak, manager
9. Year of Construction : 2010-11
10. Applicant's letter No. : Online Application no. 2021072415777 dated 22.09.2021

The said guest house building is comprised of basement, ground plus four upper floors.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Fire safety requirements as per FSC dt. 24.07.2018	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	06 mts	Provided	MR
	• Gate width	4.5mts	Directly accessible from the road	MR
	• Width of internal road	N/A	N/A	N/A
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases	-	-	-
	• Upper Floors	01	01	MR being old case
	• Basements	01	01	MR being old case
	b. Width of staircases	-	-	-
	• Upper Floors	1.25 mts	1.30 mts	MR being old case
	• Basements	Old case	1.10 mts.	MR being old case
	c. Protection of exits	-	-	-
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	e. No. of continuous staircases to terrae	01	01	MR
	g. Width of Corridor	1.0 mt.	1.30 mts	MR
	h. Door Size	1.0 mt.	0.84 mts	MR being old case
3	Compartmentation.			
	• Fire check door	N/A	N/A	N/A
	• Sealing of electrical shafts	N/A	Sealed	----
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4	Smoke Management System.			
	• Basements	30 a/c per hour	Exhaust fan provided	MR
	• Upper floors	12 a/c per hour	Not Provided	date of compliance has been extended up to 30.09.2021
5	Fire Extinguishers			
	• Total numbers	14	Provided	MR
	• Types	CO ₂ , ABC, WCO, ISI marked	Provided	MR
	• IS marking		Provided	MR

N-19

N/A

N/A

N-18

6	First-Aid Hose Reels.				MR
	• Total numbers on each floor	01	Provided		MR
	• Length of hose reel hose	30 m	Provided		MR
	• Nozzle diameter	5 mm	Provided		MR
7	Automatic fire detection and alarming system.				date of compliance has been extended up to 30.09.2021
	• Type of detectors	Carbon Monoxide	Not Provided		date of compliance has been extended up to 30.09.2021
	• Location of Main Panel	Required	Not Provided		N/A
	• Location of Repeater Panel	N/A	N/A		MR
	• Alternate source of power	Required	Provided		N/A
	• Hooters' Location	N/A	N/A		MR
8	MOEFA	Required	Provided		MR
9	Public Address System.	Required	Provided		MR
10	Automatic Sprinkler System.				Area less than 200 sq. mts.
	• Basement	N/A	Provided		N/A
	• Upper Floor	N/A	N/A		N/A
	• Sprinkler above false ceiling	N/A	N/A		N/A
11	Internal Hydrants				N/A
	• Size of riser/down-comer	N/A	N/A		N/A
	• Number of hydrants per floor	N/A	N/A		N/A
	• Hose Box	N/A	N/A		N/A
12	Yard Hydrants.				N/A
	• Total number of hydrants	N/A	N/A		N/A
	• Hose Box	N/A	N/A		N/A
13	Pumping Arrangements.				---
	• Ground Level	---	---		N/A
	➤ Discharge of main Pump	N/A	N/A		N/A
	➤ Head of Main pump	N/A	N/A		N/A
	➤ Number of main pumps	N/A	N/A		N/A
	➤ Jockey Pump out put	N/A	N/A		N/A
	➤ Jockey pump head	N/A	N/A		N/A
	➤ Standby Pump out put	N/A	N/A		N/A
	➤ Standby Pump Head	N/A	N/A		N/A
	➤ Auto Starting/ Manual stopping	N/A	N/A		N/A
	➤ Pump House Access	N/A	N/A		N/A
	• Terrace level	-----	-----		-----
	➤ Discharge of pump	450 LPM	Provided		MR
	➤ Head of the pump	30 mts	Provided		MR
	➤ Power Supply	Required	Provided		MR
	➤ Auto Starting of pump	N/A	N/A		N/A
14	Captive Water Storage for fire fighting.				N/A
	• Underground tank capacity	N/A	N/A		N/A
	➤ Draw-off connection	N/A	N/A		N/A
	➤ Fire service inlet	N/A	N/A		N/A
	➤ Access to tank	N/A	N/A		N/A
	• Overhead Tank capacity	Old Case	Provided (4000 lts)		MR being old case
		Required	Provided		MR
15	Exit Signage.				
16	Provision of Lifts.				

	<ul style="list-style-type: none"> Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A
		N/A	N/A	N/A
		Required	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
17	Standby power supply	Required	Provided	MR
18	Refuge Area.	Required	Provided	MR
	➤ Total Area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19	Fire Control Room			
	<ul style="list-style-type: none"> Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were checked and found functional at the time of inspection. The basements of building has other ownership and have separate entry and exit from guest house building and fourth floor sealed by the owner. Guest house management given an undertaking in this matter at C-42

The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/359-374 dated 29.06.2021 in respect of existing building (copy enclosed) shall be implemented by 30.09 .2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/DFS/MS/GH/SZ/2018/1727 dated 24.07.2018, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

D.O. (SW) - On M (Rest)

Dy. C.O. (SZ) F.T.

[Handwritten signature]

[Handwritten signature] 23/9/21

Signature of the Inspecting Officer
P.V. Rathee
Asstt. Div. Officer (SRD)

ADD SPD