

C-37

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**


No. F.6/DFS/MS/GH/SZ/2021/ 410

Dated: 23/9/21

FIRE SAFETY CERTIFICATE

Certified that **M/s. Gagan Guest House located at Cottage No.- 15, West Patel Nagar, New Delhi- 110008** was granted FSC for building comprised of basement, stilt, ground plus three upper floors, using basement as storage, stilt as parking, ground floor using as reception plus 07 guest rooms, first floor having 07 guest rooms, second floor having 06 guest rooms & third floor having 05 guest rooms, (total 25 guest rooms) by this department vide letter No. F6/DFS/MS/GH/SZ/2018/1846 dated 08.08.2018. The premises was re-inspected by the officer concerned of this department on 20.09.2021 in presence of Sh. Gagandeep Singh, owner of the guest house and found that the guest house have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) **for basement (incidental storage), stilt floor (parking), ground floor (Reception & 07 guest rooms), first floor (07 guest rooms), second floor (06 guest rooms) & third floor(05 guest rooms) (total 25 guest rooms only)** with effect from 23/9/21 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed back side.

Issued 23/9/21 at New Delhi by.


(Sunil Chaudhary)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service

Copy to:-

1. Sh. Gagan Deep Singh (Owner), M/s. Gagan Guest House, Cottage No.- 15, West Patel Nagar, New Delhi- 110008.
2. The Joint C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.

Following Fire Safety Directives must be adhered to: -

1. **The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/359-374 dated 29.06.2021 in respect of existing building (copy enclosed) shall be implemented by 30.09.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void**
2. No occupancy above third floor & basement as storage purpose, shall be adhered by Owner/Occupier
3. All the means of escape shall be kept free of all type of obstruction all the time.
4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
6. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
7. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
8. All comments / directions of licensing department shall always be permitted and followed.
9. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
10. The owner / occupier shall apply for renewal of this **Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37)** along with copy of the certificate, six months prior to its expiry.
11. Basement shall be used as per BBL.
12. No temporary shed is allowed on terrace.
13. The Fire Safety Certificate is only for Guest Rooms.

INSPECTION REPORT

H-7

1. Name & address of the building : M/s. Gagan Guest House, Cottage No.- 15, West Patel Nagar, New Delhi- 110008
2. Type of Occupancy : Lodging House
3. Type of Case : Renewal
4. Details of previous NOC : F6/DFS/MS/GH/SZ/2018/1846 dated 08.08.2018
5. Fire Safety directives letter No : Nil
6. Date of inspection : 20.09.2021
7. Name of the Inspecting Officers : P.V. Rathee, Asst. Divisional Officer (SRD)
8. Name and designation of officers from the building side : Sh. Gagan Deep Singh, owner
9. Year of Construction : 2010
10. Applicant's letter No. : Online Application no. 2021072916260 dated 11.09.2021

The said guest house is comprised of basement, stilt, ground plus three upper floors.

| S. No. | Minimum Standards on fire prevention and fire safety U/R 33 | Fire safety arrangements as per FSC dt. 08.08.2018 | Provided at site | Remarks MR/NMR |
|--------|---|--|----------------------|---|
| 1 | Access to building | | | |
| | • Road width | 06 mts | Provided (15mts) | MR |
| | • Gate width | 4.5 mts | Directly accessible | MR |
| | • Width of internal road | N/A | N/A | N/A |
| 2 | Number, Width, Type & Arrangement of Exits | | | |
| | a. Number of staircases | - | - | - |
| | • Upper Floors | 01 | 01 | MR |
| | • Basements | 01 | 01 | MR |
| | b. Width of staircases | - | - | - |
| | • Upper Floors | 1.25 mts | 1.50 mts | MR |
| | • Basements | 1.25 mts each | 1.35 mts | MR |
| | c. Protection of exits | - | - | - |
| | • Fire check door | Required | Not Provided | date of compliance has been extended up to 30.09.2021 |
| | • Pressurization | N/A | N/A | N/A |
| | e. No. of continuous staircases to terrace | 01 | 01 | MR |
| | g. Width of Corridor | N/A | N/A | N/A |
| | h. Door Size | 1.25 mts | 1.25 mts | MR |
| 3 | Compartmentation. | | | |
| | • Fire check door | Required | Not Provided | date of compliance has been extended up to 30.09.2021 |
| | • Sealing of electrical shafts | Required | Provided | MR |
| | • Fire Rating of shaft door | N/A | N/A | N/A |
| | • Water Curtain | N/A | N/A | N/A |
| | • Fire Dampers | N/A | N/A | N/A |
| 4 | Smoke Management System. | | | |
| | • Basements | 30 a/c per hour | Exhaust fan provided | MR |
| | • Upper floors | 12a/c per hour | Not Provided | date of compliance has been extended up to 30.09.2021 |
| 5 | Fire Extinguishers | | | |
| | • Total numbers | 16 | Provided | MR |
| | • Types | CO ₂ , ABC | Provided | MR |
| | • IS marking | ISI marked | Provided | MR |

11-8

| | | | | |
|----|--|-----------------|----------------------------|---|
| 6 | First-Aid Hose Reels. | | | |
| | • Total numbers on each floor | 01 | Provided | MR |
| | • Length of hose reel hose | 30 m | Provided | MR |
| | • Nozzle diameter | 5 mm | Provided | MR |
| 7 | Automatic fire detection and alarming system. | | | |
| | • Type of detectors | Carbon Monoxide | Not Provided | date of compliance has been extended up to 30/09/2021 |
| | • Location of Main Panel | Required | Not Provided | date of compliance has been extended up to 30/09/2021 |
| | • Location of Repeater Panel | N/A | N/A | N/A |
| | • Alternate source of power | Required | Provided (D/G set 125 KVA) | MR |
| | • Hooters' Location | N/A | N/A | N/A |
| 8 | MOEFA | Required | Provided | MR |
| 9 | Public Address System. | Required | Provided | MR |
| 10 | Automatic Sprinkler System. | | | |
| | • Basement | Required | Provided | MR |
| | • Upper Floor | N/A | N/A | N/A |
| | • Sprinkler above false ceiling | N/A | N/A | N/A |
| 11 | Internal Hydrants | | | |
| | • Size of riser/down-comer | N/A | Provided | N/A |
| | • Number of hydrants per floor | N/A | 01 | N/A |
| | • Hose Box | N/A | 01 | N/A |
| 12 | Yard Hydrants. | | | |
| | • Total number of hydrants | N/A | N/A | N/A |
| | • Hose Box | N/A | N/A | N/A |
| 13 | Pumping Arrangements. | | | |
| | • Ground Level | --- | --- | --- |
| | ➤ Discharge of main Pump | N/A | N/A | N/A |
| | ➤ Head of Main pump | N/A | N/A | N/A |
| | ➤ Number of main pumps | N/A | N/A | N/A |
| | ➤ Jockey Pump out put | N/A | N/A | N/A |
| | ➤ Jockey pump head | N/A | N/A | N/A |
| | ➤ Standby Pump out put | N/A | N/A | N/A |
| | ➤ Standby Pump Head | N/A | N/A | N/A |
| | ➤ Auto Starting/ Manual stopping | N/A | N/A | N/A |
| | ➤ Pump House Access | N/A | N/A | N/A |
| | • Terrace level | ----- | ----- | ----- |
| | ➤ Discharge of pump | 900 LPM | Provided | MR |
| | ➤ Head of the pump | 30 mts | Provided | MR |
| | ➤ Power Supply | Required | Provided | MR |
| | ➤ Auto Starting of pump | Required | Provided | MR |
| 14 | Captive Water Storage for fire fighting. | | | |
| | • Underground tank capacity | N/A | N/A | N/A |
| | ➤ Draw-off connection | N/A | N/A | N/A |
| | ➤ Fire service inlet | N/A | Provided | N/A |
| | ➤ Access to tank | N/A | N/A | N/A |
| | • Overhead Tank capacity | 10,000 lts | Provided | MR |
| 15 | Exit Signage. | Required | Provided | MR |

12

| | | | | |
|----|--|----------|----------|-----|
| 16 | Provision of Lifts. | | | |
| | • Pressurization of Lift Shaft | N/A | N/A | N/A |
| | • Pressurization of Lift lobby | N/A | N/A | N/A |
| | • Communication In lift Car | Required | Provided | MR |
| | • Fireman's Grounding Switch | Required | Provided | MR |
| | • Lift Signage | Required | Provided | MR |
| 17 | Standby power supply | Required | Provided | MR |
| 18 | Refuge Area. | | | |
| | ➤ Total Area | N/A | N/A | N/A |
| | ➤ Location | N/A | N/A | N/A |
| 19 | Fire Control Room | | | |
| | • Detector System Panel | N/A | N/A | N/A |
| | • Flow Switch Panel | N/A | N/A | N/A |
| | • PA System Panel | N/A | N/A | N/A |
| | • Battery backup | Required | Provided | MR |
| | • Building Floor Plans | N/A | N/A | N/A |
| 20 | Special Fire Protection Systems for Protection of special Risks, if any: | N/A | N/A | N/A |

The fire protection systems provided in the building were checked and found functional at the time of inspection.

The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/359-374 dated 29.06.2021 in respect of existing building (copy enclosed) shall be implemented by 30.09.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/DFS/MS/GH/SZ/2018/1846 dated 08.08.2018, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

[Handwritten Signature]

Signature of the Inspecting Officer
P.V. Rathee
Asstt. Div. Officer (SRD)

D.O (SW) - on medical Rest.

Dy. CFO (EZ)

A. P. S. R.

[Handwritten Signature]