

# GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI – 110001

F6/DFS/MS/GH/NDZ/2021 461

Dated:  $\frac{30}{9/2}$ 

### FIRE SAFETY CERTIFICATE

Certified that the M/s Aslam Guest House Located at 501, Gali Matia Mahal, Jama Masjid, Delhi, comprised of Ground + 03 upper floors, Ground floor: Commercial use, 1st floor - 08 guest rooms + reception, 2<sup>nd</sup> floor- 08 guest rooms, 3<sup>rd</sup> floor -09 guest rooms, total 25 guest room was granted FSC by this department vide letter no. F6/DFS/MS/GH/NDZ/2018/1603 dated 11.07.2018. The building/premises was re-inspected by Assistant Divisional Officer (SPM) from this department on 28.09.2021 in presence of the Manager and found that building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of "Group A-1 (Residential)" Sub Division - for total 25 guest rooms 1st floor - (08 guest rooms), 2nd floor- (08 guest rooms), 3rd floor -09 guest rooms, renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on .....at New Delhi by

(Dr. S.K. Tomar)

(X10mm)

Dy. Chief Fire Officer

Tel: 011-23412025

- Copy to:
  1. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New
- 2. The Licensee the M/s Aslam Guest House Located at 501. Gali Matia Mahal, Jama Masjid, Delhi-06.

#### Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. .Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

## H126

# INSPECTION REPORT

1.	Name and address of the building:	M/s Aslam Guest House Located at 501,			
		Gali Matia Mahal, Jama Masjid, Delhi.			
2.	Type of occupancy with details of floors:	Ground + 03 upper floors			
		Ground floor – Commercial use  1 <sup>st</sup> floor - 08 guest rooms + reception  2 <sup>nd</sup> floor- 08 guest rooms  3 <sup>rd</sup> floor -09 guest rooms			
3.	Type of case:	Renewal			
4.	Details of previous FSC:	F6/DFS/MS/GH/NDZ/2018/1603 dated			
		11.07.2018			
5.	Fire safety directives no.:	Nil			
6.	Date of inspection:	28.09.2021			
7.	Name of the inspecting officer:	Rajesh Kumar Shukla ADO (SPM)			
8.	Name and designation of the officer	Manager			
	from the building side:				
9.	Year of construction:	Old			
10.	Reference letter no.:	Email dated 17.09.2021.			

S.N	No M	Iinimum standard of Fire revention and Fire Safety U/R 33	Requirements (Existing Fire & Safety Measures)	Provide at site (PSS)	Remark s MR/ NMR
1	A	ccess to Building.		10.42	NA
	A		NA (special area)	2.43 mtrs.	NA NA
	B		NA	NA	NA NA
	C		NA	NA	NA
2	N	umber, Width, Type & Arrangeme	ent of Exits.		
	A	No. of Staircase:		,	2.60
		a) Upper floor	01 nos.	01 nos.	MR
		b) Basements	NA	NA	NA
	В	Width of the Staircase:		1.10	MD
	-	a) Upper floors	0.80 mtrs.	1.10 mtrs.	MR
		b) Basements	NA	NA	NA
	C	Protection of Exits		T	274
		a) Fire check door	NA (no. of beds per floor <10)	NA	NA
		b) Pressurization	NA	NA	NA
	D	No. of continuous staircase to terrace:	NA	NA	NA
	F	Width of the corridor	NA	NA	NA
	E	Door size	1.25 mtrs.	1.25 mtrs.	MR
3	Cor	npartmentation:		•	
	A	Fire check doors	NA	NA	NA
	В	Sealing of electrical shafts	NA	NA	NA
	$\overline{\mathbf{C}}$	Fire rating of shaft doors	NA	NA	NA
	D	Water curtain	NA	NA	NA
	E	Fire dampers	NA	NA	NA
4	Smo	oke management System:			
-	A	Upper floors	Natural/Mechanical	Natural	MR
	В	Basements	NA	NA	NA
5	Fire	extinguishers.	1		
+	A	Total numbers	06 no.	08 no.	MR
	В	Types	CO2, ABC	CO2, ABC	MR
-	C	ISI marking	Required	Provided	MR

	First	Aid Hose reel.			MD
	A	Total no. at each floor	l nos.	1 nos.	MR
	В	Length of hose reel	30 mm	30 mm	MR
	C	Nozzle diameter	5 mm	5 mm	MR
	Auto	matic Fire Detection and Alarr	n System (ADA!	5).	
	A	Type of detectors -(CO)	CO detectors	Provided	MR
		detector	(required as per		
			GN dated		
	-		27.05.2019)	Provided	MR
	В	Location of main Panel	At reception	Provided	
	-		(at 1 <sup>st</sup> floor)	NA	NA
	C D	Location of repeater panel	NA NA	NA	NA
	E	Alternate power Source Hooter's location	At every floor	Provided	MR
8	-	EFA.	NA	NA	NA
9	-		Required	Provided	MR
		lic Address System.	Required	Tiovided	
10	Aut	omatic Sprinkler System.  Basement	NA	NA	NA
	B	Upper floor	NA	NA	NA
	С	Sprinklers above false ceiling	NA	NA	NA
11	_	ernal Hydrants.	1.77.	1	
1.1	A	Size of the riser/down comer	NA	NA	NA
	В	No. of hydrants per floor	NA	NA	NA
	C	Hose box	NA	NA	NA
12		rd Hydrants.	1		
	A	Total no. of hydrants	NA	NA	NA
	В	Hose box	NA	NA	NA
13		mping arrangements.			
	I	Ground Level			1
		a) Discharge of main	NA	NA	NA
		p <b>um</b> p		1	NIA
		b) Head of main pump	NA	NA	NA
		c) Number of main pump	NA	NA	NA
		d) Discharge of jockey	NA	NA	NA
		p <b>um</b> p	37.4	NIA	NA
		e) Head of jockey pump	NA	NA NA	NA
		f) Discharge of standby	NA	IN/A	1471
		pump	NA	NA	NA
		<ul><li>g) Head of standby pump</li><li>h) Auto starting/ manual</li></ul>	NA NA	NA	NA
		,	1		
	77	stopping Terrace Level			
	II	0	225 LPM	225 LPM	MR
			223 21 171		
		<ul><li>pump</li><li>b) Head of terrace pump</li></ul>	40 meters	40 meters	MR
		and the state of t	Required	Provided	MR
			Required	Provided	MR
	-	d) Auto starting of pump uptive Water Storage for Fire F			
14	SALITY OF STREET	Underground tank capacity	NA	NA	NA
	A	Draw off connection	NA	NA	NA
	В	Fire service inlet	NA	NA	NA
	C	Access to tank	NA	NA	NA
	E	Overhead tank capacity	2500 litres	2500 litres	MR
	D		Required	Provided	MR
15		it Signage. ovision of lift.			
16	THE RESERVE THE PERSON NAMED IN COLUMN TWO	Pressurization of lift shaft	NA	NA	NA
	A	Pressurization of lift lobby	NA	NA	NA
	В	Communication in lift car	NA	NA	NA
	Ç	Fireman switch	NA	NA	NA
	D		NA	NA	NA
	E	Lift signage andby Power Supply.	Required	Provided	MR

18	Refuge Area.				
	A	location	NIA	NI	
	B	Total area	NA	NA	NA
19	Fire Control Room.				
	A	Fire detection system panel	NA	NA	NI.A
	В	Flow switch panel	NA NA	NA	NA
	C	P A system panel		NA	NA
	D	Battery backup	NA NA	NA	NA NA
	E	Building floor plan	NA NA	NA	NA
20	Sp	ecial Fire Protection for special r	ials if any	IVA	NA

Meeting requirement (MR), Not meeting requirement (NMR), Not applicable (NA), Provided but not functional (PNF).

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

The guest house has complied with the applicable provisions of gazette notification dated 27.05.2019 i.e CO detectors were found provided and functional at the time of inspection.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2018/1603 dated 11.07.2018 is recommended to be renewed under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer Name Rajesh Kumar Shukla

Designation ADO (SPM)

(AD2) 1. F. M. pl. 2. Pl. correct-ladjust inspection profone

1. Fi iet peut up ple.
2. Margier of the inspection performa have boon readjusted.

cro (ND2)

MS