

C26

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/EH/SZ/2021/ 262

Dated: 30/09/2021

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s **Upgrade Kitchen & Bar** (A unit of Urban Gala), Shop No-42, 43, 44, First Floor, India Mall, Community Centre, New Friends Colony, New Delhi-110025, comprised of Basement, Ground plus 02 upper floors but the restaurant running at 1st Floor was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/EH/2018/SZ/2094 dated 13/09/2018. The premise was re-inspected by the officer concerned of this department on 28/09/2021 in the presence of Mr. Bharat Chhabra and observed that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the said premises is fit for occupancy class "**Group-D Assembly**" with effect from 30/09/2021 for a period of **Three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued on 30/09/2021 at New Delhi by

(Sunil Chawdhary)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service

Copy to: -

1. The Dy. Health Officer, South MCD, Public Health Department, Central Zone, Lajpat Nagar, New Delhi-110024
2. M/s Upgrade Kitchen & Bar (A unit of Urban Gala), Shop No-42, 43, 44, First Floor, India Mall, Community Centre, New Friends Colony, New Delhi-110025

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire-fighting system.
4. The owner/occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

INSPECTION REPORT

1	Name & Address of the Building	M/s Upgrade Kitchen & Bar (A unit of Urban Gala), Shop No- 42, 43, 44, FF, India Mall, Community Centre, New Friends Colony, New Delhi-110025		
2	Type of Occupancy	Assembly Building "Group-D" Restaurant		
3	Building comprised of	Basements, Ground + 02 upper floors.		
4	Type of Case	Renewal		
5	Details of Previous NOC	F.6/DFS/MS/EH/2018/SZ/2094 dated 13/09/2018		
6	Fire Safety Directives Letter No	Nil		
7	Date of Inspection	28/09/2021		
8	Name of the Inspecting Officers	DO (SD)		
9	Name & Designation of Officers from the building side	Mr. Bharat Chhabra		
10	Year of construction	1999	Restt. at FF of mall building	
11	Applicant letter No.	Online ID-2020092407283 dated 24/09/2020		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC Requirement	Provided at Site	Remarks MR/NMR
1	Access to Building.	(No. F.6/DFS/MS/Cinema/2018/SZ/1519 dated 29/06/2018)		
	<ul style="list-style-type: none"> Road width Gate width Width of internal road 	Restt located within India Mall	As above -NA- -NA-	MR -NA- -NA-
2	Number, width, type & arrangement of exits	Provided & Maintained by Mall Mgmt.		
	a. Number of Staircase	2 Nos	As above	MR
	<ul style="list-style-type: none"> Upper floors Basement floor 	-NA-	As above	-NA-
	b. Width of Staircase	Provided & Maintained by Mall Mgmt.		
	<ul style="list-style-type: none"> Upper floors Basement floor 	1.5m -NA-	As above As above	MR -NA-
	c. Protection of exits	Provided & Maintained by Mall Mgmt.		
	<ul style="list-style-type: none"> Fire check door Pressurization 	-NA- -NA-	As above As above	-NA- -NA-
	d. No. of continuous staircase to terrace	Required	As above	MR
	e. Width of corridor	N/A	N/A	N/A
	f. Door size	2 exits	2m & 1.5m	MR
3	Compartmentation.	Provided & Maintained by Mall Mgmt.		
	<ul style="list-style-type: none"> Fire check door. Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. 	-NA- -NA- -NA- -NA- -NA-	As above As above As above As above As above	-NA- -NA- -NA- -NA- -NA-
4	Smoke Management system.	Provided & Maintained by Mall Mgmt.		
	<ul style="list-style-type: none"> Basement Upper floors 	30 ACPH 12 ACPH	N/A Provided in kitchen	N/A MR
5	Fire Extinguishers.	Provided & Maintained by Mall Mgmt.		
	<ul style="list-style-type: none"> Total numbers Types ISI Marking 	04 Nos. ABC / CO2 ISI marked	Provided ABC & CO2 Provided	MR MR MR
6	First Aid Hose Reels.	Provided & Maintained by Mall Mgmt.		
	<ul style="list-style-type: none"> Total numbers on each floor. Length of hose-reel hose. Nozzle Diameter 	One 30m 5mm	Provided Provided Provided	MR MR MR


		(Provided & Maintained by Mall Mgmt.)		
7	Automatic fire detection & alarming system.			
	• Type of detectors	N/A	As above	N/A
	• Location of Main Panel	N/A	As above	N/A
	• Location of Repeater Panel	N/A	As above	N/A
	• Alternate source of power	N/A	As above	N/A
	• Hooper's location	N/A	As above	N/A
8	MOEFA	Required	Provided	MR
9	Public Address System	-NA-	As above	-NA-
10	Automatic Sprinkler System	Provided & Maintained by Mall Mgmt.		
	• Basement	-NA-	As above	-NA-
	• Upper floors	-NA-	As above	-NA-
	• Sprinkler above false ceiling	-NA-	As above	-NA-
11	Internal Hydrants.	Provided & Maintained by Mall Mgmt.		
	• Size of Riser/Down-comer	Required	As above	-NA-
	• Number of Hydrant per floor	-NA-	As above	-NA-
	• Hose box.	-NA-	As above	-NA-
12	Yard Hydrants.	Provided & Maintained by Mall Mgmt.		
	• Total number of hydrants.	-NA-	As above	-NA-
	• Hose box.	-NA-	As above	-NA-
13	Pumping arrangements.	Provided & Maintained by Mall Mgmt.		
	• Ground Level	-NA-	2400 LPM	-NA-
	➤ Discharge of main pump.	-NA-	50m	-NA-
	➤ Head of main pump.	-NA-	One	-NA-
	➤ Number of main pumps.	-NA-	220 LPM	-NA-
	➤ Jockey Pump output.	-NA-	50m	-NA-
	➤ Jockey Pump head.	-NA-	2400 LPM	-NA-
	➤ Standby Pump output.	-NA-	50m	-NA-
	➤ Standby Pump head.	-NA-	Provided	-NA-
	➤ Auto Starting / Manual Stopping.	-NA-	Provided	-NA-
	➤ Pump House Access	-NA-		
	• Terrace Level	Provided & Maintained by Mall Mgmt.		
	➤ Discharge of pump.	450 LPM	As above	MR
	➤ Head of pump.	40m	As above	MR
	➤ Power supply.	Required	As above	MR
	➤ Auto starting of pump.	Required	As above	MR
14	Captive water storage for Fire Fighting.	Provided & Maintained by Mall Mgmt.		
	• Underground tank capacity.	-NA-	2,00,000 Ltrs	-NA-
	➤ Draw-off connection.	-NA-	Provided	-NA-
	➤ Fire Service Inlet.	-NA-	Provided	-NA-
	➤ Access to tank.	-NA-	Provided	-NA-
	• Overhead tank capacity.	10,000 Ltrs	25,000 Ltrs	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	Provided & Maintained by Mall Mgmt.		
	• Pressurization of lift shaft.	-NA-	As above	-NA-
	• Pressurization of lift lobby.	-NA-	As above	-NA-
	• Communication in lift car.	-NA-	As above	-NA-
	• Fireman's switch.	-NA-	As above	-NA-
	• Lift signage.	-NA-	As above	-NA-
17	Standby Power Supply	Required	As above	MR
18	Refuge Area			
	• Total area	-NA-	-NA-	-NA-
	• Location	-NA-	-NA-	-NA-

19	Fire Control Room.			
	• Detector System Panel.	-NA-	As above	-NA-
	• Flow Switch Panel.	-NA-	As above	-NA-
	• PA system Panel.	-NA-	As above	-NA-
	• Battery backup	-NA-	As above	-NA-
	• Building floor plan	-NA-	As above	-NA-
20	Special Fire Protection System for the Protection of special Risk, if any :	-NA-	As above	-NA-



The Fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F.6/DFS/MS/EH/2018/SZ/2094 dated 13/09/2018, renewal under Rule 37 of the Delhi Fire Service Rules, 2010 is recommended.


Accordingly, DFA is put up for approval and signature please.


 Signature of the Inspecting Officer
 Name: S.K. Dua
 Design: DO (SD)


DCFO (SZ)

F.T.


 D.O.S.A.

F.T. letter is put up for sig. pl.

DCFO (SZ)


M.S. Cell
 Uploaded
 30/9


 30/9/21