

💜 No. F6/DFS/MS/EH/SZ/2021/ 🔰 2 🖇 🕫

FIRE SAFETY CERTIFICATE

Dated: 08/10/21

(Atul(Garg)) Director OLDelhi Fire Service

Certified that the M/s. EVVA Restaurant (a unit of salt and straw LPP), 30-B, Third Floor, Pusa Road, Old Rajinder Nager, New Delhi - 110060, , running at third floor of a building comprised of basement, stilt, ground plus three upper floors, owned/occupied by Saurabh Chhabra, Mayank Sabharwal, Neha Paul & Rajat Jain have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officers concerned of Fire Service on 09.09.2021 in presence of Mr. Rajat Jain (Owner) and the building/premises is fit for occupancy class assembly (restaurant) running at third floor only with effect from $\frac{\sigma_s}{10}$ for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued on 08/(0/2) at New Delhi by.

Copy to:-

- Ac

- 1. Sh. Rajat Jain (Owner), M/s. Evva Restaurant (A unit of salt and straw LLP), 30-B, Third Floor, Pusa Road, Old Rajinder Nagar, New Delhi- 110060.
- 2. The Deputy Health Officer, North Delhi Municipal Corporation, Karol Bagh Zone, New Delhi- 110005.
- The Joint Commissioner of Police (Lic), 1st Floor, Police Station Defence Colony, New Delhi- 110024.

Conditions for the validity of Fire Safety Certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained firefighting staffs should be available round the clock.
- Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- All the means of escapes /exits shall not be locked/bolted/blocked at any time for safe evacuation of the occupants in case of any emergency.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

			POR	

6-5

M-4

1. Name & address of the building	: M/s. Evva Restaurant (Evva a unit of salt and straw LLP), Plot No. 30B, third floor, Old Rajender Nagar, Pusa Road, New Delhi.
2. Building Composition	: Basement, stilt, ground plus three upper floors.
3. Type of Occupancy	: Assembly (Restaurant)
4. Type of Case	: New Case
5. Details of previous NOC	: Nil
6. Fire Safety directives letter No	: Níl
7. Date of inspection	: 09.09.2021
8. Name of the Inspecting Officers	: D.B. Mukharjee, DO (SWD) & P.V. Rathee, ADO (SRD)
9. Name and designation of officer	5
from the building side	: Mr.Rajat Jain (Owner)
9. Year of Construction	: 2021

10. Applicant's letter No. : Online application Id 2021090119711 dated 07.09.2021 The said restaurant is running at third floor of a building comprised of basement, stilt, ground plus three upper floors, and the building was issued FSC vide letter no. F.6/DFS/MS/SZ/2021/409 dt. 23.08.2021

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per NBC/BBL	Provided at site	Remarks MR/NMR			
1	Access to building		1				
	• Road width	06mts	Provided	MR			
	• Gate width	4.5 mts	Provided	MR			
	• Width of internal road	N/A	N/A	N/A			
2	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases	-	-	-			
	• Upper Floors	02 Nos.	Provided	MR			
	 Basements 	N/A	N/A	N/A			
	b. Width of staircases	1-5 675.	-	-			
	• Upper Floors	(2.0)&1.50 mts	2.0 &1.50 mts	MR			
	Basements	N/A	N/A	N/A			
		-	-	-			
	c. Protection of exits	Required	Provided	MR			
	 Fire check door 	N/A	N/A	N/A			
	• Pressurization e. No. of continuous staircases to	02	02	MR			
	terrace	N/A	N/A	N/A			
	11. 19001 517.0	2m&1.50 m	2.0 & 1.50 mts	MR			
	Compartmentation.		D. 11.1				
	 Fire check door 	Required	Provided	MR			
	 Sealing of electrical shafts 	Required	Provided	MR			
	 Fire Rating of shaft door 	N/A	N/A	N/A			
	 Water Curtain 	N/A	N/A	N/A			
	Fire Dampers	N/A	N/A	NA			
	Smoke Management System.						
	Basements	N/A	N/A	N/A			
	• Upper floors	Required	Provided	MR			
	Fire Extinguishers						
	 Total numbers 	Required	Provided ABC & CO ₂ type	MR			
	TypesIS marking	ABC & CO ₂ type ISI marked	Provided	MR			

11 0(//

ct

:d i

Hojiar

Se:

:101

n Z

wo

ctie

tho

the ble

iegt ior I

6	First-Aid Hose Reels. Provided & Maintained by Bldg. management				
	Total numbers on each floor	01 nos.			
	 Length of hose reel hose 	30 m	01 at each floor Provided	MR 🥠	
	 Nozzle diameter 	5 mm	Provided	MR	
7	Automatic fire detection and alarming		riovided	MR	
	• Type of detectors	Smoke	Provided	MR	
	• Location of Main Panel	Required With in	Provided		
	Location of Repeater Panel	restaurant area		MR	
		N/A	N/A	N/A	
	• Alternate source of power	Required Required With in	Provided	MR	
0	Hooters' Location	restaurant area	Provided	MR	
8	MOEFA	Required	Provided	MR	
9	Public Address System.	Required	Provided	MR	
10	Automatic Sprinkler System.	Not required but provided			
	• Basement	N/A	N/A	N/A	
	Upper Floor	N/A	N/A	N/A	
	 Sprinkler above false ceiling 	N/A	N/A	N/A	
11		ovided & Mainta	ined by Bldg. managen	nent	
	• Size of riser/down-comer	100 mm	Provided	- MR	
	• Number of hydrants per floor	01 No.	Provided	MR	
	Hose Box	01 No.	Provided	MR	
12	Yard Hydrants.				
	• Total number of hydrants	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
13		ovided & Mainta	ined by Bldg. manager	nent	
	Ground Level				
	Discharge of main Pump	2280 lpm	Provided	MR	
	Head of Main pump	60m	Provided	MR	
	Number of main pumps	01	Provided	MR	
	 Jockey Pump out put 	180 LPM	Provided	MR	
	Jockey pump head	60m	Provided	MR	
	Standby Pump out put	2280 LPM	2280 LPM	MR	
	Standby Pump Head	60m	60 m	MR	
	Auto Starting/ Manual stopping	Required	Provided	MR	
	Pump House Access	Required	Provided	MR	
	• Terrace level			· · ·	
	Discharge of pump	450 LPM	900 LPM	MR	
	Head of the pump	45 mts	45 mts	MR	
	Power Supply	Required	Provided	MR	
	Auto Starting of pump	Required	Provided	MR	
4	Captive Water Storage for fire fighting		Maintained by Bldg.		
	• Underground tank capacity	1,00,000 lts	Provided	MR	
	Draw-off connection	Required	· Provided	MR	
	Fire service inlet	Required	Provided	MR	
	Access to tank	Required	Provided	MR	
	Overhead Tank capacity	10,000 lts	Provided	MR	
5	Exit Signage.	Required	Provided	MR	
6	Provision of Lifts. Lifts not installed		2.774	NT/ A	
	• Pressurization of Lift Shaft	N/A	N/A	N/A	
	• Pressurization of Lift lobby	N/A	N/A	N/A	
	•		N/A	N/A	
	Communication In lift Car	N/A			
		N/A	N/A	N/A	
	Communication In lift Car			N/A N/A MR	

			M-6	
	Refuge Area.			
-	Total Area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
	Fire Control Room			
	Detector System Panel	N/A	N/A	N/A
	 Flow Switch Panel 	N/A	N/A	N/A
		N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Batter backup		N/A	N/A
	Building Floor Plans	N/A	_	
	Special Fire Protection Systems for	N/A	N/A	N/A
	Protection of special Risks, if any:			

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant fire safety certificate under Delhi Fire Service Act-2007 & Rules- 2010.

DFA is put up for approval & signature please.

Ò

D.B. Mukharjee Divisional Officer (SWD)

19/21

P.V. Rathee Asstt. Div. Officer (SRD)

(52)