

C-28

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001


No. F.6/DFS/MS/EH/2021/SZ/273

Dated: 5/10/2021

FIRE SAFETY CERTIFICATE

Certified that M/s **Chic Fish Restaurant** located at 32, Corner Market, Maharishi Dayanand Marg, Malviya Nagar, New Delhi-110017, comprised of ground plus one upper floor but restaurant running at ground floor only was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/EH/2018/SZ/2049 dated 06/09/2018. The premise was re-inspected by the officers concerned of this department on 28/09/2021 in the presence of Mr. Rajesh Sethi and observed that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building premises is fit for occupancy class-D "**Assembly Building**" (Restaurant) with effect from 5/10/2021 for a period of **three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 5/10/2021 at New Delhi by


(Sunil Chawdhary)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service



Copy to: -

1. The Dy. Health Officer, South MCD, Public Health Department, South Zone, Green Park, New Delhi-110016
2. M/s Chic Fish Restaurant at 32, Corner Market, Maharishi Dayanand Marg, Malviya Nagar, New Delhi-110017

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire fighting system.
4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

INSPECTION REPORT

1	Name & Address of the Building	M/s CHIC Fish Restaurant, 32 Corner Market, Maharishi Dayanand Marg, Malviya Nagar, New Delhi 110017
2	Type of Occupancy	Group - D-4 Assembly
3	Building Comprised of	Ground + One upper floor
4	Type of Case	Renewal
5	Details of Previous NOC	F6/DFS/MS/E/H/2018/SZ/2049 Dt. 06/09/2018
6	Fire Safety Directives Letter No	NBC / BBI Requirement
7	Date of Inspection	08/09/2021
8	Name of the Inspecting Officers	DO (SD) & ADO (BCP)
9	Name & Designation of Officers from the building side	Mr. Rajesh Sethi
10	Year of construction	1994 Restt. running at Ground floor only
11	Applicant letter No.	MHA ID: 2021071215088 dated 12/07/2021

S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC Requirements	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	• Road width	Required	10 mtr	MR
	• Gate width	N/A	N/A	N/A
	• Width of internal road	N/A	N/A	N/A
2	Number, width, type & arrangement of exits.			
	a. Number of Staircase			
	Upper floors.	N/A	N/A	N/A
	Basement floor.	N/A	N/A	N/A
	b. Width of Staircase			
	Upper floors	N/A	N/A	N/A
	Basement floor	N/A	N/A	N/A
	c. Protection of exits			
	Fire check door	N/A	N/A	N/A
	Pressurization	N/A	N/A	N/A
	d. No. of continuous staircase to terrace	N/A	N/A	N/A
	e. Width of corridor	N/A	N/A	N/A
	f. Door size	2 exits	2m & 1m	MR
3	Compartmentation.			
	• Fire check door.	N/A	N/A	N/A
	• Sealing of electrical shafts.	N/A	N/A	N/A
	• Fire rating of shaft door.	N/A	N/A	N/A
	• Water curtain	N/A	N/A	N/A
	• Fire dampers.	N/A	N/A	N/A
4	Smoke Management system.			
	• Basement	12 ACPH	N/A	N/A
	• Upper floors	12 ACPH	Provided in kitchen	MR
5	Fire Extinguishers.			
	• Total numbers	06 Nos	10 Nos	MR
	• Types	ABC/CO ₂	ABC & CO ₂	MR
	• ISI Marking	ISI marked	Provided	MR
6	First Aid Hose Reels.			
	• Total numbers on each floor.	One	Provided	MR
	• Length of hose-reel hose.	30m	Provided	MR
	• Nozzle Diameter	5mm	Provided	MR


7	Automatic fire detection & alarming system.			
	• Type of detectors	N/A	N/A	N/A
	• Location of Main Panel	N/A	N/A	N/A
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
	• Hooter's location	N/A	N/A	N/A
8	MOEFA	Required	Provided	MR
9	Public Address System	N/A	N/A	N/A
10	Automatic Sprinkler System			
	• Basement	N/A	N/A	N/A
	• Restaurant area	Required	Provided	MR
	• Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.			
	• Size of Riser/Down-comer	N/A	100 mm	N/A
	• Number of Hydrant per floor	N/A	One	N/A
	• Hose box.	N/A	One	N/A
12	Yard Hydrants.			
	• Total number of hydrants.	N/A	N/A	N/A
	• Hose box.	N/A	N/A	N/A
13	Pumping arrangements.			
	• Ground Level			
	➤ Discharge of main pump.	N/A	N/A	N/A
	➤ Head of main pump.	N/A	N/A	N/A
	➤ Number of main pumps.	N/A	N/A	N/A
	➤ Jockey Pump output.	N/A	N/A	N/A
	➤ Jockey Pump head.	N/A	N/A	N/A
	➤ Standby Pump output.	N/A	N/A	N/A
	➤ Standby Pump head.	N/A	N/A	N/A
	➤ Auto Starting/Manual Stopping.	N/A	N/A	N/A
	➤ Pump house access.	N/A	N/A	N/A
	• Terrace Level			
	➤ Discharge of pump.	450 LPM	Provided	MR
	➤ Head of pump.	40m	Provided	MR
	➤ Power supply.	Required	Provided	MR
	➤ Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.			
	• Underground tank capacity.	N/A	N/A	N/A
	➤ Draw-off connection.	N/A	N/A	N/A
	➤ Fire Service Inlet.	N/A	N/A	N/A
	➤ Access to tank.	N/A	N/A	N/A
	• Overhead tank capacity.	5,000 Ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	• Pressurization of lift shaft.	N/A	N/A	N/A
	• Pressurization of lift lobby.	N/A	N/A	N/A
	• Communication in lift car.	N/A	N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
	• Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A


N/A	19	Fire Control Room.			
N/A		• Detector system panel.	N/A	N/A	N/A
N/A		• Flow switch panel.	N/A	N/A	N/A
N/A		• PA system panel.	N/A	N/A	N/A
N/A		• Battery backup.	N/A	N/A	N/A
N/A		• Building floor plan.	N/A	N/A	N/A
N/A	20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

The fire protection systems provided in the building were checked, tested at random and found functional at the time of inspection. The shortcomings communicated by this department vide letter No. F.6 D/S MS 2021 366 dated 27/08/2021 found complied.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6 D/S MS 2018 SZ/2049 dated 06/09/2018, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.


Accordingly, DFA is put up for approval and signature please.


 Signature of the Inspecting Officer
 Name : S.K. Dua
 Designation: DO (SD)



 Signature of the Inspecting Officer
 Name : Rajesh Kumar
 Designation: ADO (BCP)


DCFO (SZ)







As approved, f.t. letter is put up for your signature pl


 01/10/2021


 DCFO/SZ





Uploaded MHA online Portal
 06/10/2021