

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/2021/WZ/ 445

Dated: 11/10/2621

FIRE SAFETY CERTIFICATE

Certified that the Bhagwati Hospital located at CS/OCF-6, Sector-13, Rohini, Delhi-110085, comprised of Basement + Ground + Three upper floors owned / occupied by (A unit of Sarvodaya Health Foundation, Delhi) has already been issued FSC by this department vide letter No. F.6/DFS/MS/Hospital/2018/WZ/1280 dated 31.05.2018. The premises was reinspected by the officer concerned of this department on 20.03.2021 in the presence of Dr. Naresh Pamnani (Medical Superintendent) and observed that all the prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class (Hospital) with effect from 111012020 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

(Aful Garg) DIRECTOR Ph; 011-23414000

Copy to :-

1. Dr. Naresh Pamnani (Medical Superintendent), Bhagwati Hospital located at CS/OCF-6, Sector-13, Rohini, and Delhi-110085

Conditions for the validity of fire safety certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/ http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

والمراجع والم والمراجع والمراجع والمراجع والمراجع والمراجع والمراجع والمراج		INSPECT	ION DEPOND					
1	. Name & address of the building	Bhanvai II	ION REPORT					
2	. Type of Occupancy	ilding :Bhagwati Hospital CS/OCF-6, Sec-13, Rohini, Delhi-110085.						
.3.	. Type of Case	: Renewal : F.6/DFS/MS/Hospital/2018/WZ/1280 dated 31.05.2018 to : F.6/DFS/MS/BP/Hospital/99/1377 dated 25.10.1999						
4.								
5.	. Fire Safety directives letter No.							
6.	. Date of inspection							
7.	. Name of Inspecting Officer	. 1 12 631	: 20 .03 .2021 : A.K.Sharma ADO(Rohini)					
8.	. Name and designation of office	- A.N.Snarm	a ADO(Rohini)					
	from the building side							
10. Applicant's letter No. 2003								
							S. No	o. Minimum Standards on fire
	and the safety U/R 33	prevention	BBL/NBC	Provided at site	MR/NMR			
4	Access to building			the state of the s	MINITAL			
	 Road width 		Accessible	12 m	MR			
	 Gate width 		Accessible	5.0m	MR			
	 Width of internal road 		NA	NA NA	NA			
2.	The state of the s			1971	1473			
age - dan en rithete word	Number, Width, Type & Arrangement of Exits a. Number of staircases							
	 Upper Floors 	02	02	MR				
	 Basements 		1, 1 (ramp)	1, 1 (ramp)	MR			
	b. Width of staircases		1, 1 (tump)	1,1 (14111)				
	Upper Floor		2.0m	2.0m & 1.10m	MR(Old case)			
	Basements							
	c. Protection of exits		2.0m	1.80m & ramp 2.0m	MR(Old case)			
	Fire check door		Required	Provided	MR			
	• Pressurization		NA	NA	NA			
	d. No. of continuous staircases to terrace		02	02	MR			
	e. Width of Corridor		2.0m	1.30 m to 2.0 m	MR(Old case)			
f. Door Size			1.0m	1.0m	MR (Old case)			
3.	Compartmentation							
	 Fire check door 		Required	Provided in basement	MR			
	 Sealing of electrical sh 		Required	Provided	MR			
	 Fire Rating of shaft door 		NA	NA				
	 Water Curtain 		NA		NA			
	 Fire Dampers 		NA	NA	NA			
4.	Smoke Management System		INA	NA	NA			
	Basements		30 a/c per hour	Eulana C	¥			
	and the second s		-	Exhaust fan provided	MR			
	 Upper floors 		12 a/c per hour	NA	NA			
5.	Fire Extinguishers							
	 Total numbers 		20nos	52nos	140			
	• Types	• Types		ABC/CO2	MR			
	• IS marking		ABC/CO2 ISI marked	Yes	MR			
5.	First-Aid Hose Reels			ICS	MR			
	Total numbers on each floor		01	01				
	 Length of hose reel hose 		30mm	The state of the s	MR			
	Nozzle diameter			Provided	MR			
	Automatic fire detection and alarming system		5m Provided		MR			
and the second second	The state of the s		Smoke					
			Gr. floor	110/1060				
		cation of Main Panel		Provided	MR			
	Location of Repeater Panel			The same of the sa	MR			
	Alternate source of power		Required	Provided				
	 Hooters' Location 		D : 1	Daniel	MR			
	Thorees Eccation		Required	Provided	MR			

				-			
8.	MOEFA	Required	Provided	MR			
9.	Public Address System	Required	Provided	MR			
10.	Automatic Sprinkler System Basement	Required	D				
	 Ground & Upper Floors 	NA	Provided NA	MR			
	 Sprinkler above false ceiling 	NA	NA	NA			
11.	Internal Hydrants		147	NA			
	 Size of riser/down-comer 	NA	NA	NA			
	 Number of hydrants per floor 	NA	NA	NA			
1.3	Hose Box	NA	NA	NA			
12.	Yard Hydrants	A STATE OF THE STA					
	 Total number of hydrants 	NA	NA	NA			
	Hose Box	NA	NA	NA			
13.	Pumping Arrangements						
	 Ground Level 	NA	NA	NA			
	Discharge of main Pump	NA	NA	NA			
	Head of Main pump	NA	NA				
	Number of main pumps	NA		NA			
	Jockey Pump out put		NA	NA			
	* *	NA	NA	NA			
	> Jockey pump head	NA	NA	NA			
	Standby Pump out put	NA	NA	NA			
	Standby Pump Head	NA	NA	NA			
	Auto Starting/Manual Stopping	NA	NA	NA			
	Pump House Access	NA	NA	NA			
	Terrace level		1423	INA			
	Discharge of pump	450 & 180lpm	450 0 1001				
	Head of the pump	430 & 1801pm	450 & 180lpm	MR			
	Power Supply	Required	40m	MR			
	Auto Starting of pump	Required	Provided Provided	MR			
1.4		required	riovided	MR			
14.	Captive Water Storage for fire fighting						
	 Underground tank capacity 	25,000ltr	25,000ltr	MR			
	> Draw-off connection	NA	NA	NA			
	Fire service inlet	NA	NA	NA			
	Access to tank	NA	NA	NA			
	 Overhead Tank capacity 	12,500ltr	15,500ltr				
15.	Exit Signage.	Required	Provided	MR MR			
16.	Provision of Lifts.						
		271					
	• Pressurization of Lift Shaft	NA	NA	NA			
	Pressurization of Lift lobby Communication In 116 C	NA Parasiant	NA NA	NA			
	• Communication In lift Car	Required	Provided	MR			
	• Fireman's Grounding Switch	Required	Provided	MR			
	 Lift Signage 	Required	Provided	MR			
17.	Standby power supply	Required	2 X 750 kva				
18.	Refuge Area.			MR			
	Total Area	NA	NA				
	Location	NA	NA NA	NA			
10	Fire Control Room	INA	NA	NA			
19.							
	Detector System Panel Start Report	Required	Provided	MR			
	• Flow Switch Panel	NA Promised	NA Provided	NA			
	PA System Panel	Required	Provided	MR			
	Battery backup Floor Plans	Required NA	Provided NA	MR			
	 Building Floor Plans 	INA	INA	NA			

28/N Special Fire Protection System for Protection of special Risks, if any: NA NA NA The fire protection systems provided in the building were tested, checked at random and found some shortcomings. Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is not recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010 shortcoming as noted at serial no.2 & 13. Note: There is changes in the building in comparison to the building plans approved by this department vide letter F6/MS/DFS/99/Hospital/1377 dated 25.10.1999 and addition of some temporary rooms on terrace of building. Signature of the Inspecting Officer Ajay Kumar Sharma Name Designation ADO(Rohini)

Asthis 15 a Ru 2) remul, knul plu only what or Chys In bulf and what all