<u>GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI</u> <u>HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI – 110001</u>

No. F6/DFS/MS/School/NDZ/2021/857

<u>____HI</u> <u>110001</u> Dated: | 8 | 10 | 20 2 \

FIRE SAFETY CERTIFICATE

Certified that the Govt. Sarvodaya Kanya Vidyalaya (G.S.K.V), Dayanand Road, Daryaganj, New Delhi-02 is comprised of four blocks: Main block (Ground +01), Secondary Block (Ground floor), Primary block (Ground floor – not in use) & Auditorium block. Main block & Secondary Block have complied with the fire prevention and fire safety requirements in accordance with the circular No. F.16/ Estate/CC fire safety/2011/3298 to 3398 dated 01.03.11 issued by the Directorate of education, Govt. of NCTof Delhi. Same has been verified by the officer concerned of this department on 01.10.2021 in the presence of Mrs. Shveta Sachdeva (Vice principal). Two blocks of G.S.K.V, Dayanand Road, Daryaganj, Delhi namely Main block (Ground +01), & Secondary Block (Ground floor) are fit for occupancy of Group B (Educational Building) with effect from $\frac{10}{20}$, $\frac{10}{20}$, $\frac{10}{20}$, $\frac{10}{20}$, for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Director Tel: 011-23414000 ote 1. 10.21

Copy to:-

- 1. Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi.
- 2. The Vice Principal, Govt. Sarvodaya Kanya Vidyalaya (G.S.K.V), Dayanand Road, Daryaganj, New Delhi-02.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available during the schooling period.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>www.dfs.delhigovt.nic.in</u>.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.



الم (8 <u>INSPECTION REPORT</u>

1	Dayanand Road Delhi-02.			and Road, Dan	a Kanya Vidyalay I, Daryaganj, New		
2	Тур	e of occupancy with details of f	floors: Educa	Educational Building Group -B 04 Blocks			
				The second second second			
				ock (G + 01)	nd floor only		
				ry block (grou			
	1			block (ground	floor only)		
				Auditorium block. Inspection considered for Main Blo and secondary block only			
3	Tune	of acces			ily		
4		e of case: ils of previous FSC:		New case NA F.16/Estate/fire safety/2011/3298-339 dated 01.03.2011			
5		safety directives no.:					
5	rne	safety directives no.:					
6	Date	of inspection:	29.09.20				
7	Nam	e of the inspecting officer:	ADO Ra	esh Kumar Shu	ukla (SPM)		
8	Nam	e and designation of the officer	from Mrs. Sacl	ndeva (Vice Pri	incipal)		
1.15		uilding side:	and the second second	and the fait of the			
9		of construction:	1932	gener i verezije to			
10	Refer	rence letter no.:	E-mail da	ated 28.09.202	1		
S.N	req F.10 339	nimum Standards on fire safet uirements as per circular no. 5/Estate/fire safety/2011/3298- 8 dated 01.03.2011	y Requirement	s Provide at site	Remarks MR/NMF		
1		ess to Building:	alater a service a service a				
	A	Road width	6 mtrs.	6 mtrs.	MR		
	B	Gate width	NA	NA	NA		
	C	Width of internal roads	NA	NA	NA		
2		iber, Width, Type & Arranger	ment of Exits:				
	A	No. of Staircase:					
		a) Upper floor	02 nos.	02 nos.	MR		
	and and	b) Basements	NA	NA	NA		
	B	Width of the Staircase:			Sec. 1		
		a) Upper floor	1.5 mtrs.	1.4 & 1.15	MR		
	1 3.4.1	b) Basements	NA	MTRS.	NA		
	C	Protection of Exits		INA	INA		
		a) Fire Check Door	NA	NA	NIA		
		b) Pressurization	NA	NA	NA		
	D	No. Of continuous	NA		NA		
		staircase to terrace:		NA	NA		
	F	Width of the corridor	1.5 mtrs.	1.5 mtrs.	MR		
	E	Door size	1 mtrs.	1 mtrs.	MR		
3	Com	artmentation:	1		TALX		
	A	Fire Check doors	NA	NA	NA		
Ī	B	Sealing of Electrical Shafts	NA	NA	NA		
ł	C	Fire rating of shaft Doors	NA	NA			
ŀ	D	Water curtain	NA	NA NA	NA		
	E	Fire dampers	NA		NA		
1	CE CLARK			NA	NA		
4		e management System:			Ender A.		
-	A B	Upper floors Basements	NA	NA	NA		
	A Mail and	13 Picket	NA	NA	NA		
		ktinguishers:	and the second second				
	A	Total numbers	12 nos.	21 nos.	MR		
	B	Types	CO2, ABC	CO2, ABC	MR		
-	C	ISImarking	Required	Provided	MR		
	and the second s	Door					
		nin din .					
		ire .					

		Aid Hose Reel:	NA	NA	NA
-	A	Total no. at each floor	NA	NA	NA
	B	Length of Hose Reel		NA	NA
	C	Nozzle diameter	NA (ADAS):		
7	Auto	matic Fire Detection and Alarm Syst	tem (ADAS):	NA	NA
	Α	Type of detector	INA	NA	NA
T	B	Location of main Panel	NA	NA	NA
t	Ç	Location of Repeater Panel	NA	NA	NA
t	D	Alternate power Source	NA .	NA	NA
1	E	Hooter's location	NA	NA	NA
8	MO	EFA:	NA	Contraction in the local sector in the local sector in the local sector is the local s	NA
9	Pub	lic Address System:	NA	NA	
10	Aut	omatic Sprinkler System:			NA
10	A	Basement	NA	NA	NA
	B	Upper Floor	NA	NA	NA
	C	Sprinklers above false ceiling	NA	NA	1.1.1
11	Int	ernal hydrants:		1.21.4	NA
	A	Size of the riser/down comer	NA	NA	NA
	B	No. Of hydrants per floor	NA	NA	NA
	C	Hose box	NA	NA	14/1
12		rd Hydrants:		1.1.4	NA
	A	Total no. of hydrants	NA	NA NA	NA
	B	Hose box	NA	NA	1474
13	Pu	mping arrangements:			
	A	Ground Level	1	NA	NA
		a) Discharge of main pump	NA	NA	NA
		b) Head of main pump	NA	NA	NA
		c) Number of main pump	NA	NA	NA
		d) Discharge of jockey pump	NA		NA
		e) Head of jockey pump	NA	NA	NA
		f) Discharge of Standby pump	NA	NA NA	NA
		a) Head of Standby pump	NA	NA	NA
		h) Auto starting/ manual stopping	NA	INA	
-	B	Terrace Level			NA
	-	a) Discharge of terrace pump	NA	NA	
		b) Head of terrace pump	NA	NA	NA
		c) Alternate power supply	NA	NA	NA NA
		d) Auto starting of pump	NA	NA	NA
-		aptive Water Storage for Fire Fightin	g:		NIA
14	A		14/1	NA	NA NA
	B	m mantion	NA	NA	NA
	C		NA	NA	NA
	E	Access to tank	NA	NA	NA
	D		NA	NA	MR
1		xit Signage:	Required	Provided	IVIN
1	Provision of lift:		214	NA	NA
	A	Pressurization of lift shaft	NA	NA	NA
	E	Pressurization of lift lobby	NA	NA	NA
	C	Communication in lift car	NA	NA	NA
	T		NA	NA	NA
	F	Lift signage	NA	NA	NA
-	7 5	itandby Power Supply:	NA		

1

N	19
---	----

18	Refuge Area:					
8	A	location	NA	NA	NA	
	B	Total area	NA	NA	NA	
19	Fire Control Room:					
car e d	A	Fire Detection System panel	NA	NA	NA	
1	B	Flow switch panel	NA	NA	NA	
	C	P A system panel	NA	NA	NA	
	D	Battery backup	NA	NA	NA	
	E	Building floor plan	NA	NA	NA	
20	0 Special Fire Protection for special risk if any:			NA		

Meeting requirement (MR), Not meeting requirement (NMR), Not applicable (NA)

The fire protection systems provided in the building were tested checked and found properly functional at the time of inspection.

The school had been issued shortcomings vide letter no. F6/DFS/MS/SCHOOL/2014/1536 dated 01.07.2014 are applicable for auditorium only and the same has not been complied till date and therefore auditorium block has not been considered for FSC. Use of Primary block has been discontinued by the school and hence the same has also not been considered. However, school has admitted the same vide letter no. SKY/DN/2021/291 dated 29.09.2021 submited at the time of inspection. Main Block and Secondary Block comply with the requirements of Fire Safety Directives.

In view substantial compliance of the minimum standards on fire prevention and fire safety required under the rules as per the directives of Education Department vide letter no. F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01.03.2011, issuance of FSC to Main Block and Secondary Block of Govt. Sarvodaya Kanya Vidhayala, Dayanand Road, Daryaganj, New Delhi-02 is recommended.

A.0/21

Signature of the Inspecting Officer

Name Designation

ADO (SPM)

Rajesh Kumar Shukla

Pl. Apeak. New care.

BO+ADOCSPM) on 8/x/21 nited please Johen