-60

FORM 'H' FORM FOR ISSUING FIRE SAFETY CERTIFICATE [Refer sub - rule (1) of rule 35] GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI

No. F6/DFS/MS/EH/2021/ 🖓 9 🎘

Dated: / 8 /10/2021

FIRE SAFETY CERTIFICATE

Certified that the Green Lounge Restaurant Located at Ground Floor, 39-43, Aggarwal City Mall, Plot No-05, Road No-44, Pitampura, New Delhi-110034 in a building comprised of **Basement + Ground + 03 Upper Floors** owned/occupied by Green Lounge Restaurant was issued FSC by this department vide Letter No.F6/DFS/MS/EH/2018/198 dated 01.02.2018. The premises was re-inspected by the officer concerned of this department on **12.10.2021** in the presence of Sh. Rattan Singh (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class "Assembly" Group D with effect from **18** 10 2021 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

(Dharampal Bhardwaj) Dy. Chief Fire Officer (West Zone)

- Melvert

Copy to:-

- The Addl. Commissioner of Police (Lic), 1st Floor, Licensing Unit, Police Station, Defence Colony, New Delhi
- Colony, Hen Denni
 The Dy. Health Officer, Keshav Puram Zone, NDMC, Public Health Department, A-1 Block Kashav Puram Zone, Delhi.
- Kesnav Puram Zone, Denn.
 3. Sh. Rajeev Nagpal (Director), Green Lounge Restaurant, Ground Floor, 39-43, Aggarwal City Mall, Plot No-05, Road No-44, Pitampura, New Delhi-110034.



CONDITION

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.
- The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <u>www.dfs.delhigovt.nic.in</u>.
- 8. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expired.

N-22

INSPECTION REPORT

1. Name & address of the building: Green Lounge Restaurant Located at Ground floor of 39-43, Aggarwal City Mall Plot No-05, Road No-44, Pitampura, New Delhi

- 2. Type of Occupancy : Class-Assembly at Ground Floor in a mall comprised of B + G + Three upper floors.
- 3. Type of Case : Renewal
- 4. Details of previous NOC : F6/DFS/MS/EH/2018/198 dated 01.02.2018 Mall: DFS/MS/Mercantile/WZ/2021/464 dated -24/09/2021
- 5. Fire Safety directives Letter No. : F-6/DFS/MS/2005/1527 Dated 19/07/2005 For the mall
- 6. Date of inspection : 12.10.2021
- 7. Inspecting Officer : Satpal Bhardwaj ADO (WP)
- 8. Name and designation of Officer

from the building side : Sh. Rattan Singh (Manager)

- 9. Year of Construction :2014
- : 2021092122125 Dated- 9.10.2021 10. Applicant's letter No.

S	Minin	num standards on fire	BBL		Provided at site	Remarks			
No	prevei	ntion and fire safety U/R	Requi	rements/ letter		MR/NMR			
	33	-	dated	1.2.2018					
1.									
	•	Road width	16 m		24 m Provided	MR			
	•	Gate width	6 m		Provided	MR			
	•	Width of internal road	As pe	er sanction plan	Provided	MR			
2.	. Number, width, Type & Arrangements of exits								
	a.					-			
	•	Upper floors		NA	NA	NA			
	•	Basements		NA	NA	NA			
	b.								
		• Upper floors		NA	NA	NA NA			
				NA	NA				
	с.	Protection of exits							

• Fire check door NA NA NA Pressurization • NA NA NA d. No of continuous staircase to NA NA NA terrace NA NA e. Width Of Corridor NA Old case 110cm,95cm &2x120cm f. Door Size MR (Old case) 3. Compartmentation • Fire check door NA NA NA Sealing of electrical shafts NA NA NA Fire Rating of shaft door NA NA NA Water Curtain NA NA • Fire Dampers ΝA NA NA NA Smoke managements System 4. Basements • NA NA NA Upper floors Required Provided MR 5. Fire Extinguishers Total numbers • 04 nos. 04Provided MR Types • ABC & CO2 Provided MR IS marking ISI marked Provided MR First – Aid Hose Reels 6. Total numbers on each floor • 01 Provided MR Length of hose reel hose • 30 m Provided MR • Nozzle diameter 5 mmProvided MR Automatic fire detection and alarming system 7. Type of detectors • Smoke& Heat Provided MR Location of Main Panel • Required Provided MR Location of Repeater Panel Required Provided MR Alternate source of power Required Provided MR Hooters' Location At strategic location • Provided MR 8. **MOEFA** Required Provided MR Public Address System 9. Required Provided MR 10. Automatic Sprinkler System **Basements** • NA NA NA Upper Floor • Required Provided MR • Sprinkler above false ceiling Required Provided MR 11. Internal Hydrants Common with Mall Size of riser/down- comer • 150 mm Provided MR Number of hydrants per floor • 2 2 MR • Hose Box 2 2 MR 12. Yard Hydrants Common with Mall

Total number of hydrants
Hose Box
4
4
MR
4
MR

N- 24

13.	Pump	ing Arrangements	Comm	on with Ma					
15.		round Level	NIA		22901				
		ischarge of main pump	NA		22801	pm		NA	
		ead of main pump	NA		60m	60m		NA	
	> N	umber of main pumps	NA		1	1		NA	
		Jockey pump out put	NA			180lpm		NA	
	\triangleright	Jockey pump head	NA		60m		NA		
	Standby Pump out put		NA		2280lpm		NA		
			NA		60m			NA	
	Þ	Standby Pump Head	NA			rovided		NA	
	Auto Staring/Manual		NA Provided					NA	
		stopping							
	\triangleright	Pump House Access			ng arrangement at Ground			MR	
	٠	Terrace level	level is		s at higher side				
	\triangleright	Discharge of pump	60 m	Provi				MR	
	\triangleright	Head of the pump	Required		Provid	Provided		MR	
	\triangleright	Power supply	Required		Provided		MR		
	\triangleright	Auto starting of pump	-	0	•.1	Ma ¹¹			
14.	Capti	ve water Storage for fire f	0 0		on with Mall 200000ltrs NA				
	•	Under ground tank	NA		Doocouri				
		capacity	NA		Provided NA Provided NA				
		Draw of connection	NA				NA		
		Fire service inlet	NA		Provided		MR		
		Access to tank	10,000 ltr	S	Provided		IVIR		
	Overhead Tank								
		capacity	D 1 1		Provided MR				
15		Signage	Required		FIOVID				
16.	Provi	sion of Lifts	0	NA		NA	NA		
		Pressurization of Lift Sl				NA	NA		
		Pressurization of lift lob	by NA					NA	
			Car NA				NA		
			witch NA NA		NA NA		NA		
		Lift Signage		INA					
17	Stand	by power supply		Required	Provid	ed	MR		
17. 18.		e Area							
10.	Refug	Total area	NA		NA NA				
		Location				NA NA NA			
		ontrol room							
9.		Detector system panel	NA		NA NA				
	A	Flow Switch Panel	NA	NA		NA			
		PA System Panel	NA		NA		NA		
		Battery backup	NA		NA		NA		
		Building Floor Plans	NA		NA		NA		

20. Special Fire Protection	NA	NA	NA
Systems for Protection of			
special Risks, if any;			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter no. F6/DFS/MS/EH/2018/198 Dated-1.02.2018 renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer

Name S P Bhardwaj

Designation: ADO (WP)

0/2021

110/22)

Dowert

mist al