## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F6/DFS/MS/EH/2021 / W2 30 FIRE SAFETY CERTIFICATE

Dated: 25/10/2021

Certified that the M/s Shots Restaurant located at Plot No.03, LSC Gujrawala Town Part-I, Delhi-110009 in the building comprised of Basement + Ground + 03 Floors owned/ occupied by M/s Shots Restaurant was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/2018/WZ/2403 dated 26.10.2018. The premises was re-inspected by the officers concerned of this department on 11.10.2021 in the presence of Mr. Manik Ghai (Owner) and found the building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of 03 (Three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 35/10/202 at New Delhi by

(Sunil Choudhary) Dy. Chief Fire Officer Ph.-011-25156707

Copy to:-

- 1. The Dy. Health Officer, NDMC, Public Health Department City S.P.Zone, Old Hindu College, Kashmere Gate, Delhi.
- The Joint Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi-110049.
- 3. M/s Shots Restaurant located at Plot No.03, LSC Gujrawala Town Part-I, Delhi-110009.

## Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="http://delhi.gov.in./wps/wcm/connect/doit">http://delhi.gov.in./wps/wcm/connect/doit</a> fire/FIRE/Home/Forms.
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

: M/s Shots Restaurant located at Plot No.03, LSC Gujrawala Town, Part-I, Name & address of the building Delhi-110009. : Restaurant (Assembly) 2. Type of Occupancy : Renewal (B+G+03 upper floor) Type of Case : F6/DFS/MS/2018/WZ/2403 dated:26.10.2018 Basement- Vacant 4. Details of previous NOC Ground floor- Restaurant 5. Fire Safety directives letter No : BBL 1st floor-Restaurant : 11.10.2021 Date of inspection 2<sup>nd</sup> floor- Restaurant : ADO (RN) ame of the Inspecting Officers 3<sup>rd</sup> floor- Restaurant ame and designation of officers : Sh. Manik Ghai (Owner) from the building side : 2005 9. Year of Construction : Online I D No. 2021081818123 Dated: 25.08.2021 10. Applicant's letter No. 11. Covered area-172sqm Remarks Provided at site Minimum Standards on fire prevention and **BBL** Requirements MR/NMR fire safety U/R 33 1 Access to building MR 06 08m Road width 05m Directly Accessible MR Gate width NA NA NA Width of internal road Number, Width, Type & Arrangement of Exits 2 a. Number of staircases 02 02 MR Upper Floors NA NA NA Basements b. Width of staircases MR (old case) 1.25m each 1.40m & 1.25m Upper Floors NA NA NA Basements c. Protection of exits NA. NA NA Fire check door NA NA NA Pressurization NA d. No. of continuous staircases to terrace NA NA e. Width of Corridor NA NA NA f. Door Size MR 01m 01m 3 Compartmentation. NA NA NA Fire check door NA NA NA Sealing of electrical shafts NA NA Fire Rating of shaft door NA Water Curtain NA NA NA Fire Dampers NA NA NA 4 Smoke Management System. NA NA 12 a/c per hour Basements Natural Ventilation MR Upper floors 12 a/c per hour 5 Fire Extinguishers MR 14nos 14nos Total numbers

10

	1)pcs	113 01 008		
	ISI marking	Yes	Yes	MR
6	First-Aid Hose Reels.			
	Total numbers on each floor	01each floor	Provided	MR
	<ul> <li>Length of hose reel hose</li> </ul>	30m	Provided	MR
-	Nozzle diameter	5mm	Provided	MR
7	Automatic fire detection and alarming system.	Simil	Trovided	TVIII.
	Type of detectors	Required	Provided	MR
	<ul> <li>Location of Main Panel</li> </ul>	NA	NA	NA
	Location of Repeater Panel	NA	NA	NA
	Alternate source of power	NA	NA	NA
	Hooters' Location	NA	NA	NA
8	MOEFA	Required	Provided	MR
9	Public Address System.	Required	Provided	MR
10	Automatic Sprinkler System.			A
		NA	NA	NA
	Basement			
	• Upper Floor	Required	Provided	MR
2 1	Sprinkler above false ceiling	NA	NA	NA
11	Internal Hydrants			
	Size of riser/down-comer	100mm	Provided	MR
	Number of hydrants per floor	01	Provided	MR
	Hose Box	01	Provided	MR
12	Yard Hydrants.			
	Total number of hydrants	01	Provided	MR
	Hose Box	- 01	Provided	MR
13	Pumping Arrangements.			
	Ground Level	x *		
	Discharge of main Pump	NA	NA	NA
	Head of Main pump	NA	NA	NA
	Number of main pumps	NA	NA	NA
	> Jockey Pump out put	180lpm	Provided	MR
	Jockey pump head	40m	Provided	MR
	Standby Pump out put	N/A	N/A	N/A
	<ul><li>Standby Pump Head</li><li>Auto Starting/ Manual stopping</li></ul>	N/A	N/A	N/A
	> Pump House Access	N/A	N/A	N/A
	Terrace level			
	Discharge of pump	450lpm	900lpm	MR
	Head of the pump	40m	40m	MR
	Power Supply		40m Provided	
	> Auto Starting of pump	Required		MR
1		Required	Provided	MR
14	Captive Water Storage for fire fighting.		The state of the s	
	Underground tank capacity	NA	NA	NA

	> Draw-off connection	NA	NA	NA		
	> Fire service inlet	NA	NA	NA		
	Access to tank	NA	NA	NA		
	Overhead Tank capacity	5,000ltr	Provided	MR		
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.					
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	NA	NA	NA		
	Fireman's Grounding Switch	NA	NA	NA		
	Lift Signage	NA	NA	NA		
17	Standby power supply	Required	Provided	MR		
18	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel     Batter backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
		N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA		

The fire protection systems provided in the building were tested/ checked and found some in working order at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules. It is recommended to renew Fire Safety vide this department letter of even no.2403 dated 26.10.2018 Certificate under rule 37(3) of Delhi Fire Service Rules 2010.

DO (NW) - ON Leave

DU GO (WZ)

1110/2021

Signature of the Inspecting Officer

Name: - C.L. Meena

Designation:- ADO/RN

As approved, F.T. letter is lutup For your enguatur Pl.

Dy cfo (MZ) - ON Leave

by cfolsz

22/10/202