GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/BNQT/2021/SZ/ 530

Dated: 27/10/2021

FIRE SAFETY CERTIFICATE

Certified that the M/s Silver Grand Banquet is running at second floor only building comprised of lower basement, upper basement, ground floor plus four upper floors located at S-26 (Part), Second Floor, Ivory Tower, Old Ajanta Cinema Complex, Ajay Enclave, Subhash Nagar, New Delhi, owned/occupied by M/s Silver Grand Banquet was issued FSC by this department vide letter no. F6/DFS/MS/BNQT./2018/SZ/2400 dated 25/10/2018. The banquet hall was re-inspected by the officers concerned of this department on 04/10/2021 in the presence of Sh. Yaddu Mohan Mittal (MD) and found that the Banquet have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises (Second floor Only) is fit for occupancy class Group-D "Assembly Building" (Banquet Hall) w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on at New Delhi.

DELHI FIRE SERVICE

Copy to:-

1. The Manager, M/s Silver Grand Banquet, S-26 (Part), Second Floor, Ivory Tower, Old Ajanta Cinema Complex, Ajay Enclave, Subhash Nagar, New Delhi

2. The Dy. Health Officer, S.D.M.C. Public Health Department, West Zone, Vishal Enclave, Rajouri Garden, New Delhi-110027

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

		10/05				
	INSPECT	ION REPORT				
	Name & address of the building: M/s Sil Old Aj	Old Ajanta Cinema Complex, Ajay Enclave, Subhash Nagar, New				
	2 Building is comprised of Lower	basement, upper basem	ent, Ground floor	olus four upper		
	floors b	out banquet hall is runni	ing at second 11001	Olliy		
		D (Assembly Building))			
	4. Type of Case : Renew 5. Details of Previous NOC : F6/DF:	ai S/MS/BNQT.2018/SZ//	2400 dated 25/10/2	018.		
	6. Fire Safety directives letter No : F6/MS/	/DFS/BP/2004/1973 da	ted 31.08.2004			
	7. Date of inspection : 04/10/2	2021				
	8. Name of Inspecting Officers : A.D.O). R.K.Yadav				
	9. Name and designation of officers	addu Mohan Mittal (MI))			
	From the building side : Sh. Ya 10. Year of Construction : 2010-2		<i>,</i>			
	11. Applicant's letter No. : received	by email dated 27/09/	2021	_		
S.	Minimum Standards on fire prevention and fire		Provided at	Remarks MR/NMR		
No.	safety U/R 33	Î	site	MR/NMR		
1.	Access to building	0.0	Provided	MR		
	 Road width 	09 m 06 m	Provided	MR		
	Gate width	N/A	N/A	N/A		
	Width of internal road	13/13				
2.	Number, Width, Type & Arrangement of Exite	s				
2.	a. Number of staircases		D 11.1	MR		
	Upper Floors	05 no.'s	Provided	. 40		
	 Basements 	03 no.'s & 01 ramp	03 no.'s & 02 ramp	JS IVIIX		
	Will Chairman		1X2.0 M & 4X 1.50	M MR		
	b. Width of staircasesUpper Floor	2.0 & 1.50 m	1X2.0 N & 4X 1.50			
	Basements	1.50 m	& 02 ramps	MIX		
	c. Protection of exits	Required	Provided	MR		
	Fire check doorPressurization	Required	Provided	MR		
	• Pressurization			. 45		
	d. No. of continuous staircases to	Required	Provided	MR		
	terrace	1.50 m	2.05 m	MR		
	e. Width of Corridor	2.0/1.50/1.0 m	2.0, 1.50,	MR		
	f. Door Size		1. 60 & 1.40 n	1		
3.	Compartmentation					
	Fire check door	Required	Provided	MR		
	 Fire check door Sealing of electrical shafts 	N/A	N/A	N/A		
	 Sealing of electrical states Fire Rating of shaft door 	N/A	N/A	N/A		
	Water Curtain		N/A	N/A		
	• Fire Dampers	N/A N/A	N/A	$\frac{N/A}{N/A}$		
		13//1	1			
) .	Smoke Management System			MD		
	Basements	Required	Provided	MR		
	Upper floors	Required	Provided	MR		
S	Fire Extinguishers					
		14 No.'s	Provided	MR		
	• Total numbers	ABC/CO ₂	Provided	MR		
	 Types 	ISI marked	Provided	MR		
	 IS marking 		FIOVICE			

ovi •

St

2(

6.	First-Aid Hose Reels			
	Total numbers			1
		Two	Provided	MR
	• Length of hose reel hose	30 m	Provided	MR
7.	Nozzle diameter	5 mm	Provided	MR
•	Automatic fire detection and alarming system	and the same of th	71071000	ALIX
	Type of detectors	Smoke	Provided	MR
	• Location of Main Panel	Required		
	 Location of Repeater Panel 	N/A	G Floor	MR
	Alternate source of power Hootors' Leave:	Required	N/A	N/A
	rioders Location	Required	Provided	MR
8.	MOEFA	the state of the s	Nr. Main gate	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System	Required	Provided	MR
	Basement	Required	Provided	V (1)
	 Ground Floor 	Required	Provided	MR
	 Sprinkler above false ceiling 			MR
11.	Internal Hydrants	Required	Provided	MR
	Size of riser/down-comer	150 mm	Dennist 1	MD
	Number of hydrants	Two	Provided Provided	MR MR
	Hose Box	Two	Provided	MR
12.	Yard Hydrants	1 WO	Flovided	VIK
	Total number of hydrants	00 '-	D 1.1	V.65
	Hose Box	09 no.'s	Provided	MR
13.	Pumping Arrangements	09 no.'s	Provided	MR
	Ground Level		(Common with who	ole premises)
	Discharge of main Pump	2050 1 221		
	-	2850 LPM	Provided	MR
	pump	60 m	Provided	MR
	Number of main pumps	Two	Provided	MR
	Jockey Pump out put	450 LPM	Provided	MR
	Jockey pump head	60 m	Provided	MR
		2850 LPM	Provided	
	Standby Pump out put			MR
	Standby Pump Head	60 m	Provided	MR
	Auto Starting/Manual Stopping	Required	Provided	MR
	> Pump House Access	Required	Provided	MR
	Terrace level			
	Discharge of pump	450 LPM	Provided	MR
	Head of the pump	30 m	Provided	MR
	Power Supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Provided	MR
1.	Captive Water Storage for fire fighting			
	Underground tank capacity	2,00000 ltrs	Provided	MŘ
	> Draw-off connection	Required	Provided	MR
	Fire service inlet			
	> Access to tank	Required	Provided	MR `
		II agained	D	I MD
		Required	Provided	MR
	Overhead Tank capacity	20000 ltrs	Provided	MR

-			
	M25		
		.1.1	MR
of Lifts.	Required	Provided	MR
ressurization of Lift Shaft	Required	Provided	MR
recentization of Lift loopy	Required	Provided	MR
ommunication In lift Car	Required	Provided	MR
reman's Grounding Switch	Required	Provided	MR
ft Signage	Required	Provided	1
power supply	Requir		
			N/A
rea.	N/A	N/A	21/4
otal Area		4 th floor	N/A
ocation	N/A		
			MR
trol Room	Required	Provided	N/A
netector System Panel	N/A	N/A	MR
low Switch Panel	Required	Provided	-
A System Panel		Provided	MR
lattery backup	Required	Provided	MR
Building Floor Plans	Required	N/A	N/A
	N/A	NIA	
Fire Protection System for Protection of			
		and foun	d functional at
fire protection systems provided in the of inspection. The shortcomings was iss	building were o	checked and roun	NQT/2021/SZ/1
fire protection systems provided was iss	ued vide letter no	0. F0/DF5/M5/2	
of inspection. The shortcomings was iss 122/09/2021 has been complied. ew the deemed compliance of the mixed the deemed compliance of the mixed promited and the	land	on fire prevent	ion and fire sa
the deemed compliance of the mi- ew the deemed compliance of the mi- ures as required under the rules as required which the rules as recommended. The built is recommended. The builties are some size of the mi- tal and the mi-	ules, the re	val under rule 37	of the Delhi
ures as required as a required	5/10/2018 renew	y been given FSC	by this depart
FS/MS/BNQ1/2010/000mmended. The bui	lding has alread	18/2021	
ares as required under the first as required under the first as required under the first as a second of the second	Z/401 dated 18/0	10/2021.	
ice rules 2010 is recommended. The but Letter No. F6/DFS/MS/Cinema/2021/S.		1) h
			160
			y y y
		Signature of the I	nspecting Office
		Name '-R.	K.Yadav

special Risks, if any: The fire protection time of inspection. T dated 22/09/2021 ha In view the deemed e measures as rec ١t F.6/DFS/MS/BNQT Service rules 2010 i vide Letter No. F6/I

Name

:-R.K.Yadav

Designation :-ADO(JKP)

05/10/2021 DO (South West)

Provision of Lifts.

Standby power supply

Total Area Location

Fire Control Room

Special Fire Protection

Refuge Area.

16.

17.

18.

19.

20.