

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001.

No. F.6/DFS/MS/EH/2021/SZ/ 314

Dated: 29/10/21

FIRE SAFETY CERTIFICATE

Certified that the **Mc Donald's Family Restaurant**, located at 30/4 & 30/4A, Double Storey, Tihar-II, Ashok Nagar, New Delhi-110018 comprised of ground floor plus three upper floors but the restaurant is running at ground floor plus one upper floor only. The above restaurant was issued FSC vide Letter No. F6/DFS/MS/EH/2018/SZ/72 dated 08/01/2019 owned/ occupied by M/S Connaught Plaza Restaurant Pvt. Ltd. The Restaurant building was re-inspected by the officer concerned of this department on 21/10/2021 in the presence of Sh. Ravi Arora (Store Manager) and found that the M/S Connaught Plaza Restaurant Pvt. Ltd. have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the restaurant building (**ground floor plus one upper floor only**) is fit for occupancy class Group D assembly building w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on.....29/10/21.....at New Delhi.



(SUNIL CHAWDHARY)
DY. CHIEF FIRE OFFICER

Copy to:-

The Manager,
Mc Donald's Family Restaurant, located at 30/4 & 30/4A,
Double Storey, Tihar-II, Ashok Nagar, New Delhi-110018.

Expt no

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
4. The trained staff should be available round the clock.
5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Safety Rules 2010. form is available on www.dfs.delhigovt.nic.in.
8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

N/13
INSPECTION REPORT

1. Name & address of the building: Mc Donald's Family Restaurant, located at 30/4 & 30/4A, Double Storey, Tihar-II, Ashok Nagar, New Delhi-110018.
2. Building is comprised of : G+3 (Restaurant is running at ground plus one upper floor only)
3. Type of Occupancy : Group D (Assembly)
4. Type of Case : Renewal
5. Details of Previous NOC : F6/DFS/MS/EH/2019/SZ/72 dated 08/01/2019
6. Fire Safety directives letter No : Nil.
7. Date of inspection : 21/10/2021
8. Name of Inspecting Officer : A.D.O. R.K.Yadav
9. Name and designation of officers
From the building side : Sh. Ravi Arora (Store Manager)
10. Year of Construction : Before 2010
11. Applicant's letter No. : ID No. 2021092222246 dated 28/09/2021

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirements	Provided at site	Remarks
1.	Access to building			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	Accessible 4.5 m N/A	09 m Directly accessible from road N/A	M/R M/R N/A
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases	02 No.'s	Provided	M/R
	<ul style="list-style-type: none"> • Upper Floors • Basements 	N/A	N/A	No Basement
	b. Width of staircases	1.5 m & 1.0 m	1.70 & 1.10 m	M/R
	<ul style="list-style-type: none"> • Upper Floor • Basements 	N/A	N/A	No Basement
	Protection of exits	N/A	N/A	N/A
	<ul style="list-style-type: none"> • Fire check door • Pressurization 	N/A	N/A	N/A
	d. No. of continuous staircases to terrace	N/A	One	N/A
	e. Width of Corridor	N/A	N/A	N/A
	f. Door Size	02 m	02 m	M/R
3.	Compartmentation			
	<ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Water Curtain • Fire Dampers 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
4.	Smoke Management System			
	Basements	N/A	N/A	No Basement
	Upper floors	Required	Natural Ventilation	M/R
5.	Fire Extinguishers			
	Total numbers	08 no's	Provided	M/R
	Types	ABC/CO ₂	Provided	M/R
	IS marking	ISI marked	ISI marked	M/R

2/14				
6.	First-Aid Hose Reels			
	Total numbers on ground floor	One/Floor	(Restaurant at GF & FF only)	
	Length of hose reel hose	30 mtrs	Provided	M/R
	Nozzle diameter	5 mm	Provided	M/R
7.	Automatic fire detection and alarming system			
	Type of detectors	N/A	Provided	MR
	Location of Main Panel	N/A	Near reception	MR
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	Provided	MR
	Hooters' Location	N/A	Near staircase	MR
8.	MOEFA	Required	Provided	M/R
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	Basement	N/A	N/A	N/A
	Ground Floor & FF in restaurant area	N/A	Provided	MR
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	Size of riser/down-comer	100 MM	Provided	M/R
	Number of hydrants	One	One	N/A
	Hose Box	One	One	N/A
12.	Yard Hydrants			
	Total number of hydrants	N/A	one	N/A
	Hose Box	N/A	one	N/A
13.	Pumping Arrangements			
	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
	Pump House Access			
	Terrace level	450 LPM & 180	Provided	M/R
	Discharge of pump	LPM		
	Head of the pump	30 mtrs	Provided	M/R
	Power Supply	Required	Provided	M/R
	Auto Starting of pump	Required	Provided	M/R
14.	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
	Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	10,000 ltrs	Provided	M/R
15.	Exit Signage.	Required	Provided	M/R

N/15

				(No Lift)
16.	Provision of Lifts.			
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17.	Standby power supply	Required	Provided	M/R
18.	Refuge Area.			
	Total Area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19.	Fire Control Room			
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	M/R
	Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the Fire Safety Certificate issued vide letter number F6/DFS/MS/EH/2018/SZ/72 dated 08/01/2019 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

R. K. Yadav
22/10/2021

Signature of the Inspecting Officer
Name- R.K.Yadav
Designation- ADO(JKP)

~~DO(South West)~~

Lim
22/10/21

DeFO (S)

Fit.
[Signature]
22/10/21

A D/O JKP

FT letter as put up for