GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE **NEW DELHI**

No. F6/DFS/MS/EH/WZ/2021/ 302_

Dated: 25// 0 /2021

FIRE SAFETY CERTIFICATE

Certified that the M/s The Market Place (A unit of Rain tree Grill) located at 1st floor A-7, A-8 Kailash Park, Main Najafgarh Road, New Delhi-110015 in a building comprised of Basement + Ground + 3 Upper Floors owned/Occupied by M/s. The Market Place (A unit of Rain tree Grill) was already issued FSC by this department Vide letter no. F6/DFS/MS/2018/EH/WZ/1413 dated 15/06/2018 for Ground & first floor. The Premises was reinspected by the officer concerned of this department on 13/10/2021 in the presence of Sh. Shivam Sehgal (owner) and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have deemed complied with fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Assembly" Group D (1st Floor Only) with effect from _______for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010. Anditions mentions below.

Issued on. 25. J. P. J. 2. J. at New Delhi by.

Dy. Chief Fire Officer Delhi Fire Service

Copy to: -

- 1. The Joint Commissioner of Police, Licensing Unit, 1st floor, Police Station, Defence Colony, New Delhi.
- 2. M/S The Market Palace (A unit of Rain tree Grill) located at A/7 A/8 Ground Floor & 1st Floor, Kailas Park, Main Najafgarh Road, New Delhi-110015.
- 3. Dy. Health Officer, SDMC, West Zone, Vishal Enclave, Rajouri Garden, New Delhi -110027.

Following fire safety directives must be adhered to:-

- 1. F.S.C is valid to run restaurant on 1st floor only.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per building bye laws.
- 8. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 9. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

Name & address of the building : The Market Place (A unit of Rain Tree Grill) at A-7 A-8,

I" floor main Najafgarh Road New Delhi-110015.

2. Type of Occupancy Assembly
3. Type of Case Renewal

4. Details of previous NOC : F6/DFS/MS/2018/WZ/BNQT/1413 dated 15/06/2018(Rain

Tree Grand Banquet restaurant for Ground & First Floor)

5. Fire Safety directives letter No : Nil

6. Date of inspection : 13/10/2021

7. Name of the Inspecting Officers: Mukesh Verma DO(WZ)/FPW & Sarabjeet Singh ADO(MN)

8. Name and designation of officers

5

from the building side : Sh. Vikas (General Manager)

9. Year of Construction : 2004 (As per previous Inspection Report dated 15/06/2018)

10. Applicant's letter No. : Online Application No. 2021071715368 dated 17/07/2021

The said Banquet is running at First Floor. Earlier it was running on Ground & 1st both floor in the name of Rain Tree Grand Banquet restaurant in a Building comprised of Basement +Ground +03 Upper Floors.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	BBL /NBC Requirement/As per prev. Insp. Rep. dtd- 08/06/2018		Provided at site	Remarks MR/NMR
Broom	Access to building				
	Road width	09 mts		vided	MR
	Gate width	N/A I	Directly accessi	ble from the r	oad N/A
	 Width of internal road 	N/A	N	∛A	N/A
2	Number, Width, Type & Arrangem	ent of Exits			
	a. Number of staircases				
	Upper Floors	02	Pro	vided	MR
	Basements	02	02 Pro		MR
	b. Width of staircases				
	Upper Floors	1.5m &1m	2m,1.5n	2m,1.5m &1.25m	
	 Basements 	NA	2.20m	&1.5 m	NA
	c. Protection of exits				
	Fire check door	NR	1	VR.	NR
	 Pressurization 	NR	N	R	NR
	e. No. of continuous staircases to terrace	NR	N	R	NR
	f. Width of Corridor	N/A	N	A	N/A
	g. Door Size	2 m &1 m	2m,1.5n	n&1.25m	MR
	Compartmentation.			and the second s	S 1 M2
	Fire check door	NR		R	NR NR
	Sealing of electrical shafts	NR		R	
	• Fire Rating of shaft door	NR		R	NR
	Water Curtain	NR		R	NR NR
	• Fire Dampers	NR		R	717
	Smoke Management System.				
-	No. of the Control of	30 a/c per hour	N	A	NA
	BasementsUpper floors	12 a/c per hour		n Provided	MR
	Fire Extinguishers	n valent i maninger til mennen til samten hann skriver skriver skriver skriver skriver i men skriver skriver s	anger significant and the second		recognision to the second section of the set
	Total numbers	06	Prov	ided	MR
	• Types	CO., ABC type	Prov	ided	MR
	IS marking	ISI marked	Prov	ided	MR

11' WILLIAM

	First-Aid Hose Reels.				
	Total numbers on each floor	01	Provided	MR	
	 Length of hose reel hose 	30m	Provided	MR	
	Nozzle diameter	05mm	Provided	MR	
7	Automatic fire detection and alarming system.				
/	Smoke Provided			MR	
	Type of detectorsLocation of Main Panel	&Heat			
	Location of Repeater Panel	Required	Provided	MR	
	Alternate source of power	Required	Provided	MR	
	Hooters' Location	Required	Provided	MR	
	Trooters Essential	Required	Provided	MR	
0	MOEFA	Required	Provided	MR NR	
8 9	Public Address System.	NR	NR	TVIC	
10	Automatic Sprinkler System.	NR	Provided	NR	
	Basement	NR	Provided	NR	
	Upper Floor It was have followed lines.	NR	Provided	NR	
	Sprinkler above false ceiling				
11	Internal Hydrants	100mm	Provided	MR	
	Size of riser/down-comer	01	Provided	MR	
	 Number of hydrants per floor 	01	Provided	MR	
	Hose Box U1				
12	Yard Hydrants.	NR	NR	NR	
	Total number of hydrants	NR	NR	NR	
	Hose Box	IVIC			
13	Pumping Arrangements.				
	Ground Level	27/4	N/A	N/A	
	Discharge of main Pump	N/A	N/A	N/A	
	Head of Main pump	N/A N/A	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A	
	> Jockey Pump out put	N/A	N/A	N/A	
	> Jockey pump head	N/A	N/A	N/A	
	> Standby Pump out put	N/A	N/A	N/A	
	> Standby Pump Head	N/A	N/A	N/A	
	Auto Starting/ Manual stopping Pump House Access	N/A	N/A	N/A	
	Terrace level	450 lpm	Provided	MR	
	Discharge of pump	40MH	Provided	MR	
	Head of the pump	Required	Provided	MR	
	Power Supply	Required	Provided	MR	
	Auto Starting of pump				
14	Captive Water Storage for fire fighting	ig.	N/A	N/A	
	 Underground tank capacity 	N/A	N/A	N/A	
	Draw-off connection	N/A	Provided	MR	
	> Fire service inlet	Required		N/A	
	> Access to tank	N/A	N/A	MR	
	 Overhead Tank capacity 	10,000 ltrs	Provided	MR	
	Exit Signage.	Required	Provided	IVIK	

16	Provision of Lifts.						
	Pressurization of Lift Shaft	NR	NR	NR			
	 Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	NR	NR	NR			
		NR	NR	NR NR			
		NR	NR				
		NR	NR	NR			
17	Standby power supply	Required	Provided	MR			
18	Refuge Area.						
	> Total Area	N/A	N/A	N/A			
	> Location	N/A	N/A	N/A			
19	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Batter backup	N/A	N/A	N/A			
	 Building Floor Plans 	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of special Risks, if any:	NI/A	N/A	N/A			

The fire protection systems provided in the building were checked and found functional at the time of inspection. The shortcomings issued by this department vide letter no. F6/DFS/MS/EH/WZ/2021/423 dated 28/09/2021 have been complied.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Name: - Mukesh Verma

Designation: - DO (WZ)/FPW

Signature of the Inspecting Name: - Sarabjeet Singh

Designation: - ADO (MN)

Shock my. why FSC flow www

Apolen, fol is already issued for restaurant for G t Ist floor. NOW, applicant is requested to sun sestourant at f. floor only through

MUA portal.
Submitted for approved please.

//mutes/ahen