1-33

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F.6/DFS/MS/School/2021/NDZ/ 9 | 6

Dated: 01/11/21

FIRE SAFETY CERTIFICATE

Certified that Little Flowers Public Sr. Sec. School at Shivaji Park, Babarpur Road Shahdara, Delhi-110032, comprised of ground plus three upper floors owned/occupied by Little Flowers Public Sr. Sec. School was issued FSC vide letter no. F.6/DFS/MS/School/2018/NDZ/1764 dated 20/04/2018. The school building has complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 04/10/2021 in the presence of Mrs. C. M. Patel (Manager) & Mrs. Neeta Dua, (Principal) of the school and that the school building is fit for occupancy class "B" 'Educational Building' with effect from Delhi Principal under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 & also conditions printed overleaf..

(Dr. S. K. Tomar) Dy. Chief Fire Officer

ofc Dig.

To,

The Principal, Little Flowers Public Sr. Sec. School Shivaji Park, Babarpur Road, Shahdara, Delhi-110032

Copy to:-

- 1. The Commissioner (Any unauthorized construction or unauthorized use of EDMC, Headquarter land/activities, may be dealt at your end)
 419, Udyog Sadan,
 Patparganj Industrial Area,
 New Delhi-110092
- The Dy. Director of Education, North-East, B-Block, Yamuna Vihar, Delhi-110053

CONDITIONS



- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities. This Fire Safety Certificate is valid only for permanent building structure as per plan.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land or activities, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

		J4/13				
	INSPECT	ION REPORT				
1.	Name & address of the building	: Little Flowers Pu	blic Sr Sec S	School		
2.		: Little Flowers Public Sr. Sec. School, Shivaji Park, Shahdara, Delhi-110032				
3.	and a comprised of	: G+3	maura, Delini	110032		
4.	Type of Occupancy Type of Case	: Educational				
5.	- JPC OI Case	: Renewal				
	Details of Previous NOC letter	: F.6/DFS/MS/Sch	ool/2018/ND	Z/764		
6.	Fire Safety direction letter No.	dt-20/04/2018				
	dietry direction letter No.	: Circular No. 262-	- 362 dated 17	//01/2005/		
7.	Date of Inspection	NBC Part-IV: 04/10/2021				
8.	Name of the Inspecting officers					
9.	Name and designation of Officer	: ADO Nagender S	Singh			
	from the building side	· Mro CM Date 1				
		: Mrs. C.M. Patel (Manager) &			
10.	Year of Construction	Mrs. Neeta Dua (: 1980	(Principal)			
	I P-20alt 5 letter II()	: LFPS/16513/202	1 dated 06/00	2021		
	Minimum Standards on Fire	Circular/NBC	Provided	Remarks		
	Prevention and Fire Safety U/R33	Requirement	at Site	MR/NMR		
01	Access to Building		1 310	IVIIOIVIIC		
	Road width	6 m				
	Gate width	4.5 m	6 m	MR		
	Width of internal road	N/A	5 m	MR		
02	Number, Width, Type and Arrangem	ent of Evita	N/A	N/A		
	a. Number of Staircases	Ent of Exits				
	Upper floor					
	Basement	2 nos.	8 nos.	MR		
	b. Width of Staircases	N/A	N/A	N/A		
	Upper floor	1.7. /				
	- PPO MOOI	1.5 m/ add.	1.06m,	MR(Accepted		
		0.75 m	1.18m, 1.05m,	earlier)		
			1.20m,			
			1.10m upto (G+3) &			
			1.12m, 1m,			
	a Danie		1.10m upto			
	Basement	N/A	(G+1)			
-	c. Protection of Exits	14/14	N/A	N/A		
	• Fire check door					
	Pressurization	N/A	N/A	N/A		
	d. No. of Continuous Staircases to	N/A	N/A	N/A		
	Terrace Terrace	2 nos.	2 nos.	MR		
	e. Width of Corridor	1.5 m				
		1.510	1 m	MR(accepted		
0.2	f. Door Size	1 m	1 m	earlier)		
03	Compartmentation.	7 111	1 m	MR		
11. Sr. No. 01 02 03 04	Fire check door	NY/A				
	Sealing of electrical shafts	N/A N/A	N/A	N/A		
	Fire rating of shaft door	N/A N/A	N/A	N/A		
	Water curtain	N/A	N/A	N/A		
	Fire dampers	N/A	N/A	N/A		
04	Smoke Management System.	11/11	N/A	N/A		
	Basement					
	Upper floor	N/A	N/A	N/A		
05	Fire Extinguishers	N/A	N/A	N/A		
	The Extinguishers					
	 Total numbers 	16 nos.	20 nos.	MD		
	• Types	ABC/CO ₂	ABC/ CO ₂	MR MR		
	 IS marking 	ISI marked	ISI Marked	MR		
			1	1111		

N/14

06	First-Aid-Hose Reels.						
	Total numbers on each floor	02 nos.	02 nos.	MR			
	 Length of hose reel hose 	30 m	30 m	MR			
	Nozzle diameter	5 mm	5 mm	MR			
07	Automatic Fire Detection and Alarming System.						
	Type of detectors	N/A	N/A	N/A			
	Location of main panel	N/A	N/A	N/A			
	 Location of repeater panel 	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooter	N/A	N/A	N/A			
80	MOEFA	N/A	N/A	N/A			
09	Public Address System.	N/A	N/A	N/A			
10	Automatic Sprinkler System.						
	Basement	N/A	N/A	N/A			
	Upper Floor	N/A	N/A	N/A			
	Sprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants						
	Size of riser/down-comer	N/A	Provided	MR			
	Number of hydrants per floor	N/A	01 no.	MR			
	Hose box	N/A	Provided	MR			
12	Yard Hydrants.						
	Total number of hydrants	N/A	N/A	N/A			
	Hose box	N/A	N/A	N/A			
13	Pumping Arrangements.						
	> Ground Level						
	Discharge of main pump	N/A	N/A	N/A			
	Head of main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey pump out put	N/A	N/A	N/A			
	 Jockey pump head 	N/A	N/A	N/A			
	Standby pump out put	N/A	N/A	N/A			
	 Standby pump head 	N/A	N/A	N/A			
	Auto starting /manual stopping	N/A	N/A	N/A			
	 Pump house access 	N/A	N/A	N/A			
	> Terrace Level						
	Discharge of pump	450 LPM	450 LPM X 2	MR			
	Head of the pump	40 m	40 m	MR			
	Power supply	Required	Provided	MR			
	Auto starting of pump	Required	Provided	MR			
14	Captive Water Storage for Fire Fighting.						
	Underground tank capacity	N/A	N/A	N/A			
	Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	 Access to tank 	N/A	N/A	N/A			
	 Overhead tank capacity 	10,000 Ltrs.	10,000 Ltrs.	MR			
15	Exit Signage.	Required	Provided	MR			



16	Provision of Lifts.					
	Pressurization of lift shaft	N/A	N/A	N/A		
	 Pressurization of lift lobby 	N/A	N/A	N/A		
	 Communication in lift car 	N/A	N/A	N/A		
	 Firemen's grounding switch 	N/A	N/A	N/A		
	 Lift signage 	N/A	N/A	N/A		
17	Standby Power Supply	N/A	Provided	MR		
18	Refuge Area.					
	Total area	N/A	N/A	N/A		
	Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector system panel	N/A	N/A	N/A		
	Flow switch panel	N/A	N/A	N/A		
	PA system panel	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	Building floor plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of Special Risks, if Any:	N/A	N/A	N/A		

Kindly peruse the affidavit submitted by the owner declaring that no addition/alteration has been made to the existing building, the portion which includes stilt ground plus three upper floor is part of building and was in existence during previous inspections also (Affidavit placed at C/28).

Keeping in view of the compliance of the minimum standards of fire prevention and fire safety measures required under the rules, if agreed, it is recommended to renew Fire Safety Certificate under rule 37 of Delhi Fire Service Rules, 2010.

(Nagender Singh) ADO (Shandara)

DY. CFO (NDZ)

251101

ABO(Shan)

FT letter is placed for signature please

DycFolMor)

X 20mm/

- ()29 (1 h

MC