

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F6 /DFS/MS/School/2021/ 🕺 🖇 7

Dated:27/10/2021

Director

Ph:-011-23414000

-19

FIRE SAFETY CERTIFICATE

Certified that the Mata Ramrakhi Sanatan Dharm Saraswati Bal Mandir located at C-67, Mahendru Enclave, Delhi- 110033 comprised of ground and two upper floors only owned/ occupied by the Mata Ramrakhi Sanatan Dharm Saraswati Bal Mandir have complied with the fire prevention and safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 30.09.2021 in the presence of Mrs. Neelam Patial (Principal) and that the building/premises is fit for occupancy Class "Group B Educational" with effect from $\dots 2 \dots 7 \dots f_{1 \to 1} \dots \dots$ for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ... 2.7. 1.0. 1.2.1...... at New Delhi

Copy to: -

- 1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi 110054.
- 2. The Principal, Mata Ramrakhi Sanatan Dharm Saraswati Bal Mandir at C-67, Mahendru Enclave, Delhi-110033.

Conditions for the validity of Fire Safety Certificate:

- 1 All the means of escape/entry/exit shall be kept free from any obstruction.
 - 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
 - 3. All the staff members must know the correct method of operation of firefighting system.
 - 4 The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.
 - 5 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
 - 6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in **Form 'J'** [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

			NIG
	~		INSPECTION REPORT
1	. Nam	e & address of the building	:Mata Ramrakhi Sanatan Dharm Saraswati Bal Mandir, C-67, Mahendru Enclave, Delhi-110033.
2	. Туре	of Occupancy	:Educational
3	. Туре	of Case	:New Case (Ground + 02 upper floors)
4	. Detai	ls of previous NOC	: Nil
5.	. Fire	Safety directives letter No	: Director of Education Circular dated 01.03.2011
6.	. Date	of inspection	: 30.09.2021
7.	. Nam	e of the Inspecting Officers	: ADO (RN)
8.	. Nam	and designation of officers	
	from	the building side	: Mrs. Neelam Patial (Principal)
9.	Year of	Construction	: 1990
10.	. Applic	ant's letter No.	: Online E-mail ID dated 22.09.2021

n wald

2	Access to building Road width Gate width Width of internal road Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors Basements b. Width of staircases Upper Floors	06m 2.5m NA 02 NA 1.50m	6m 2.90m &1.50m NA 02 NA 1.15m & 85cm	MR MR NA MR NA			
2	 Gate width Width of internal road Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors Basements b. Width of staircases 	2.5m NA 02 NA	2.90m &1.50m NA 02 NA	MR			
2	Width of internal road Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors Basements b. Width of staircases	02 NA		MR			
2	Number, Width, Type & Arrangement of Exits a. Number of staircases • Upper Floors' • Basements b. Width of staircases	02 NA	02 NA	MR			
2	 a. Number of staircases Upper Floors Basements b. Width of staircases 	NA	NA				
	Upper FloorsBasementsb. Width of staircases	NA	NA				
	• Basements b. Width of staircases			NA			
	b. Width of staircases						
		1.50m	1 15m & 85cm				
	Upper Floors		1.1511 & 05011	MR(old building)			
		NA	NA	NA			
	 Basements 						
	c. Protection of exits	NA	NA	NA			
	 Fire check door 	NA	NA	NA			
	 Pressurization 	NA	NA	NA			
	d. No. of continuous staircases to terrace	NA	NA	NA			
	e. Width of Corridor f. Door Size	l m	1.15m	MR			
	Compartmentation.						
	Fire check door	NA	NA	NA			
	Sealing of electrical shafts	NA	NA	NA			
	Fire Rating of shaft door	NA	NA	NA			
	• Water Curtain	NA	NA	NA			
	• Fire Dampers	NA	NA	NA			
	Smoke Management System.						
	Basements	12 a/c per hour	NA	NA			
	• Upper floors	12 a/c per hour	Natural Ventilated	MR			
	Fire Extinguishers						
	Total numbers	10nos ABC	11nos ABC-11	MR			

Ø

417

				0-			
	ISI marking	1SI Marked	Yes	МК			
	First-Aid Hose Reels.						
	Total numbers on each floor	01	Provided	MR			
	Length of hose reel hose	30m	Provided	MR			
	Nozzle diameter	£	Provided	MR			
	Automatic fire detection and alarming system.	5mm	Tovided				
	NA						
	Type of detectors	NA	NA	NA			
	Location of Main Panel	NA	NA	NA			
	Location of Repeater Panel	NA	NA	NA NA			
	Alternate source of power	NA					
	Hooters' Location		Provided	MR			
	MOEFA	Required	NA	NA			
	Public Address System.	NA	NA	,			
	Automatic Sprinkler System.	NA	NA	NA			
	• Basement	NA	NA	NA			
	Upper Floor		NA	NA			
	• Sprinkler above false ceiling	NA	INA				
	Internal Hydrants		NA	NA			
	• Size of riser/down-comer	NA	NA	NA			
	 Number of hydrants per floor 	NA		NA			
	• Hose Box	NA	NA				
	Yard Hydrants.		NA	NA			
	Total number of hydrants	NA					
	• Hose Box	NA	NA	NA			
	Pumping Arrangements.						
3	Ground Level						
	 Discharge of main Pump 	N/A	N/A	N/A			
	Head of Main pump	N/A	N/A	N/A			
	> Number of main pumps		N/A	N/A			
	Jockey Pump out put	N/A					
	 Jockey pump head 	N/A	N/A	N/A			
	 Standby Pump out put 	N/A	N/A	N/A			
	 Standby Pump Head 	N/A	N/A	N/A			
	the Greating/ Manual stopping	N/A	N/A	N/A			
	 Auto Starting/ Manual stopping Pump House Access 	N/A	N/A	N-A			
	Terrace level	450 lpm	Provided	MR			
	 Discharge of pump 	450 ipin 40m	Provided	MR			
	 Head of the pump 		Provided	MR			
	 Power Supply 	Required		MR			
	 Auto Starting of pump 	Required	Provided	МК			
14	Captive Water Storage for fire fighting.						
		NA	NA	NA			
	 Underground tank capacity 		NA	NA			
	 Draw-off connection 	NA	NA	NA			
	 Fire service inlet 	NA		NA			
	 Access to tank 	NA	NΛ	MR			
			10.000ltr				

q

5	Exit Signage.	Required	Provided	MR			
16	Provision of Lifts						
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car	N/A	N/A	N/A			
	Fireman's Grounding Switch	N/A	N/A	N/A			
	Lift Signage	N/A	N/A	N/A			
17	Standby power supply	N/A	N/A	N/A			
18	Refuge Area.						
	Total Area	N/A	N/A	N/A			
	 Location 	N/A	N/A	N/A			
19	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Batter backup	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A			

N/8

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. 379 dated 30.07.2021

communicated by this department vide fetter of even no. 579 dates even and on fire prevention and fire safety Keeping in view the satisfactory compliance of the minimum standard on fire prevention and fire safety requirements as stipulated under the circular issued by Director of Education dated 01.03.2011, it is recommended to grant Fire Safety Certificate

[0[202]

Signature of the Inspecting Officer Name :-C.L. Meena Designation:- ADO/RN

05/10

W2)

94

plsspr mixtre poken

P.T.O.