

C/38

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001**

No.F6/DFS/MS/Indl/NDZ/2021/

537

Dated : 29 .10.2021

**FIRE SAFETY CERTIFICATE**

Certified that the M/s Mother Dairy Building located at Patparganj, Delhi-110092 comprises of **Ground + 02 Upper floors** owned occupied by M/s Mother Dairy Fruits & Vegetable Pvt. Ltd., was granted FSC vide letter No. **F6/DFS/MS/Indl/2019/NDZ/113 dated 16/01/2019**. The premises was inspected by the officers concerned of this department on **22/10/2021** in the presence of Mr. Rahul Jain(Safety Officer) & Mr. Bhardwaj(CSO) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class G "**Industrial Building**" **Ground + 02 Upper floors** with effect from ~~22/10/2021~~ 29/10/2021 for period of **three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued on 29/10/2021 at New Delhi by.

  
(Arul Garg)  
Director  
Delhi Fire Service

Copy to:-

The Manager,  
Mother Dairy Fruits & Vegetable Pvt. Ltd.,  
Patparganj, Delhi-110092.

**Condition for the validity of fire safety certificate**

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT

1. Name & address of the building : M/s Mother Dairy Fruits & Vegetable Pvt. Ltd., Patparganj, Delhi-110092.
2. Type of occupancy : Industrial Building  
(Ground + 02 Upper floors)
3. Type of case:- : Renewal
4. Details of previous FSC : F6/DFS/MS/Indl/2019/NDZ/113 dated 16/01/2019
5. Fire safety directives No. : NA
6. Date of inspection:- : 22/10/2021
7. Name of the inspecting officer : Sh. Manoj Kumar Sharma (ADO/LN)
8. Name & designation of officer From the building side : Mr. Rahul Jain(Safety Officer) & Mr. Bhardwaj(CSO)
9. Year of construction : 1991
10. Applicant's letter No : email dated 30/09/2021

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement Existing dt.1.515	Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	06 mtr.	12 mtr.	MR
	2) Gate width	4.5 mtr.	6 mtr.	MR
	3) Width of internal road	6 mtr.	6 mtr.	MR
2.	Number, Width Type & Arrangement of Exits			
	A. Number of staircases			
	1. Upper floors	02 No.	02 No.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	1.20 M	1.20 M each	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	01 nos.	01 nos.	MR
	E. Width of corridor	1.5 mtr	1.5 mtr	MR
	F. Door size	1.0 mtr	1.0 mtr	MR
3.	Compartmentation			
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	Required	Sealed	MR
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
	1) Basements	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
5.	Fire Extinguishers			
	1) Total numbers	300 Nos.	380 nos.	MR
	2) Types	ABC ,CO2 & water type	ABC ,CO2 & water type	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel			

	1) Total number of each floor	02 Nos.	02 Nos.	MR
	2) Length of hose reel hose	30 m	30 m	MR
	3) Nozzle diameter	5 mm	5 mm	MR
7.	Automatic Fire Detection & Alarming System			
	1) Type of detectors	Smoke	Provided	MR
	2) Location of main panel	Security Room	Provided	MR
	3) Location of repeater panel	Security Room	Reception	MR
	4) Alternate source of power	Battery & DG set	Provided	MR
	5) Hooter's Location	Staircase	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	1) Size of riser/down-comer	100/200 MM	100/200 MM	MR
	2) Number of hydrants per floor	02 nos.	02 nos.	MR
	3) Hose box each floor	02 nos.	02 nos.	MR
12.	Yard Hydrants			
	1) Total number of hydrants	20 nos.	Provided	02 nos.
	2) Hose box	20 nos.	Provided	N/A
13.	Pumping Arrangement			
	1) Ground level			
	a) Discharge of main pump	2850 LPM	2850 LPM	MR
	b) Head of main pump	70 m	70 m	MR
	c) Number of main pump	01 nos.	01 nos.	MR
	d) Jockey pump output	180 LPM	180 LPM	MR
	e) Jockey pump head	70 m	70 m	MR
	f) Stand by pump output	2850 LPM	2850 LPM	MR
	g) Stand by pump head	70 m	70 m	MR
	h) Auto starting/Manual stopping	Required	Provided	MR
	2) Terrace level			
	a) Discharge of pump	900 LPM	900 LPM	MR
	b) Head of pump	40 m	40 m	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
14.	Captive Water Storage for Fire Fighting			
	1) Under ground tank capacity	2,00,000 ltr.	3,00,000 ltr.	MR
	a) Draw-off connection	Required	Provided	MR
	b) Fire service inlet	Required	Provided	MR
	c) Access to tank	Accessible	Accessible	MR

MWD

	d) Over head tank capacity	50,000 Ltrs.	50,000 Ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	Required	Provided	MR
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	Required	Provided	MR
	d) Battery backup	Required	Provided	MR
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:	Required	Provided	MR

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/Indl/2019/NDZ/113 dated 16/01/2019 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

*M.K. Sharma*  
 Name :- M.K. Sharma  
 Designation :- ADO (LN)

Dy.CFO/NDZ

*K. Sharma*  
 25/10/21

*CFO (H.O)*

*Kamp*  
*27/10/21*

*Angela*

*Men*

(P.T.O.)

