GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F6/DFS/MS/2021/]6

FIRE SAFETY CERTIFICATE

ITI Dheerpur, Delhi-110033 Certified that the World Class Skill Centre located at comprised of ground and two upper floors only owned/ occupied by the World Class Skill Centre have complied with the fire prevention and safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 12.10.2021 in the presence of Sh. S.K. Sharma and that the building/premises is fit for occupancy Class "Group B Educational" with effect from ... O/. /. 1.1/. 21..... for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on at New Delhi

Director Ph:-011-23414000 ele (b)

Dated [] /]]/2021

144

Copy to: -

- 1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi 110054.
- 2. Delhi Tourism & Transportation Development Corporation LTD., Lajpat Nagar Ring Road, Sri Niwaspuri Delhi-110065.
- 3. The Principal, World Class Skill Centre, ITI Dheerpur, Delhi-110033.

Conditions for the validity of Fire Safety Certificate:

- 1 All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- The owner / occupier shall submit a declaration every year in Form "K" provided in the first 4 available is on 2010. The form Rules Service Fire Delhi schedule of http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-5 2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

h	4		

		INSPECTION REPORT
1. 2. 3.	Name & address of the building Type of Occupancy Type of Case	: World Class Skill Centre, ITI Dheerpur, Delhi-110033. : Educational : New Case (Ground+02 upper floors only)
4.	Details of previous NOC	: New Case (Ground+02 upper floors only) : Nil
5.	Fire Safety directives letter No	: NBC Part-4
6.	Date of inspection	: 12.10.2021
7.	Name of the Inspecting Officers	= ADO (RN)
8.	Name and designation of officer	'S

from the building side : S.K. Sharma 9. Year of Construction :-

 10. Applicant's letter No.
 :

 10. Applicant's letter No.
 : Letter no.23(05)DTTDC/EE(E)/Engg./2021-22/207 dated 15.09.2021

5

Fire Extinguishers

_		dards on fire prevention and e safety U/R 33	NBC Part-4	Provided at site	Remarks		
1	Access to building	Access to building MR/NMR					
	 Road wid 	Road width					
	Gate widt		06m	06	MR		
		internal road	05m	05m	MR		
2			NA	NA	NA		
2	Number, Width,	Гуре & Arrangement of Exits	3		NA		
	a. Number of stairc	cases					
	• Upper Flo	oors	02	02	MR		
	Basements		NA	NA	NA		
	b. Width of staircas	ses					
	Upper Flo	ors	1.50m	1.60m each	MR		
	Basements	S	NA	NA	NA		
	c. Protection of exit	ts			INA		
	Fire check	door	NA	NIA			
	Pressurizat	tion	NA	NA NA	NA		
	d. No. of continuou	is staircases to terrace	NA	NA	NA		
	e. Width of Corrido				NA		
	f. Door Size		NA	NA	NA		
	Compartmentation		1.20m	1.20m	MR		
,	compartmentation.						
	• Fire check		NA	NA	NA		
		electrical shafts	NA	NA	NA		
	Fire Rating	of shaft door	NA	NA	NA		
	Water Curta	ain	NA	NA			
	• Fire Dampe	ers		NA	NA		
			NA	NA	NA		
	Smoke Managemen	t System.					
	Basements		12 a/c per hour				
		-	-	No basement	NA		
	• Upper floors	S	12 a/c per hour	Natural Ventilation	MR		

Jp.







good w

afety Fire St





				100		
	Total numbers	12nos	14nos	MR		
	• Types	ABC/Co2	ABC-14	MR		
	ISI marking	Yes	Yes	MR		
6	First-Aid Hose Reels.					
	Total numbers on each floor	02	02 each floor	MR		
	• Length of hose reel hose	30m	30m	MR		
	Nozzle diameter			MR		
7	Automatic fire detection and alarming system	5mm	5mm	IVIIX		
	Type of detectors	NA	Provided	NA		
	Location of Main Panel	NA	NA	NA		
	Location of Repeater Panel	NA	NA	NA		
	Alternate source of power	NA	NA	NA		
	Hooters' Location					
		NA	NA	NA		
3	MOEFA Public Address System	Required	Provided	MR		
0	Public Address System. Automatic Sprinkler System.	NA	NA	NA		
•						
	• Basement	NA	NA	NA		
	Upper Floor	NA	NA	NA		
	Sprinkler above false ceiling	NA	NA	NA		
1	Internal Hydrants					
	• Size of riser/down-comer	NA	NA	NA		
	• Number of hydrants per floor	NA	NA	NA		
	Hose Box	NA	NA	NA		
2	Yard Hydrants.					
	• Total number of hydrants	NA	NA	NA		
	• Hose Box	NA	NA	NA		
	Pumping Arrangements.					
t	Ground Level					
	Discharge of main Pump	N/A	N/A			
	Head of Main pump			N/A		
	> Number of main pumps	N/A	N/A	N/A		
	Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A		
	Auto Starting/ Manual stopping	N/A				
	Pump House Access		N/A	N/A		
	Tamaa las l	N/A	N/A	N/A		
	Terrace level					
	Discharge of pump	450 lpm	450 lpm x2	MR		
	Head of the pump	40m	40m	MR		
	Power Supply	NA	NA	NA		
	Auto Starting of pump	Required	Provided			
C	aptive Water Storage for fire fighting.			MR		
	Underground tank capacity	NA	NA	NA		
	> Draw-off connection	NA	NA	NA		
				1 1 1 1		

MS

÷

T T

	Fire service inlet	NA	NA	NA		
	 Access to tank 	NA	NA	NA		
	 Overhead Tank capacity 	10.000 ltr	20,000ltr	MR		
5	Exit Signage.	Required	Provided	MR		
6	Provision of Lifts.					
	Pressurization of Lift Shaft	N/A	NA	NA		
	Pressurization of Lift lobby	N/A	NA	N/A		
	Communication In lift Car	NA	N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
	 Lift Signage 	NA	N/A	N/A		
17	Standby power supply	N/A	N/A	N/A		
18	Refuge Area.					
	Total Area	N A	N/A	N/A		
	> Location	N A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	 Flow Switch Panel 	N/A	N/A	N/A		
	 PA System Panel Batter backup 	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
	Bunding Floor Plans	N/A	N/A	NA		
0	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A		

NIG

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standard on fire prevention and fire safety requirements as stipulated under the circular issued by NBC Part-IV, it is recommended to grant Fire Safety Certificate

N Leave DE CFO (WZ) 10/002)

Signature of the Inspecting Officer

Name :-C.L. Meena Designation:- ADO/RN

f [] /

P.T. 0