

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110 001.

No.F.6/DFS/MS/School/2021/SZ / 927

Dated: 09/11/21

FIRE SAFETY CERTIFICATE

Certified that the **Govt. Co-Ed. Secondary School**, Vipin Garden, and New Delhi-110059 comprised of ground plus one upper floor only, owned/occupied by Govt. Co-Ed. Secondary School. The building have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and verified by the officer concerned of this department on 25/10/2021 in the presence of Sh. Ramesh Chand (Principal) and found that the building is fit for occupancy 'Group B "Educational Building"' with effect from 09/11/21 for a period of **three** years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on.....09/11/21.....at New Delhi by



(Atul Garg)
Director

Delhi Fire Service



Copy to:-

1. The Principal,
Govt. Co-Ed. Secondary School,
Vipin Garden, New Delhi-110059.
2. Director of Education,
Govt. of NCT of Delhi, Old secretariat
New Delhi-110054.

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
6. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

N/S

INSPECTION REPORT

- 1. Name & address of the building : Govt. Co-Ed. Secondary School, Vipin Garden, New Delhi-110059
- 2. Building is comprised of : Ground plus one upper floor only.
- 3. Type of Occupancy : Educational
- 4. Type of Case : New
- 5. Details of Previous NOC : N/A
- 6. Fire Safety directives letter No : Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011
- 7. Date of inspection : 25/10/2021
- 8. Name of Inspecting Officer : A.D.O. R.K.Yadav
- 9. Name and designation of officers
From the building side : Sh. Ramesh Chand (Principal)
- 10. Year of Construction : 2015
- 11. Applicant's letter No. : Nil dated 27.9.2021

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NMR
1.	Access to building			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	Accessible 06 m 4.5 m N/A	08 m 4.8 m (02 no.'s) N/A	M/R MR N/A
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	<ul style="list-style-type: none"> • Upper Floors • Basements 	03 No.'s N/A	03 No.'s N/A	M/R N/A
	b. Width of staircases			
	<ul style="list-style-type: none"> • Upper Floor • Basements 	1.50 & .75 m N/A	2x1.50 m & 1.0 m N/A	M/R N/A
	c. Protection of exits			
	<ul style="list-style-type: none"> • Fire check door • Pressurization 	N/A N/A	N/A N/A	N/A N/A
	d. No. of continuous staircases to terrace	N/A	N/A	N/A
	e. Width of Corridor	1.50 m	1.75 m	M/R
	f. Door Size	1.0 m	1.17 m (Double door)	M/R
3.	Compartmentation			
	<ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Water Curtain • Fire Dampers 	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A
4.	Smoke Management System			
	<ul style="list-style-type: none"> • Basements • Upper floors 	N/A Required	N/A Natural ventilation provided	N/A M/R
5.	Fire Extinguishers			
	<ul style="list-style-type: none"> • Total numbers • Types • IS marking 	05 no's ABC/CO ₂ type ISI marked	Provided Provided Provided	M/R M/R M/R

Both wings are interconnected and third staircase is common.

N7

		No Lift		
16.	Provision of Lifts. <ul style="list-style-type: none"> • Pressurization of Lift Shaft • Pressurization of Lift lobby • Communication In lift Car • Fireman's Grounding Switch • Lift Signage 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
17.	Standby power supply			
18.	Refuge Area. <ul style="list-style-type: none"> > Total Area > Location 	N/A	N/A	N/A
		N/A	N/A	N/A
19.	Fire Control Room <ul style="list-style-type: none"> • Detector System Panel • Flow Switch Panel • PA System Panel • Battery backup • Building Floor Plans 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection. The shortcomings was issued vide letter no.F.6/DFS/MS/School/2016/SZ/2611 dated 04/11/16 has been complied.

Keeping in view of the above compliance of the minimum standards of fire prevention and fire safety measures in accordance with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 it is recommended to grant Fire Safety Certificate.

R.K. Yadav
 Signature of Inspecting Officer 26/10/2021

Name:- R.K. Yadav
 Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

A. Gupta
 26/10/2021

Sh
 28/10

Deep

Deep
 29/10/2021

Deep

